

WTC Visual Survey Form

Premise Address: 254 Front St		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name: RAI Trust		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name: Mr. Jerome		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	☐ Yes ☐ No	Debris	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"
Facade Description: Cleaned					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ 1/2 to 1" ☐ > 1"					
Description:					
Setbacks N/A ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Comments					

Date: 4/26/2002 **Inspection Team: Name:** AL **Agency:** _____
Name: _____ **Agency:** _____

ENTERED



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

April 26, 2002

Building Owner Name: LIT Trust
Address: 254 Front St
NYC
Subject: Mr. Jerome

Dear Sir/ Madam:


In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.


The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,


**R. Radhakrishnan, P.E.
Director
Asbestos Control Program**



Page: 1 Document Name: Extra

04/29/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPIQ31
 MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
 254..... FRONT STREET..... 1 MANHATTAN 10038 BIN# 1001377
 DCP GEOGRAPHICAL INFORMATION:
 FRONT STREET 254 - 258 HEALTH AREA : 77 TAX BLK: 107..
 DOVER STREET 22 - 22 CENSUS TRACT: 11001 TAX LOT: 28...
 COMMUNITY BD: 101 CONDO :
 MULTI STRUCT: 1 CUI NO :
 DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
 OWNER NAME : JOSELYN LUCHNICK TRUST JOSELYN LUCHNICK TRUS
 CORP. NAME : %ALAN LUCHNICK LPC LANDMARK STATUS: LANDMARK
 ADDRESS : 236 GOLDEN BEACH DR DOB LOCAL LAW STATUS: NO
 GOLDEN BEACH FL 33160-2242
 DOF BUILDING INFORMATION:
 BLDG SIZE: 0044.00 X 0071.00 TRANS LAND VALUE: 600,000
 LOT SIZE: 0069.58 X 0071.75 TAX EXEMPT FLAG : NO
 BLDG CLASS : K1 STORE BUILDING TAX EXEMPT CLASS:
 STORIES : 1 CITY OWNERSHIP : NO
 FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
 OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

 PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 4/29/ 2 Time: 09:46:22 AM

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Inspection Detail

Report Date 04/24/2002 12:52 PM

Submitted By

Page 2

Linked Requests

Service #	Problem	Problem Date	Address
Location			

No Linked Requests for this Service Request Inspection

NYC DEP

Method

Source

Critical Service

Log Log Type Entered By	Description Comments	Log Started	Log Ended
-------------------------------	-------------------------	-------------	-----------

There are no log entries for this service number

End of Report