

WTC Visual Survey Form

CLEAN

Premise Address: 40 FULTON STREET		
Block: 75 Lot: 21	Residential ☐ Commercial ☒ Mix Use ☐ Other ☐	Name of Building:
# of Stories: 29	AKA's:	
Building Owner/Management: 40 FULTON LLC Name: MPC MANAGEMENT LLC		Telephone Number: (212) 269-8171 FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☒ Yes ☐ No Locations: ROOF SURFACES AND FACADE SURFACES		
ACM Clean Up ☐ Yes ☐ No Locations:		
Air Monitoring ☐ Yes ☐ No Locations:		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:				
North	☐ N/A	Inspected ☒ Yes ☐ No	Debris ☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
Facade Description:				
Roof				
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"				
Description: NO WTC DEBRIS OBSERVED				
Setbacks N/A ☐				
Floor: 26	Debris: ☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Comments				

Date: 07 / 16 /2002

Inspection Team: Name: DA / A020

Agency: NYC DEP

Name: _____ Agency: _____

WTC Visual Survey Form

CLEAN

Premise Address: 40 FULTON STREET		
Block: 75 Lot: 21	Residential ☐ Commercial ☒ Mix Use ☐ Other ☐	Name of Building:
# of Stories: 29	AKA's:	
Building Owner/Management: 40 FULTON LLC		Telephone Number: (212) 269-8171
Name: MRC MANAGEMENT LLC		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☒ Yes ☐ No		Locations: ROOF SURFACES AND FACADE SURFACES
ACM Clean Up ☐ Yes ☐ No		Locations:
Air Monitoring ☐ Yes ☐ No		Locations:
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	☒ Yes ☐ No	Debris	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
Facade Description:					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: NO WTC DEBRIS OBSERVED					
Setbacks N/A ☐					
Floor: 26		Debris: ☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Comments					

Date: 07 / 16 / 2002

Inspection Team: Name: DA / A020

Agency: NYC DEP

Name: _____ Agency: _____