

WTC Visual Survey Form

1075618

Premise Address:

40 FULTON STREET

Block: 75
Lot: 21Residential ☐ Commercial ☒
Mix Use ☐ Other ☐

Name of Building:

of Stories: 29

AKA's:

Building Owner/Management:

Telephone Number: (212) 269-8171

Name:

FAX: ()

Address:

On Site Contact: ASST. BLDG. MGR

Name: ERIC BASSIN

Telephone Number: ()

Building Owner Management Activities

Interior Survey Performed ☒ Yes ☐ NoExterior Survey Performed ☐ Yes ☐ NoGeneral Clean Up ☒ Yes ☐ No Locations: VARIOUSACM Clean Up ☐ Yes ☒ No Locations:Air Monitoring ☒ Yes ☐ No Locations: INTERIOR MONTHLY BKG.Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

North ☒ N/A

Inspected

☒ Yes ☐ NoSouth ☐ N/A☒ Yes ☐ NoEast ☐ N/A☒ Yes ☐ NoWest ☐ N/A☒ Yes ☐ No

Debris

☒ No Visible/Fine Layer☐ 1/2 to 1"☐ > 1"☒ No Visible/Fine Layer☐ 1/2 to 1"☐ > 1"☒ No Visible/Fine Layer☐ 1/2 to 1"☐ > 1"☒ No Visible/Fine Layer☐ 1/2 to 1"☐ > 1"

Facade Description:

FACADE CLEANED

Roof

31st FL.Debris: ☒ No Visible /Fine Layer☐ 1/2 to 1"☐ > 1"

Description:

Setbacks

N/A ☐30th on water street side only.Floor: 30thDebris: ☒ No Visible/Fine Layer☐ 1/2 to 1"☐ > 1"

Floor: _____

Debris: ☐ No Visible/Fine Layer☐ 1/2 to 1"☐ > 1"

Floor: _____

Debris: ☐ No Visible/Fine Layer☐ 1/2 to 1"☐ > 1"

Floor: _____

Debris: ☐ No Visible/Fine Layer☐ 1/2 to 1"☐ > 1"

Floor: _____

Debris: ☐ No Visible/Fine Layer☐ 1/2 to 1"☐ > 1"

Comments

Kadi, CUSTODIAL ASST. ESCORTED ME TO ROOF

Date: 2/15/2002

Inspection Team: Name: R. RAMMOHAN

Agency: DEP.

Name:

Agency: