

WTC Visual Survey Form

1001172

Premise Address: 50 FULTON STREET		
Block: 75	Residential ☐ Commercial ☐	Name of Building: NEALE HOUSE
Lot: 7501	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management: Trinity Church		Telephone Number: (212) 602-0812
Name: Father Hoke		FAX: ()
Address:		
On Site Contact:		
Name: Sister Marjorie Wysocky		Telephone Number: (212) 619-2672
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☒ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:**Facade:**

		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☒ No Visible Fine dust / Fine Layer	☐ ½ to 1"	☐ > 1"
South	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: _____

Roof

Debris: ☒ ~~No Visible~~ / Fine Layer ☐ ½ to 1" ☐ > 1"

Description: _____

Setbacks N/A ☒

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 2 / 16 / 2002
 Inspection Team: Name: R. RAMMOHAN Agency: DEP
 Name: _____ Agency: _____



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

February 16, 2002

Building Owner Name: Trinity Church / ATTN. Father Hoke
Address: 74 Trinity Place
NY NY 10006
Subject: 50 FULTON STREET

Dear Sir/Madam:

In September 2001, the New York City Department of Environmental Protection (NYCDEP) and the Department of Health (NYCDOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the assessment of building contamination for possible hazardous components, including asbestos.

Today, a visual survey of your building's exterior was conducted as a follow up to DEP's October survey of buildings around the World Trade Center site. At the above referenced site, visible dust accumulations were observed at:

- ☒ building facade(s)
- ☐ setback(s)
- ☒ roof
- ☐ other, _____

Please be advised building owners are responsible for the cleaning of building exteriors, grounds and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

Please provide information regarding your actions to address the dust accumulations by February 27, 2002. Copies of the environmental hazard assessments including bulk sample results, air monitoring results and/or a summary of clean-up activities at the above-referenced site may be faxed to (718) 595-3744 or sent to the NYCDEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

If you have any questions, you may reach the NYCDEP at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. NYCDEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan
for R. Radhakrishnan, P.E.
Director
Asbestos Control Program





**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

February 16, 2002

Building Owner Name: Trinity Church / Father Hoke

Address: 74 Trinity place
NY, NY 10006

Subject: 50 FULTON STREET

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan
for R. Radhakrishnan, P.E.
Director
Asbestos Control Program



