

Asbestos Inspection Report

Premise No. <u>64 FULTON STREET</u>					Inspection Date: <u>10/21/02</u>	
Floor	Zip <u>10038</u>	Borough <u>1</u>	Block <u>76</u>	Lot <u>1</u>	Squad # <u>N/A</u>	Badge # <u>A019</u>
Inspector <u>P. THEODORELLIS</u>		Building Type <u>A</u>		Basis of Inspection <u>WTC EPA Referral</u>		Photos Taken
Contractor's Name <u>N/A</u>				Sample Number <u>N/A</u>		
Address City				Sample Number <u>N/A</u>		
State	Zip	Phone		Sample Number <u>N/A</u>		
Laboratory Name <u>N/A</u>				Owner's Name <u>COUNTRY CLUB RECOVERY</u>		
Address		City		Address		City
				<u>64 Fulton St.</u>		<u>New York</u>
State	Zip	Phone		State	Zip	Phone
				<u>NEW YORK</u>	<u>10038</u>	
Contact Person				Time of Inspection from: <u>3:15pm - 3:30pm</u>		
<u>At approximately 3:00pm, I contacted telephone number of concerned citizen listed in the e-mail from the USEPA. First attempt was informed wrong number. Tried again. This time confirmed that number called was number in e-mail. Number is not correct. Then proceeded to the site.</u> <u>At the site, I found that there was no PII listed and no PII apartment listed on the building directory. There was however a listing for a PII AT # PII I attempted to gain access. I tried the buzzer for ~10 minutes at intervals but did not receive a response</u>						

Radhakrishnan, Krish

From: Basso.Ray@epamail.epa.gov
Sent: Friday, October 18, 2002 1:41 PM
To: krishr@dep.nyc.gov
Cc: Butler.Elizabeth@epamail.epa.gov; Perera.Dilshad@epamail.epa.gov
Subject: ACM referrals

Krish, could you please provide for an inspection and appropriate follow up actions at the two addresses described below. Thanks. Please let me know when your actions are scheduled.

Elizabeth Butler

10/18/2002 09:42
AM

To: Ray Basso/R2/USEPA/US@EPA, Dilshad
Perera/R2/USEPA/US@EPA
cc:
Subject: ACM referrals

Ray,
We encountered two instances of asbestos insulated pipes this week.
The first was in an apartment we were scheduled to clean at 64 Fulton,
apt. [PII]. The resident's name is [PII], and her phone number is
[PII]. She had wrapped the pipes in duct tape the night before,
but in doing so knocked loose insulation onto her floor.
The second was in a boiler room/bicycle storage room of a whole building
we took a tour of at 69 Gold. The building manager's name is Joseph
DeAngelis and his number is 212-312-5728.
Please let me know if you need any further information.
Thanks.
Elizabeth