

**BENJAMIN KURZBAN
& SON CONTROL, INC.**1248 Ralph Ave.
BROOKLYN, N.Y. 11236

(718) 531-2900

INVOICE

1199

TO Department of Environmental Protection
59-17 Junction Blvd
Corona, NY 11368

DATE 10/15/02	ORDER NO.
SHIP TO Contract ROM-REF 2	

SALESPERSON	DATE SHIPPED	SHIPPED VIA	F.O.B. POINT	TERMS	
QUANTITY	DESCRIPTION			UNIT PRICE	TOTAL
>	Registration # CT82620020015280				
	Pin# 82601WTCROOF2				
	For work completed at 70 Fulton St				
	12,349 SF @ 2/SF				
	Total Amount due this Invoice				\$24,698.00
	<i>R. Raether</i>				

ORIGINAL

Thank You!

22. Sample Analysis Laboratory _____


23. NYS DOH ELAP # _____

VI. PROJECT INFORMATION

24. Starting date for this portion of work 09/24/02Projected completion date 10/24/02Asbestos work schedule ☒ Monday ☒ Tuesday ☒ Wednesday ☒ Thursday ☒ Friday ☒ Saturday ☒ SundayShift from: 8⁰⁰ ☒ am ☐ pm to 8⁰⁰ ☐ am ☒ pmIf other,
specify _____

Access to inspect the premises must be provided during the work schedule indicated in this item

25. Total amount of asbestos-containing material to be abated during this work

12349 Square Feet, and/or 0 Linear Feet

E175WTC

ONLY
TYPEWRITTEN
FORMS WILL BE
ACCEPTED



NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
Asbestos Control Program
59-17 Junction Boulevard, 8th Floor, Corona, NY 11368-5107
ASBESTOS PROJECT NOTIFICATION
(ASBESTOS INSPECTION REPORT)

File 15654102
Building Dept. or TRU No
FOR OFFICIAL USE ONLY
1. NYC DEP
(See fee schedule)

When submitting this form at the NYC Department of Buildings, the original form and three (3) copies with original signatures are required. Submittal at the NYCDEP requires one copy of the form with original signatures. This form must be submitted to the NYC DEP not less than one week in advance of the start of abatement activities.

I. FACILITY

2. Address 70 FULTON STREET Borough MAN Zip 10038
AKA _____ 3. Block 76 4. Lot 28
5. Type of Facility MIXED USE 6. Name of Building _____

II. BUILDING OWNER

7. Name _____ 8. Contact Person _____
9. Tel. # _____ Fax # _____
10. Address _____ City _____ State _____ Zip _____

III. GENERAL CONTRACTOR

11. Name _____ Tel. # _____

IV. ASBESTOS ABATEMENT CONTRACTOR

12. Name BENJAMIN KURZBAN & SON CONTROL INC. 13. Contact Person LOUIE LANNICO
14. Federal Employer ID. # PII 15. Tel. # (718) 531-2900 Fax # (718) 209-1808
16. Address 1248 RALPH AVENUE City BROOKLYN State NY Zip 11236

V. THIRD PARTY AIR MONITOR

17. Name WARREN & PANZER ENGINEERS 18. Contact Person MICHAEL NOLAN
19. Federal Employer ID. # PII 20. Tel. # (212) 922-0077 Fax # (212) 922-0630
21. Address 228 EAST 45TH STREET City NEW YORK State NY Zip 10017
22. Sample Analysis Laboratory _____ 23. NYS DOH ELAP # _____

VI. PROJECT INFORMATION

24. Starting date for this portion of work 09/24/02 Projected completion date 10/24/02

Asbestos work schedule ☒ Monday ☒ Tuesday ☒ Wednesday ☒ Thursday ☒ Friday ☒ Saturday ☒ Sunday

Shift from: 8⁰⁰ ☒ am ☐ pm to 8⁰⁰ ☐ am ☒ pm

If other,
specify _____

Access to inspect the premises must be provided during the work schedule indicated in this item.

25. Total amount of asbestos-containing material to be abated during this work

12349 Square Feet, and/or 0 Linear Feet



ACP
2/200

BUREAU OF ENVIRONMENTAL
REMEDIATION & ENFORCEMENT
ASBESTOS CONTROL
PROGRAM
T811

ASBESTOS INSPECTION REPORT (continued)

26. Asbestos Hauler: IESI, NY NYS DEC Permit # NJ-462 Tel.# (718) 522-2263
 Disposal Site(s) BLUE RIDGE LANDFILL PO Box 399 SCOTSDALE PA 17254

27. This asbestos abatement is part of a (Item a through e requires filing of this form with NYC Department of Buildings)

- a) ☐ Demolition b) ☐ Boiler Replacement c) ☐ Sprinkler Replacement d) ☐ Renovation/Alteration
 e) ☐ Fireproofing Replacement f) ☐ Other (Describe) _____

28. TYPE OF ABATEMENT (Check all appropriate boxes)

- ☐ Removal ☐ Enclosure ☐ Encapsulation ☐ Repair ☒ Clean up

29. ABATEMENT PROCEDURE (Check all appropriate boxes)

- ☐ Full Containment ☐ Glovebag ☐ Tent ☐ DEP Variance Application

30. LOCATIONS OF ABATEMENT ROOF MATERIAL: ROOF MEMBRANE (TAR)

Floor(s)	DESCRIBE SECTION OF FLOOR (e.g. entire, east wing, room #, boiler room, lobby, etc.)	AFFECTED SURFACES CONTAINING ACM (e.g. Pipe lagging, ceiling, plenum ducts, storage tanks, decking, etc.)	AMOUNT OF ACM SQUARE FEET LINEAR FEET	DESCRIPTION OF WORK BEING PERFORMED (e.g. running cable, installing fire sprinklers, removing and replacing boilers, etc.)
ROOF		ROOF SURFACE	6004	
"		METAL & SKYLIGHTS	2000	
FACADE	EAST	FACADE SURFACES	4345	

31. I hereby declare that the information provided herein is true and complete to the best of my knowledge. I am familiar with Federal, State and NYC laws and regulations applicable to asbestos related work.

WARREN & PANZER ENGINEERS Print Name of Air Monitor <u>ELENO, Dipo</u> Signature <u>9/23/02</u> Date	B. KURZBAN & SON CONTROL Print Name of Asbestos Contractor <u>[Signature]</u> Signature <u>09/23/02</u> Date	Print Name of Applicant (If other than Owner) _____ Signature _____ Date _____
--	--	---

32. I understand that as the owner of a building where asbestos abatement activity occurs, I am responsible for the performance of the asbestos abatement activities in accordance with the Asbestos Control Program Rules. I have contracted the third party air monitor who is completely independent of all parties involved in the asbestos project. I hereby declare that I have authorized the filing of this notification for the work specified herein.

 Print Name of Owner [Signature] 09/23/02
 Signature Date

A STAMPED COPY OF THIS FORM INCLUDING AMENDMENTS MUST BE AVAILABLE AT THE WORK SITE.

Any modification of information provided on this form must be reported immediately in writing directly to the NYC DEP ACP.

The requirements of the Asbestos Control Program Rules may not be lawfully avoided or lessened through the performance of work in incremental or piecemeal fashion.

ACP7
2/2001


ATHENICA

ENVIRONMENTAL SERVICES INC.

Tel. (718) 784-7490

Fax. (718) 784-4085

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

CLIENT: Warren & Panzer Engineers, P.C.

LABORATORY ID #: T02-09-089

ANALYT. METHODOLOGY: AHERA

FILTER TYPE: M.C.E.

 AVERAGE G.O. AREA (mm²): 0.013838

PROJECT: NYC DEP, 70 Fulton Street

DATE OF REPORT: 09/25/02

DATE OF ANALYSIS: 09/25/02

 EFFECTIVE FILTER AREA (mm²): 385

LABORATORY RESULTS

CLIENT #	LAB. ID #	LOCATION	VOLUME (l)	G.O.'s ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIV. (ftruct./cm ²)	TOTAL ASBESTOS AIR CONC. (ftruct./cm ²)	TOTAL ASBESTOS FILTER CONC. (ftr./100cm ²)	AIR CONC. FOR STRUCT. ANALYSIS	AIR CONC. FOR STRUCT. ANALYSIS	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST. TYPE SPECIFY
01	T02-09-089-2516	Exit to the roof	1350	5	0.0692	0.0041	<0.0041	<14.45	NA	NA	NA	NA
02	T02-09-089-2517	By decon	1350	5	0.0692	0.0041	<0.0041	<14.45	NA	NA	NA	NA
03	T02-09-089-2518	IWA left side of WA	1350	5	0.0692	0.0041	<0.0041	<14.45	NA	NA	NA	NA
04	T02-09-089-2519	IWA middle of WA	1350	5	0.0692	0.0041	<0.0041	<14.45	NA	NA	NA	NA
05	T02-09-089-2520	IWA right side of WA	1350	5	0.0692	0.0041	<0.0041	<14.45	NA	NA	NA	NA

ANALYST

E. Sioultri

LABORATORY DIRECTOR

Spiro Dangaris

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Athenica Environmental Services Inc. (AES), is responsible only for information pertaining to samples taken by its employees
- Air sampling activities will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentrations were derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

220 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-0630

WARREN & PANZER ENGINEERS, P. C.

AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

24 hr⁺/a 12 hr⁺/a 6 hr⁺/a 3 hr⁺/a Immediate ⁺/a

CLIENT: NYC DEP

PROJECT: Cleaning (Roof)

LOCATION: 70 FULTON ST NYC

W&P FILE #: 1079-01-02

LABORATORY: W&P

ANALYSIS METHOD: PCM TEM

circle one 7400 HERA EPA LEVEL II

TECHNICIAN: DIPLO FAFAN

CONTACT: MICHAEL NOLEN

PAGE 1 OF 1

P.O.

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE START	FLOWRATE STOP	TIME ON	TIME OFF	TOTAL TIME	VOLUME (liters)	CONCENTR. (lb./cc.)
01	Exit to the roof	3		09	09	1530	1800	150	1350	
02	By Decan	3		09	09	1531	1801	150	1350	
03	W&A left side of WA	3		09	09	1532	1802	150	1350	
04	✓ middle ✓	3		09	09	1533	1803	150	1350	
05	✓ right side ✓	3		09	09	1535	1803	150	1350	
06	field blank	1						NA		
07	✓	1						NA		
08	Sealed blank	1						NA		

COMMENTS:

T02-09-089

SAMPLE BY: DIPLO ELEMAN	DATE: 9/24/02
SIGNATURE: Diplo	
RELEASED BY: DIPLO ELEMAN	DATE: 9/24/02
SIGNATURE: Diplo	
RECEIVED BY: A. G. [Signature]	DATE: 9/25/02
SIGNATURE: A. G. [Signature]	

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION


ATHENICA

ENVIRONMENTAL SERVICES INC.

Tel. (718) 784-7450

Fax. (718) 784-4885

CLIENT: Warren & Pauzer Engineers, P.C.

LABORATORY ID #: T02-09-092

ANALYT. METHODOLOGY: AHERA

FILTER TYPE: M.C.E.

 AVERAGE G.O. AREA (mm²): 0.013838

PROJECT: NYC DEP, 70 Fulton Street

DATE OF REPORT: 09/26/02

DATE OF ANALYSIS: 09/26/02

 EFFECTIVE FILTER AREA (mm²): 385

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

LABORATORY RESULTS

CLIENT #	L.A.B. ID #	LOCATION	VOLUME (ft ³)	G.O.'s ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIVITY (struct./cm ²)	TOTAL ASBESTOS AIR CONC. (fibre/cm ³)	TOTAL ASBESTOS FILTER CONC. (fibre./mm ²)	AIR CONC. FOR STRUCT. 0.55-3µm	AIR CONC. FOR STRUCT. ≥2.5µm	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST. TYPE SPECIFY
01	T02-09-092-2531	Exit to roof	1530	4	0.0554	0.0045	<0.0045	<18.07	NA	NA	NA	NA
02	T02-09-092-2532	By decon	1530	4	0.0554	0.0045	<0.0045	<18.07	NA	NA	NA	NA
03	T02-09-092-2533	IWA left side of W/A	1530	4	0.0554	0.0045	<0.0045	<18.07	NA	NA	NA	NA
04	T02-09-092-2534	IWA middle of W/A	1530	4	0.0554	0.0045	<0.0045	<18.07	NA	NA	NA	NA
05	T02-09-092-2535	IWA right side of W/A	1530	4	0.0554	0.0045	<0.0045	<18.07	NA	NA	NA	NA

E. Sioukri

ANALYST

E. Sioukri

LABORATORY DIRECTOR

Spiro Doergaris

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Athenica Environmental Services Inc. (AES), is responsible only for information pertaining to samples taken by its employees.
- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

228 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-0630

WARREN & PANZER ENGINEERS, P. C. AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

PAGE 1 OF 1

P.O. _____

12 hr⁺/a 6 hr⁺/a 3 hr⁺/a Immediate ⁺/a

24 hr⁺/a

CONTACT: MICHAEL NOLAN

W&P FILE #: 1079-01-02

LABORATORY: WPL

ANALYSIS METHOD: PCM TEM TEM
circle one AHERA EPA LEVEL II

TECHNICIAN: Dipo F-12-01

CLIENT: NYC DEP

PROJECT: Cleanup (Roof)

LOCATION: 70 Fulton St NYC

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE START STOP	TIME ON OFF	TOTAL TIME	VOLUME (liters)	CONCENTR (flg./cc.)
01	Exit to roof	3		03 03	0930 1800	510	1530	
02	By Decon	3		03 03	0931 1801	510	1530	
03	W&P Left Side of W&P	3		03 03	0932 1802	510	1530	
04	✓ Middle	3		03 03	0933 1803	510	1530	
05	✓ Right Side	3		03 03	0935 1805	510	1530	
06	field blank	1			NA			
07		1			NA			
08	Sealed blank	1			NA			

COMMENTS:

T02-09-092

SAMPLE BY: Dipo F-12-01	DATE: 9/25/02
SIGNATURE: Dipo	
RELEASED BY: Dipo F-12-01	DATE: 9/25/02
SIGNATURE:	
RECEIVED BY: ASHLEY	DATE: 9/26/02
SIGNATURE: J. Giff	

SAMPLE TYPE CODES:	
Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION


ATHENICA

ENVIRONMENTAL SERVICES INC.

 Tel. (718) 794-7490
 Fax. (718) 794-4885

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

CLIENT: Warren & Panzer Engineers, P.C.
 LABORATORY ID #: T02-09-096
 ANALYT. METHODOLOGY: AHERA
 FILTER TYPE: M.C.E.
 AVERAGE G.O. AREA (mm²): 0.013838
 PROJECT: NYC DEP, 70 Fulton Street
 DATE OF REPORT: 09/27/02
 DATE OF ANALYSIS: 09/27/02
 EFFECTIVE FILTER AREA (mm²): 385

LABORATORY RESULTS

CLIENT #	LAB. ID #	LOCATION	VOLUME (l)	G.O. ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIVITY (microg/cm ³)	TOTAL ASBESTOS AIR CONC. (microg/cm ³)	TOTAL ASBESTOS FILTER CONC. (microg/cm ³)	AIR CONC. FOR STRUCT. 0.5-5-5µm	AIR CONC. FOR STRUCT. 5-5-5µm	ASBEST. TYPE CHRY.	AMPHIB. ASBEST. TYPE SPECIFY
001	T02-09-096-2561	East roof	1620	4	0.0554	0.0043	<0.0043	<18.07	NA	NA	NA	NA
002	T02-09-096-2562	East roof	1620	4	0.0554	0.0043	<0.0043	<18.07	NA	NA	NA	NA
003	T02-09-096-2563	Inside building	1620	4	0.0554	0.0043	<0.0043	<18.07	NA	NA	NA	NA
004	T02-09-096-2564	West roof	1620	4	0.0554	0.0043	<0.0043	<18.07	NA	NA	NA	NA
005	T02-09-096-2565	West roof	1620	4	0.0554	0.0043	<0.0043	<18.07	NA	NA	NA	NA

E. Sioukri

 ANALYST
 E. Sioukri

 LABORATORY DIRECTOR
 Spiro Dongaris

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Athenica Environmental Services Inc. (AES), is responsible only for information pertaining to samples taken by its employees.
- Air sampling easements will be placed for sixty (60) days. AES Inc., should be notified within this time frame for a free duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product enforcement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

WARREN & PANZER ENGINEERS, P. C.
AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

	24 hr ⁺ /a	12 hr ⁺ /a	6 hr ⁺ /a	3 hr ⁺ /a	Immediate ⁺ /a	P.O.
--	-----------------------	-----------------------	----------------------	----------------------	---------------------------	------

CLIENT: DEP

PROJECT: Roof cleaned

LOCATION: 70 Fulton Street

W&P FILE #: 107901902

LABORATORY: ~~W.H. H. H.~~ - ~~H. H. H. H.~~

ANALYSIS METHOD: PCM

TECHNICIAN: **ARTHUR TOLDO**

CONTACT:

P.O.

PAGE 1 OF

[illegible]

COMMENTS:

102-09-096

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR MAILING INFORMATION

SAMPLE BY: ARTHUR J. JEFFER DATE: 7/2/62

SIGNATURE: Arthur Miller

RELEASED BY: AKHANE JEFFRE DATE: 9/26/02

SIGNATURE: Arthur J. Lee

RECEIVED BY: A. CAJIGAL DATE: 9/27/02

SIGNATURE: [Signature]


ATHENICA

ENVIRONMENTAL SERVICES INC.

Tel. (718) 764-7496

Fax. (718) 764-4085

CLIENT: Warren & Padzer Engineers, P.C.

LABORATORY ID #: T02-09-116

ANALYT. METHODOLOGY: AHERA

FILTER TYPE: M.C.E.

 AVERAGE G.O. AREA (mm²): 0.013838

PROJECT: NYC DEP, 70 Fulton Street

DATE OF REPORT: 09/30/02

DATE OF ANALYSIS: 09/30/02

 EFFECTIVE FILTER AREA (mm²): 385

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

LABORATORY RESULTS

CLIENT #	LAB. ID #	LOCATION	VOLUME (#)	G.O.'s ANAL. YZXB	AREA ANALY ZED (mm ²)	ANALYT. SENSITV. (struct./cm ²)	TOTAL ASBESTOS AIR CONC. (fibre/cm ³)	TOTAL ASBESTOS FILTER CONC. (fibre/cm ²)	AIR CONC. FOR STRUCT. 0.55-5µm	AIR CONC. FOR STRUCT. S25.0µm	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST. TYPE SPECIFY
01	T02-09-116-2670	Closest to Fulton St.	1800	4	0.0554	0.0039	<0.0039	<18.07	NA	NA	NA	NA
02	T02-09-116-2671	In alleyway	1800	4	0.0554	0.0039	<0.0039	<18.07	NA	NA	NA	NA
03	T02-09-116-2672	In center of alleyway	1800	4	0.0554	0.0039	<0.0039	<18.07	NA	NA	NA	NA
04	T02-09-116-2673	10ft from sample #03	1800	4	0.0554	0.0039	<0.0039	<18.07	NA	NA	NA	NA
05	T02-09-116-2674	Furthest from sample #01	1800	4	0.0554	0.0039	<0.0039	<18.07	NA	NA	NA	NA

E. Siakoti

ANALYST

E. Siakoti

LABORATORY DIRECTOR

Spiro Doudaris

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Athenica Environmental Services Inc. (AES), is responsible only for information pertaining to samples taken by its employees.
- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

**228 East 45th Street
New York, NY 10017
(212) 922-8077
Fax (212) 922-8630**

WARREN & PANZER ENGINEERS, P. C.
AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

Fax (212) 922-0830

24 hr⁺/a 12 hr⁺/a 6 hr⁺/a 3 hr⁺/a Immediate ⁺/a

P.O.

CLIENT:

W&P FILE #: 1079-01:06

CONTACT:

PROJECT 70 SUMNER ST. N.Y.C.

LABORATORY:

ANALYSIS METHOD: PCM T80 TEM

LABORATORY:

ANALYSIS METHOD:	PCM	TEM
	circle one	AHBA EPA LEVEL II

TECHNICIAN: E. DIBALA

[illegible]

COMMENTS:

DATE: 9.28.2002

702-09-116

SAMPLE BY:

History

DATE: 9.28.2002

SIGNATURE:

10

1

RELEASED BY:

1.

DATE-

SIGNATURE:

1

RECEIVED BY

17577

DATE: 8/30/07

SIGNATURE

20

SAMPLE TYPE CODES

1 - Blank

1 - Blank

1 - Blank

5. Elmal Nizami

(admission) will fill in

(admission) will fill in

U - Ullrich, G.

ת.א. 10001-03-15

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

Asbestos Inspection Report

Premise No. 70 FULTON STREET					Inspection Date: AS NOTED	
Floor ROOF & FACADE	Zip 10038	Borough 1	Block 76	Lot 28	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type MIXED USE		Basis of Inspection WTC Survey		Photos Taken Yes/No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: AS NOTED		
TUESDAY SEPTEMBER 24 2002						
CONTRACTOR BROUGHT EQUIPMENT AND MATERIALS TO THE WORK SITE. A REMOTE DECONTAMINATION UNIT WAS ERECTED ON THE ROOF OF THE PREMISE.						
WEDNESDAY SEPTEMBER 25 2002						
THE CLEAN UP OF THE ROOF OF THE PREMISE BEGAN TODAY. AIR SAMPLING FOR TODAY'S CLEAN UP ACTIVITIES WAS PERFORMED BY DIPO EUEMO (CERTIFICATE # AH 01-14694 EXP 03/03) OF WARREN & PANZER.						
THURSDAY SEPTEMBER 26 2002						
THE CLEAN UP OF THE ROOF OF THE PREMISE WAS COMPLETED. AIR SAMPLING FOR TODAY'S CLEAN UP ACTIVITIES WAS PERFORMED BY ARTHUR C. SETTER (CERTIFICATE # AH 97-06135 EXP 03/03). AT THE COMPLETION OF CLEANING ACTIVITIES I CONDUCTED A VISUAL INSPECTION OF THE CLEANED ROOF SURFACES AND I OBSERVED NO VISIBLE WTC DEBRIS. THE CLEAN UP OF THE EAST FACADE OF THE PREMISE IS SCHEDULED FOR SATURDAY SEPTEMBER 28 2002.						
SATURDAY SEPTEMBER 28 2002						
THE CLEAN UP OF THE EAST FACADE WAS CONDUCTED. A DYKE WAS CONSTRUCTED IN THE ALLEY (RYDERS ALLEY) TO COLLECT WATER RUN OFF. A DECON TRUCK WAS UTILIZED. FACADE SURFACES WERE ACCESSED USING EXTENSION LADDERS. AIR SAMPLING WAS PERFORMED BY EDMAN DIBRA (CERTIFICATE # AH 01-12337 EXP 02/03) OF WARREN & PANZER. UPON COMPLETION OF CLEANING ACTIVITIES, I CONDUCTED A VISUAL INSPECTION OF THE CLEANED FACADE SURFACES AND I OBSERVED NO VISIBLE WTC DEBRIS. THE CLEAN UP PROJECT AT THE PREMISE IS NOW COMPLETE.						