

WTC Visual Survey Form

Premise Address: <u>180 Duane St</u>		
Block:	Residential ☒ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories: <u>6</u>	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name: <u>None</u>		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:

		Inspected	Debris	Debris	Debris
North	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: _____

Roof

Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"

Description: _____

Setbacks ☐ N/A

Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"	Debris: ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"	Debris: ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"	Debris: ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"	Debris: ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"	Debris: ☐ > 1"

Comments

Date: 5/1/2002Inspection Team: Name: CMC

Agency: _____

Name: _____ Agency: _____



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

February 5, 2002

511

Building Owner Name: _____

Address: _____

Subject: 180 Duane St

Dear Sir/ Madam:


In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,


R. Radhakrishnan, P.E.
Director
Asbestos Control Program



```

05/02/02          N.Y.C. DEPARTMENT OF BUILDINGS          BISPI031
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
180..... DUANE STREET..... 1 MANHATTAN          10013 BIN# 1001524
DCP GEOGRAPHICAL INFORMATION:
DUANE STREET          180 - 180          HEALTH AREA : 77          TAX BLK: 141..
CENSUS TRACT: 1017          TAX LOT: 24...
COMMUNITY BD: 101          CONDO :
MULTI STRUCT: 1          CUI NO :

DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : 180 DUANE STREET LLC          180 DUANE STREET LLC
CORP. NAME :          LPC LANDMARK STATUS: LANDMARK
ADDRESS : 182          DUANE ST          DOB LOCAL LAW STATUS: NO
          NEW YORK NY 10013-6605

DOF BUILDING INFORMATION:          TRANS LAND VALUE: 600,000
BLDG SIZE: 0024.00 X 0120.00          TAX EXEMPT FLAG : NO
LOT SIZE: 0024.83 X 0127.83          TAX EXEMPT CLASS:
BLDG CLASS : 00 ELEVATOR APT          CITY OWNERSHIP : NO
STORIES : 5          UPDATE DATE : 03/25/02
FOR CITY } MGMT TYPE:          MGMT CODE:          MGMT CODE NAME:
OWNERSHIP }          MGMT HOLDER CODE:          MGMT HOLDER CODE NAME:
-----
PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

```

Robert C. Avaltroni
Deputy Commissioner
Bureau of
Environmental Compliance
Tel (718) 595-4418
Fax (718) 595-4422