



Time Equities, Inc.
55 Fifth Avenue
New York, N.Y. 10003-4398
Phone: 212.206.6000
Fax: 212.727.0563
www.timeequities.com

June 14, 2002

Mr. R. Radhakrishnan, P.E.
NYCDEP
59-17 Junction Boulevard, 8th Floor
Flushing, NY 11373

Re: 7 Dutch Street

Dear Mr. Radhakrishnan, P.E.,

Enclosed please find two executed copies of the License Agreement for the DEP Cleaning Program. Please execute both agreements and return one copy to our office for our records.

Should you need any further information please call me at (212) 206-5694.

Sincerely,


Bruce Rittenberg

Enc.

CC: Michael Greenburger

WTC Visual Survey Form

Premise Address: 7 DUTCH STREET		
Block:	Residential ☒ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's: 7 1/2 DUTCH STREET	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
South	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ 1/2 to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ 1/2 to 1"	☐ > 1"
Facade Description:					
DEBRIS OBSERVED ON WINDOW LEDGES AND ON THE FIRE ESCAPES					
AND ON METAL SHUTTERS LOCATED ON THE WEST FACADE					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ 1/2 to 1" ☐ > 1"					
Description: LIGHT COATING < 1/2" ON ROOF IN SCATTERED LOCATIONS					
ON THE ROOF SURFACE AND ON DUCTING AND A/C UNIT					
Setbacks N/A ☐					
Floor: 2	Debris:	☒ No Visible/Fine Layer	☒ 1/2 to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"	
Comments					

Date: 06 / 05 / 2002

Inspection Team: Name: DA

Agency: DEP

Name: _____

Agency: _____