

WTC Visual Survey Form

1000825

Premise Address: <u>40 Exchange place (aka) 27 William St.</u>		
Block: <u>25</u>	Residential ☐ Commercial ☐	Name of Building:
Lot: <u>27</u>	Mix Use ☐ Other ☐	
# of Stories: <u>20</u>	AKA's:	
Building Owner/Management: <u>Diversified Mgmt.</u>		Telephone Number: <u>(212) 422-2446</u>
Name: <u>Darryl Washington</u>		FAX: <u>()</u>
Address:		
On Site Contact:		
Name:		Telephone Number: <u>()</u>
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:			
North	☐ N/A	Inspected	Debris
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Facade Description:			

Roof			
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"			
Description: <u>(Remote spots) noted in several locations.</u>			

Setbacks <u>N/A</u> ☒			
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Comments			

Date: 3/2/2002Inspection Team: Name: RamonaAgency: DEP

Name: _____

Agency: _____