

3
1

APPENDIX D - FIBERGLASS FINAL AIR SAMPLING RESULTS

10

3D

2



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

PROJECT INFORMATION

1. Client:	DEP		2. Project Name	DEP Clean - w/p		3. Project #	15-22306-0002		4. Project Monitor:			4c. Rotameter Number:	SD-006	
			2a. Project Address	125 Cedar St.		3a. Task #	0002		4a. Air Sampler:	E. Lewanovich				
5. Date:	10.07.02		6. Abatement Location:			7. ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____	8. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		9. Type:	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☐ Other				

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number		11. Pump Number		12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. FCC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg					
				Field Blank											
				Field Blank											
FB-PH-01	✓			13 Floor Pent house	16:31	22:55	384	10	10	10	3840	4/100	<0.001		
FB-PH-02	✓			---	16:33	22:56	383	10	10	10	3830	3/100	<0.001		
FB-PH-03	✓			---	16:35	22:57	382	10	10	10	3820	3/100	<0.001		
FB-PH-04	✓			---	16:37	22:58	381	10	10	10	3810	2/100	<0.001		
FB-PH-05	✓			---	16:39	22:59	380	10	10	10	3800	3/100	<0.001		
FB-12N-06	✓			12 Floor Apartment North	16:44	23:05	381	10	10	10	3810	4/100	<0.001		
FB-12N-07	✓			---	16:46	23:06	380	10	10	10	3800	3/100	<0.001		
FB-12N-08	✓			---	16:48	23:07	379	10	10	10	3790	5/100	<0.001		
FB-12N-09	✓			---	16:50	23:08	378	10	10	10	3780	4/100	<0.001		
FB-12N-10	✓			---	16:52	23:09	377	10	10	10	3770	1/100	<0.001		
FB-12SW-11	✓			12 Floor Apartment SW	16:57	23:12	375	10	10	10	3750	5/100	<0.001		
FB-12SW-12	✓			---	16:59	23:13	374	10	10	10	3740	10/100	<0.001		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I E. Lemnovich	A. Elbert	10.2.2	11:20
II			
III			

26. ATC Project Manager:	27. Result To:
B. Sallemi	B. Sallemi
	Beeper/Phone #'s

LAB INFORMATION

22. Lab Name: ATZ	23. Date: 10/07/06	24. Time: 1850
a. Analyzed By: Phogz		
b. QC By:		
c. Lab Batch #: 101526		

28. Comments:

25. Microscope Make/Serial #
OLYMPUS 3001105
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology

☒ PCM - NIOSH 7400B *Q. 1.*
TEM - AHRA

|



7



|





AIR MONITORING DATA
AND
CHAIN OF CUSTODY FORM

Page 2 of 4

TURNAROUND TIME

☐ 2 hrs ☐ 4 hrs ☒ 6 hrs ☐ 48 hrs ☐ Standard ☐ Other

PROJECT INFORMATION

1. Client: DEF	2. Project Name: DEF Clean - up	3. Project # 15-23306-0008	4. Project Monitor: E. Lemanovich
5. Date: 10.0.02	2a. Project Address: 125 Cedar St NY 10002	3a. Task # 00002	4c. Rotameter Number: SD-006
6. Abatement Location:	7. ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacture Lot # 51283102	8. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture Lot #	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☐ Other

F. Berglass

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		13. Time (24 hrs clock)			14. Flow Rate (L/min.)		15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	13a. Start	13b. End	13c. Total	14a. Start	14b. End			
FB-12SW-13		V		17:01	23:14	373	10	10	3730	4100	<0.001
FB-12SE-14		V		17:05	23:17	372	10	10	3720	5100	<0.001
FB-12SE-15		V		17:07	23:18	371	10	10	3710	4100	<0.001
FB-12SE-16		V		17:09	23:19	370	10	10	3700	8100	<0.001
FB-12SE-17		V		17:11	23:20	369	10	10	3690	8100	<0.001
FB-12SE-18		V		17:13	23:21	368	10	10	3680	5100	<0.001
FB-11W-19		V		17:19	23:24	365	10	10	3650	7100	<0.001
FB-11W-20		V		17:21	23:25	364	10	10	3640	6100	<0.001
FB-11W-21		V		17:23	23:26	363	10	10	3630	7100	<0.001
FB-11W-22		V		17:25	23:27	362	10	10	3620	5100	<0.001
FB-11W-23		V		17:27	23:28	361	10	10	3610	4100	<0.001
FB-11S-24		V		17:33	23:35	362	10	10	3620	4100	<0.001

CHAIN OF CUSTODY

18. Relinquished By: IC Lemanovich	19. Received By: H. Elbert	20. Date: 10.8.2	21. Time: 11:00
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC	23. Date: 10/08/02	24. Time: 18:50
a. Analyzed By: H. Elbert	b. QC By:	c. Lab Batch #: 101526
25. Microscope Make/Serial #: Nikon Labophot 238917		
26. ATC Project Manager: B. Salemi		
27. Result To: B. Salemi		
28. Comments:		
Analysis Methodology: PCM - NIOSH 7400A BOK TEM - AHERA		

WHITE - File YELLOW - Client/Report

PINK - Lab GOLDENROD - Field

NY-1 (1/01)

0



1



1





AIR MONITORING DATA
AND
CHAIN OF CUSTODY FORM

Page 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☒ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client: DEP	2. Project Name: DEP Clean - 4/0	3. Project # 15-22906-0002	4. Project Monitor: E. Lemanovich	4c. Rotameter Number: SD-006
5. Date: 10.0.02	2a. Project Address: 125 Cedar St NY 10002	3a. Task # 00002	4a. Air Sampler:	
6. Abatement Location: 101283102	7. VPCOM (0.8 micron MCE) 01283102	8. TEM (0.45 micron MCE)	9. Type:	f. Environmental
			a. Background	g. Ambient
			b. Pre-Abate	h. Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		13. Time (24 hrs clock)		14. Flow Rate (L/min.)		15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	13a. Start	13b. End	14a. Start	14b. End			
FB-11S-25	V			17:35	23:36	10	10	3610	16/100	0.002
FB-11S-26	V			17:37	23:37	10	10	3600	5/100	<0.001
FB-11S-27	V			17:39	23:39	10	10	3600	9/100	<0.001
FB-11S-28	V			17:41	23:41	10	10	3600	8/100	<0.001
FB-10N-29	V			17:57	23:57	10	10	3660	10/100	0.001
FB-10N-30	V			17:55	23:58	10	10	3650	5/100	<0.001
FB-10N-31	V			17:55	23:59	10	10	3640	4/100	<0.001
FB-10N-32	V			17:57	24:00	10	10	3630	3/100	<0.001
FB-10N-33	V			17:59	00:01	10	10	3620	5/100	<0.001
FB-10S-34	V			18:27	00:34	10	10	3680	5/100	<0.001
FB-10S-35	V			18:29	00:36	10	10	3670	7/100	<0.001
FB-10S-36	V			18:31	00:37	10	10	3660	3/100	<0.001

CHAIN OF CUSTODY

18. Relinquished By: I. E. Lemanovich	19. Received By: A. Elbert	20. Date: 10.8.2	21. Time: 11:12 am
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC	23. Date: 10/08/02	24. Time: 18:50
a. Analyzed By: [Signature]		
b. QC By:		
c. Lab Batch #: 101526		
25. Microscope Make/Serial #:	25. Microscope Make/Serial #:	
☐ Nikon Labophot 238813	☐ Nikon Labophot 238813	
☐ Nikon Labophot 238917	☐ Nikon Labophot 238917	
☐ Nikon Labophot 239079	☐ Nikon Labophot 239079	
Analysis Methodology	Analysis Methodology	
VPCOM - NIOSH 7400A B A.K.	VPCOM - NIOSH 7400A B A.K.	
TEM - AHRA	TEM - AHRA	

26. ATC Project Manager:

B. Sallemi

27. Result To: B. Sallemi

Beeper/Phone #:

WHITE - File YELLOW - Client/Report

PINK - Lab GOLDENROD - Field

of

3 D



PROJECT INFORMATION

1. Client: DEP	2. Project Name DEP Clean-up	3. Project # 15-22906-0008	4. Project Monitor:	4c. Rotameter Number:
	2a. Project Address 195 Cedar St. NY	3a. Task # 90002	4a. Air Sampler: E. Lemanovic	
5. Date: 10.07.08	6. Abatement Location:	7. ☒ PCM (0.3 micron MCE) Cassette/Filter Manufacture _____ Lot # _____	8. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # _____	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

[illegible]

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
IC Lemanovich	A. Elbert	10.8.92	11am
II			
III			

26. ATC Project Manager: <i>B Sallemi</i>	27. Result To: <i>B Sallemi</i>
	Beeper/Phone #'s _____

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC	23. Date: 10/28/07	24. Time: 1850
a. Analyzed By: Phelps		
b. QC By:		
c. Lab Batch #: 101526		
28. Comments:		

of
-

3 D

6



AIR MONITORING AND CHAIN OF CUSTODY FORM

Page 1 of 4

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client: DEP	2. Project Name: DEP clean-up	3. Project # 15-23906-0002	4. Project Monitor: E. Lewanovich	4c. Rotameter Number: SD-006
5. Date: 10.08.08	2a. Project Address: 125 Cedar St.	3a. Task # 80002	4a. Air Sampler: E. Lewanovich	
6. Abatement Location:	7. VPCM (0.8 micron MCE) Cassette/Filter Manufacture Lot # 01283108	8. TEM (0.45 micron MCE) Cassette/Filter Manufacture Lot # 876	9. Type: a. ☐ Abatement b. ☐ Background c. ☐ Post-Abate d. ☐ OSHA e. ☐ Other	1. ☐ Environmental f. ☐ Ambient g. ☐ Ambient h. ☒ Other Cleaning

Fiber-glass

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		13. Time (24 hrs clock)			14. Flow Rate (L/min.)		15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. FCC
		12a. IWA	12b. OWA	13a. Start	13b. End	13c. Total	14a. Start	14b. End			
		Field Blank									
		Field Blank									
FB-9N-01	✓	9 Floor Apartment North		04:46	11:12	386	10	10	3860	16/100	1002
FB-9N-02	✓	---		04:48	11:13	385	10	10	3850	9/100	2002
FB-9N-03	✓	---		04:50	11:14	384	10	10	3840	12/100	1002
FB-9N-04	✓	---		04:52	11:15	383	10	10	3830	14/100	1002
FB-9N-05	✓	---		04:54	11:16	382	10	10	3820	9/100	2002
FB-9S-06	✓	9 Floor Apartment South		04:57	11:27	390	10	10	3900	12/100	1002
FB-9S-07	✓	---		04:59	11:28	389	10	10	3890	8/100	2002
FB-9S-08	✓	---		05:01	11:29	388	10	10	3880	14/100	1002
FB-9S-09	✓	---		05:03	11:30	387	10	10	3870	11/100	1002
FB-9S-10	✓	---		05:05	11:31	386	10	10	3860	12/100	1002
FB-8N-11	✓	8 Floor Apartment North		05:16	11:42	386	10	10	3860	20/100	1003
FB-8N-12	✓	---		05:18	11:43	385	10	10	3850	15/100	1002

CHAIN OF CUSTODY

18. Relinquished By: I E. Lewanovich	19. Received By: E. Lewanovich	20. Date: 10.8.8	21. Time: 1750
II			
III			

LAB INFORMATION (ATC FLAP # 10879, ATC NVLAP # 1187)

22. Lab Name: E. Lewanovich	23. Date: 10/9/08	24. Time: 1750
a. Analyzed By: E. Lewanovich	b. QC By:	c. Lab Batch #:
		101531
25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☒ Nikon Labophot 238979		
26. ATC Project Manager: B. Sallami		
27. Result To: B. Sallami		
28. Comments:		
Analysis Methodology: PCM NIOSH 7400A 3 TEM - AHERA		

WHITE - File YELLOW - Client/Report

PINK - Lab GOLDENROD - Field

NY-1 (1/01)

of

CD

1



AIR MONITORING DATA
AND
CHAIN OF CUSTODY FORM

Page 2 of 4

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client: DEP	2. Project Name: DEP Clean-up	3. Project # 15-22306-0002	4. Project Monitor: E. Lemanovich
5. Date: 10.08.09	6. Abatement Location: 12a. IWA 12b. OWA	7. POM (0.8 micron MCE) 0128-3108	8. TEM (0.45 micron MCE)
	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA		f. ☐ Environmental g. ☐ Ambient h. ☒ Other Cleaning

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		13. Time (24 hrs clock)			14. Flow Rate (L/min.)		15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	13a. Start	13b. End	13c. Total	14a. Start	14b. End			
FB-8N-13				05:20	11:24	384	10	10	3840	12/100	1002
FB-8N-14				05:22	11:45	383	10	10	3830	18/100	1002
FB-8N-15				05:24	11:46	382	10	10	3820	16/100	1002
FB-8S-16				05:31	11:55	384	10	10	3840	12/100	1002
FB-8S-17				05:33	11:56	383	10	10	3830	14/100	1002
FB-8S-18				05:35	11:57	382	10	10	3820	22/100	1003
FB-8S-19				05:37	11:58	381	10	10	3810	14/100	1002
FB-8S-20				05:39	11:59	380	10	10	3800	11/100	1002
FB-7N-21				05:57	12:12	381	10	10	3810	12/100	1002
FB-7N-22				05:53	12:13	380	10	10	3800	16/100	1002
FB-7N-23				05:55	12:14	379	10	10	3790	14/100	1002
FB-7N-24				05:57	12:15	378	10	10	3780	9/100	1002

CHAIN OF CUSTODY

18. Relinquished By: I E Lemanovich	19. Received By: [Signature]	20. Date: 10.8.2	21. Time: 1750
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: [Signature]	23. Date: 10/9/09	24. Time: 0500
a. Analyzed By: [Signature]		
b. QC By:		
c. Lab Batch #:	101531	

25. Microscope Make/Serial #:	☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☒ Nikon Labophot 239079
Analysis Methodology:	NIOSH 7400A B & M TEM - AHERA

26. ATC Project Manager: B. Sallemi	27. Result To: B. Sallemi
Beeper/Phone #s:	

28. Comments:	
---------------	--

WHITE - File YELLOW - Client/Report

PINK - Lab GOLDENROD - Field

10



CD



11





AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3

TURNAROUND TIME

- ☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client: DEF	2. Project Name: DEF Clean-up	3. Project # 15-22906-0007	4. Project Monitor:
5. Date: 10.8.2	6. Abatement Location: 185 Cedar St. NY 10002	7. ☒ PCM (0.3 micron MCE) Cassette/Filter Manufacture Lot # 01283102	8. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture Lot #
9. Date: 10.8.2	10. Abatement Location: 185 Cedar St. NY 10002	11. ☒ PCM (0.3 micron MCE) Cassette/Filter Manufacture Lot # 01283102	12. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture Lot #
13. Date: 10.8.2	14. Abatement Location: 185 Cedar St. NY 10002	15. ☒ PCM (0.3 micron MCE) Cassette/Filter Manufacture Lot # 01283102	16. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture Lot #

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location	13. Time (24 hrs clock)	14. Flow Rate (L/min.)	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	13a. Start	14a. Start	14b. End	14b. Avg	
		12b. OWA	13b. End	13c. Total			
		Field Blank					
		Field Blank					
FB-7N-25		7 Floor Apartment North	05:59	10	10	10	1002
FB-7S-26		7 Floor Apartment South	06:11	10	10	10	1002
FB-7S-27		---	06:13	10	10	10	1002
FB-7S-28		---	06:15	10	10	10	1002
FB-7S-29		---	06:17	10	10	10	1002
FB-7S-30		---	06:19	10	10	10	1002
FB-6N-31		6 Floor Apartment North	06:31	10	10	10	1002
FB-6N-32		---	06:33	10	10	10	1002
FB-6N-33		---	06:35	10	10	10	1002
FB-6N-34		---	06:37	10	10	10	1002
FB-6N-35		---	06:39	10	10	10	1002
FB-6S-26		6 Floor Apartment South	06:51	10	10	10	1002

CHAIN OF CUSTODY

18. Relinquished By: E. Lemmon	19. Received By: [Signature]	20. Date: 10.8.2	21. Time: 1750
II			
III			
26. ATC Project Manager: B. Sallemi	27. Result To: B. Sallemi	28. Comments:	
25. Microscope Make/Serial #:		25. Microscope Make/Serial #:	
☐ Nikon Labophot 238913		☐ Nikon Labophot 238913	
☐ Nikon Labophot 238917		☐ Nikon Labophot 238917	
☒ Nikon Labophot 239079		☒ Nikon Labophot 239079	
Analysis Methodology:		Analysis Methodology:	
PCM NIOSH 7400A B		PCM NIOSH 7400A B	
TEM - AHERA		TEM - AHERA	

101



AD



1



DAILY AIR SAMPLE RECORD	
Fiber class	

WHITE - File	YELLOW - Client/Report	PINK - Lab	GOLDENROD - Field	NY-1 (1/01)
--------------	------------------------	------------	-------------------	-------------

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	10/9/02	0500
b. QC By:		
c. Lab Batch #:	101531	
28. Comments:		

2 of 2

10

10



AIR MONITORING DATA
AND
CHAIN OF CUSTODY FORM

Page 2 8

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other

PROJECT INFORMATION

1. Client: DZP	2. Project Name: DZP Clean-up	3. Project # 2206-0002	4. Project Monitor: S. Stanyobers	4c. Rotameter Number: HP-22
5. Date: 10/08/02	6. Abatement Location: 5th Floor Apartments	7. PPM (0.8 micron MCE) Cassette/Filter Manufacture Lot # 108	8. TEM (0.45 micron MCE) Cassette/Filter Manufacture Lot #	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☒ Other Cleaning
2a. Project Address: 125 Cedar St. NY NY	3a. Task # 00002	4a. Air Sampler: Huber Pate		

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		13. Time (24 hrs clock)		14. Flow Rate (L/min.)		15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. FCC
		12a. IWA	12b. OWA	13a. Start	13b. End	14a. Start	14b. End			
FB01										
FB02										
FB503		✓		1631	1631	10.0	10.0	3600	46/100	0.006
FB504		✓		1633	1633	10.0	10.0	3600	53.5/100	0.008
FB505		✓		1635	1635	10.0	10.0	3600	69/100	0.009
FB506		✓		1637	1637	10.0	10.0	3600	17/100	0.002
FB507		✓		1639	1639	10.0	10.0	3600	47/100	0.006
FB508		✓		1648	1648	10.0	10.0	3600	38/100	0.005
FB509		✓		1649	1649	10.0	10.0	3600	32.5/100	0.004
FB510		✓		1652	1652	10.0	10.0	3600	40/100	0.006
FB511		✓		1653	1653	10.0	10.0	3600	41/100	<0.001
FB512		✓		1657	1657	10.0	10.0	3600	57/100	<0.001

CHAIN OF CUSTODY

18. Relinquished By: I.S. Stanyobers	19. Received By: A. Elchert	20. Date: 10/09/02	21. Time: 10:00 AM
II K. Huber Pate			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC	23. Date: 10/09/02	24. Time: 17:00
a. Analyzed By: Huber Pate	b. QC By:	c. Lab Batch #: 101535
28. Comments:		
25. Microscope Make/Serial #: Olympus 238913 ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 238979		
Analysis Methodology: PCM - NIOSH 7400MB TEM - AHERA		

26. ATC Project Manager: B. Sallami	27. Result To: B. Sallami Beeper/Phone #s
-------------------------------------	--

WHITE - File YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

10



3D





AIR MONITORING DATA
AND
CHAIN OF CUSTODY FORM

Page 4

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Clearing

PROJECT INFORMATION

1. Client: DEP	2. Project Name: Clean-up	3. Project # 2206-0002	4. Project Monitor: S. Etanyobere	4c. Rotameter Number: HP-72
5. Date: 10/08/02	2a. Project Address: Cedar St. NY NY	3a. Task # 00002	4a. Air Sampler: Aulien Heister	
6. Abatement Location: 4th Fl Apartments	7. PCM (0.8 micron MCE) Cassette/Filter Manufacturer: Miltomelice	8. Lot # 108	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☒ Other Clearing	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		13. Time (24 hrs clock)		14. Flow Rate (L/min.)		15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	13a. Start	13b. End	14a. Start	14b. End			
FB4S13	✓			1717	2317	10.0	10.0	3600	16/100	0.002
FB4S14	✓			1719	2319	10.0	10.0	3600	57/100	<0.001
FB4S15	✓			1721	2321	10.0	10.0	3600	11/100	<0.001
FB4S16	✓			1723	2323	10.0	10.0	3600	7/100	<0.001
FB4S17	✓			1725	2325	10.0	10.0	3600	11/100	<0.001
FB4N18	✓			1727	2327	10.0	10.0	3600	2/100	<0.001
FB4N19	✓			1729	2329	10.0	10.0	3600	57/100	<0.001
FB4N20	✓			1731	2331	10.0	10.0	3600	3/100	<0.001
FB4N21	✓			1733	2333	10.0	10.0	3600	4/100	<0.001
FB4N22	✓			1735	2335	10.0	10.0	3600	6/100	<0.001

CHAIN OF CUSTODY

18. Relinquished By: I.S. Etanyobere	19. Received By: A. Elend	20. Date: 10/08/02	21. Time: 1700
II. K. Heister			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC	23. Date: 10/08/02	24. Time: 1740
a. Analyzed By: K. Heister		
b. QC By:		
c. Lab Batch #: 101535		
28. Comments:		
25. Microscope Make/Serial #: Nikon Labophot 238917		
Analysis Methodology: ✓ PCM - NIOSH 7400A B TEM - AHERA		

26. ATC Project Manager: B. Salemi	27. Result To: B. Salemi
------------------------------------	--------------------------

WHITE - File YELLOW - Client/Report

PINK - Lab GOLDENROD - Field

NY-1 (1/01)

10

10

10

101



101



101





AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 8 of 8

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

Client: DEP		2. Project Name: DEP Clean-up		3. Project # 22060002		4. Project Monitor: S. Stampobere		4c. Rotameter Number: HP-72	
2a. Project Address: 125 Cedar St. NY NY		3a. Task # 00002		4a. Air Sampler: Aubert-Hest		5. Type: ☐ Abatement ☐ Post-Abate ☐ OSHA		6. Abatement Location: 2nd Fl. Apartments	
Date: 01/08/02		6. Abatement Location: 2nd Fl. Apartments		7. ☒ PCM (0.5 micron MCE) ☐ TEM (0.45 micron MCE)		8. ☐ Backdrop ☐ Pre-Abate		9. ☐ Environmental ☐ Ambient ☒ Other	
Lot # 108		Lot # 108		Lot # 108		Lot # 108		Lot # 108	

DAILY AIR SAMPLE RECORD

Sample I.D. Number	Pump Number	12. Sample Location		13. Time (24 hrs clock)		14. Flow Rate (L/min.)		15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	13a. Start	13b. End	14a. Start	14b. End			
FB45										
FB46										
FB2533	✓			1841	2441	360	10.0	10.0	10.0	3600
FB2534	✓			1843	2443	360	10.0	10.0	10.0	3600
FB2535	✓			1845	2445	360	10.0	10.0	10.0	3600
FB2536	✓			1847	2447	360	10.0	10.0	10.0	3600
FB2537	✓			1849	2449	360	10.0	10.0	10.0	3600
FB2538	✓			1851	2451	360	10.0	10.0	10.0	3600
FB2539	✓			1853	2453	360	10.0	10.0	10.0	3600
FB2540	✓			1855	2455	360	10.0	10.0	10.0	3600
FB2541	✓			1857	2457	360	10.0	10.0	10.0	3600
FB2542	✓			1859	2459	360	10.0	10.0	10.0	3600
FB143	✓			1903	0103	360	10.0	10.0	10.0	3600
FB44										

CHAIN OF CUSTODY

18. Relinquished By: 18 Stampobere	19. Received By: A. Elbert	20. Date: 10/08/02	21. Time: 7:00
II A. Elbert			
III A. Elbert			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC	23. Date: 10/08/02	24. Time: 1810
a. Analyzed By: Elbert		
b. QC By: 101536		
c. Lab Batch #: 101536		
25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079 Analysis Methodology: ☒ PCM - NIOSH 7400 B ☐ TEM - AHERA		
28. Comments:		

26. ATC Project Manager:

B. Sallami

27. Result To:

B. Sallami

Beeper/Phone #'s

10
—
12

10
—
12

10
—
12