

137 Greenwich

WTC Visual Survey Form

BIN 1001038
K9-Store Bldgr

Premise Address: <u>120 Cedar St</u> <u>137 Greenwich St</u>		
Block: <u>52</u>	Residential ☐ Commercial ☐	Name of Building:
Lot: <u>10</u>	Mix Use ☒ Other ☐	
# of Stories: <u>7</u>	AKA's: <u>137-139 Greenwich St</u>	
Building Owner/Management:		Telephone Number: <u>(201) 679 3012</u>
Name: <u>Mike - Owner</u>		FAX: ()
Address:		
On Site Contact: <u>Mike</u>		Telephone Number: <u>(201) 679 3012</u>
Building Owner Management Activities Interior Survey Performed ☐ Yes ☒ No Exterior Survey Performed ☐ Yes ☒ No General Clean Up ☒ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☒ No Locations: _____ Air Monitoring ☐ Yes ☒ No Locations: _____ Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
South	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"

Facade Description: _____

Roof

 Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"
 Description: A new roof is in place.
Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Owner said EPA had announced early
that there was no ACM.
Date: 1/25 /2002Inspection Team: Name: CARL
Name: _____Agency: PCP
Agency: _____

WTC Visual Survey Form

Premise Address: <u>120 Cedar St</u>		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories: <u>3</u>	AKA's: <u>137 Greenwich</u>	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name: <u>Owner</u>		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description:					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description:					
Setbacks N/A ☐					
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Comments					

Date: 6/14/2002 **Inspection Team: Name:** CARL **Agency:** _____

Name: _____ **Agency:** _____

E N T E R E

LICENSE AGREEMENT

This License Agreement made this 14 day of MAY 2002 by and between the CITY OF NEW YORK (hereinafter called "the City"/Licensee), acting by and through the Department of Environmental Protection of the City of New York (hereinafter called "DEP"), with an office at 59-17 Junction Boulevard, Corona, New York 11368-5107 and TARA Realty Co./Crosstown Mgmt Corp. ("Landowner/Licenser") the owner of the premises at 137 GREENWICH STREET (the "Premises").

WHEREAS, the facades, roofs and setbacks ("exterior areas") of many structures in close proximity to the site of the former World Trade Center have been found to contain debris, refuse and other deposits ("the foreign material") of unknown origin;

WHEREAS, the owners of said structures are desirous of having the foreign material removed;

WHEREAS, the City believes that it is in the interest of the public to undertake a clean up of these exterior areas;

WHEREAS, the City's willingness to undertake such a cleanup should not in any way be construed as an acknowledgment or admission that the City is in any way responsible for any condition, environmental or otherwise, that may exist in or on the exterior areas or that the foreign material is a risk to the public health or safety;

NOW THEREFORE, it is hereby agreed by and between the parties to this agreement, for and in consideration of One Dollar and other good and valuable consideration, the receipt of which is hereby acknowledged,

1. **Permission to Perform Cleaning Work.** Subject to the terms and conditions hereof, Licenser hereby grants permission to Licensee and its authorized contractor(s) to perform the cleaning work on the exterior areas of the structure(s) located on the Premises, as described in the Scope of Work attached hereto as Exhibit A and made a part hereof (the "Cleaning Work").

2. **Grant of Access.** Subject to the terms and conditions hereof, Licensee and its agents, contractors and employees shall have the right, at all times while this License Agreement is in effect, to enter in and on the Premises, and to cross the Premises, with personnel, material and equipment, for the purpose of performing the Cleaning Work. It is expressly understood that the right granted under this Section 2 includes:

(a) the right to access all portions of the Premises deemed necessary by Licensee or its contractor(s) in order to properly perform the Cleaning Work, including (without limitation) roofs, parapets, window ledges, and other building exterior surfaces; and