

WTC Visual Survey Form

Premise Address: 124 Liberty St		
Block: 52	Residential ☐ Commercial ☐	Name of Building: EDNY
Lot: 22	Mix Use ☐ Other ☐	
# of Stories: 3	AKA's: 127 Cedar Street / 141-151 Greenwich St	
Building Owner/Management: XION C		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:

		Inspected		Debris		
North	☐ N/A	☒ Yes ☐ No		☐ No Visible/Fine Layer	☐ ½ to 1"	☒ > 1"
South	☒ N/A	☐ Yes ☐ No		☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☒ N/A	☐ Yes ☐ No		☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No		☐ No Visible/Fine Layer	☐ ½ to 1"	☒ > 1"

Facade Description: _____

Roof

Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☒ > 1"

Description: Inspected for roof of 125 Cedar St

Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 1/25/2002

Inspection Team: Name: Carol Lutchman

Agency: DEP

Post-It® Fax Note 7671		Date 12/12/02	# of pages 1
To Mr. Reza Zeynali		From Krish	
Co./Dept. NYC FD		Co. DEP	
Phone #		Phone #	
Fax # 718-784-2494		Fax #	

ASBESTOS INSPECTION REPORT

PAGE 1 OF

HOUSE NO. 124		STREET liberty Street		INSPECTION DATE 11/25/02	
DOOR FACADE	ZIP 10006	BORO CODE 1	BLOCK 52	LOT 22	SQUAD # 1
INSPECTOR J. Plumptre		BLDG TYPE	BASIS OF INSPECT TRU 1578 MW02		BADGE # AD10
CONTRACTORS NAME FIBER CONTROL			SAMPLE NO.		
ADDRESS 3010 BURNS AVE			CITY WANTAGH		
STATE N.Y.			ZIP 11793		
LABORATORY NAME WARREN & PANZER ENGINEERS, PC			OWNERS NAME		
ADDRESS 228 E. 45TH ST			CITY N.Y.		
STATE N.Y.			ZIP 10017		
CONTACT PERSON:			TIME OF INSPECTION FROM: 3:30 am/pm TO: 4:00 am/pm		
INSPECTION DISCLOSED:					

I conducted another final cleanup inspection on the entire facade of the firehouse and I did not see any sign of suspected debris. The window that was found with material by inspector Lamolan has been cleaned. No visible debris observed after the cleanup.

NOV #	INFRACTIONS	RESULT CODE
		5
NOV #		SUPERVISORS INITIALS
		PL

BORO 1 - MANHATTAN 2 - BRONX 3 - BROOKLYN 4 - QUEENS 5 - RICHMOND

BLDG TYPE A > 6 Stories B < 6 Stories C Single Family D School E Hospital F Public Owned Property

RESULT CODES 1 - Violation issued 2 - No Violations issued 3 - No Access 4 - Project not Started (No NOV) 5 - Project Completed (No NOV)

ACP 306

ASBESTOS INSPECTION REPORT

PAGE 1 OF

EMISE NO. 124		STREET liberty Street			INSPECTION DATE 11/25/02	
DOR FACADE	ZIP 10006	BORO CODE 1	BLOCK 52	LOT 22	SQUAD # 1	BADGE # AD10
SPECTOR PLUMPTRE		BLDG TYPE	BASIS OF INSPECT. TRU 1878 MN02		PHOTOS TAKEN YES / NO	
CONTRACTORS NAME FIBER CONTROL				SAMPLE NO.		
ADDRESS 2010 BURNS AVE				CITY WANTAGH		
STATE N.Y				ZIP 11793		
LABORATORY NAME WARREN & PANZER ENGINEERS, PC				OWNERS NAME		
ADDRESS 228 E. 45TH ST				CITY N.Y		
STATE N.Y				ZIP 10017		
CONTACT PERSON:				TIME OF INSPECTION FROM: 3:30 am TO: 4:00 am		
INSPECTION DISCLOSED:						

I conducted another final cleanup inspection on the entire facade of the firehouse and I did not see any sign of suspected debris. The window that was found with material by inspector Kandelman has been cleaned. No visible debris observed after the cleanup.

NOV #	INFRACTIONS					RESULT CODE 5
NOV #						SUPERVISORS INITIALS

BORO 1 - MANHATTAN 2 - BRONX 3 - BROOKLYN 4 - QUEENS 5 - RICHMOND

BLDG TYPE A > 6 Stories B < 6 Stories C Single Family D School E Hospital F Public Owned Property

RESULT CODES 1 - Violation Issued 2 - No Violations Issued 3 - No Access 4 - Project not Started (No NOV) 5 - Project Completed (No NOV)

ACP 308

FILE