

WTC Visual Survey Form

Premise Address: <u>124 Liberty St</u>			
Block: <u>52</u>	☐ Residential ☐ Commercial	Name of Building: <u>FDNY</u>	
Lot: <u>22</u>	☐ Mix Use ☐ Other		
# of Stories: <u>3</u>	AKA's: <u>127 Cedar Street / 141-151 Greenwich St</u>		
Building Owner/Management:		Telephone Number: ()	
Name: <u>XION C</u>		FAX: ()	
Address:			
On Site Contact:			
Name:		Telephone Number: ()	
Building Owner Management Activities			
Interior Survey Performed ☐ Yes ☐ No			
Exterior Survey Performed ☐ Yes ☐ No			
General Clean Up ☐ Yes ☐ No		Locations: _____	
ACM Clean Up ☐ Yes ☐ No		Locations: _____	
Air Monitoring ☐ Yes ☐ No		Locations: _____	
Copies of All Reports and Data Requested ☐ Yes			

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☒ > 1"
South	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☒ > 1"
Facade Description:					

Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☒ > 1"					
Description: <u>Inspected for roof of 125 Cedar St</u>					

Setbacks ☐ N/A					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 1/15/2002Inspection Team: Name: Carol LutchmanAgency: DEP

WTC Visual Survey Form

Premise Address: 124 Liberty ST

Block: Residential ☐ Commercial ☐ **Name of Building:** FDNY

Lot: Mix Use ☐ Other ☐

of Stories: 3 **AKA's:**

Building Owner/Management: Name: XONC Telephone Number: () FAX: ()

Address:

On Site Contact: Name: Telephone Number: ()

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☐ No

Exterior Survey Performed ☐ Yes ☐ No

General Clean Up ☐ Yes ☐ No Locations: _____

ACM Clean Up ☐ Yes ☐ No Locations: _____

Air Monitoring ☐ Yes ☐ No Locations: _____

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☒ > 1"
South	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☒ > 1"

Facade Description: _____

Roof

Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☒ > 1"

Description: Inspected for roof of 125 Cedar St

Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 1/15/2002

Inspection Team: Name: Carol Lutchmans

Agency: DFR

WTC Visual Survey Form

Premise Address: <u>124 Liberty ST</u>		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	<u>FDNY</u>
# of Stories: <u>3</u>	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name: <u>NON</u>		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☒ > 1"
South	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☒ > 1"
Facade Description:					

Roof

Debris:	☐ No Visible /Fine Layer	☐ ½ to 1"	☒ > 1"
Description:	<u>Inspected from roof of 125 Cedar St</u>		

Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 1/25 /2002Inspection Team: Name: Care Lutz-Hamers
Name: _____Agency: DFP
Agency: _____

Page: 1 Document Name: Extra

ADDRESS EXISTS WITH A.K.A.S WHICH HAVE THE SAME BIN

01/30/02 PUBLIC ACCESS PROPERTY PROFILE OVERVIEW BISPIQ70
124..... LIBERTY STREET..... 1 MANHATTAN 10006 BIN# 1075700

LIBERTY STREET	124 - 124	HEALTH AREA : 77	TAX BLK: 52...
CEDAR STREET	127 - 127	CENSUS TRACT: 13	TAX LOT: 22...
GREENWICH STREET	141 - 151	COMMUNITY BD: 101	CONDO :
		MULTI STRUCT: 01	VACANT :

=====

DOB SPECIAL PLACE NAME :	1	PROPERTY RECORD(S)
DOB BUILDING REMARKS :		
FINANCE OCCUPANCY CODE :	Y1-GOVERNMENT INSTAL	LANDMARK STATUS:

COUNTS FOR THIS BIN		RECORD VERIFIED :
ACTIONS : 67 , 3	JOBS/FILINGS (PF4)	SPECIAL STATUS :
VIOLATIONS DOB : 1 , 1	OPEN	LOCAL LAW :
ECB : 0 , 0	OPEN (PF12)	SRO :
COMPLAINTS : 0 , 0	OPEN (PF11)	

PF 3 = ELEVATORS	ENTER KEY= ACTIONS	PF 5/6/7 = NEW ADDR/BIN/BLK-LOT
PF 8 = BOILERS	(TYPE :)	PF 9/10 = BROWSE BIN/BLK-LOT
*NO ARA'S FILED		PF 15 = BROWSE 1 PROPERTY RECORDS
PF 14 = LPC/HPD/LOFT USE ONLY		PF 16 = ADDTN'L PROPERTY INFO

Date: 1/30/ 2 Time: 01:49:16 PM