



Building Inspections

**Exterior Inspections (100% of buildings)
(Façade and/or Roof and/or setback)**

452

**! Buildings with varying degree of
debris present**

211

Complaints

! Complaints received since 9/11

174

! Complaints responded

174

! Complaints resolved to date

169

! Violation issued

1

! Clean-up ordered

1