



Building Inspections

Exterior Inspections (100% of buildings) **452**
 (Façade and/or Roof and/or setback)

- Buildings with varying degree of debris present **211**

Complaints

- Complaints received since 9/11 **75**
- Complaints responded **75**
- Complaints resolved to date **51**
- Violation issued **1**
- Clean-up ordered **1**