



Building Inspections

Exterior Inspections (100% of buildings) (Façade and/or Roof and/or setback)	452
• Buildings with varying degree of debris present	211
Complaints	
• Complaints received since 9/11	174
• Complaints responded	174
• Complaints resolved to date	169
• Violation issued	1
• Clean-up ordered	1