



Building Inspections

Exterior Inspections (100% of buildings) 452

(Façade and/or Roof and/or setback)

- Buildings with varying degree of debris present 211

Complaints

- Complaints received since 9/11 174
- Complaints responded 174
- Complaints resolved to date 169
- Violation issued 1
- Clean-up ordered 1