



Building Inspections

Exterior Inspections (100% of buildings)

452

(Façade and/or Roof and/or setback)

• Buildings with varying degree of debris present

2111

Complaints

• Complaints received since 9/11

174

• Complaints responded

174

• Complaints resolved to date

169

• Violation issued

1

• Clean-up ordered

1