

4/23/02
Per Cault - Bldg.
not in surveyed
area. (Pm)

14112x

Name of Operator Karen Date: 4/17 Time: 11:45

Category: (circle one)

Environment Cleaning Health Indoor Air
Specific Contaminant School Old WTC Other _____

Question:

Caller lives on Vestry below Canal St on the top floor - He is concerned about dust on the roof coming into his apartment ② His air conditioning units have not been cleaned and he has applied for funding w/ FEMA/RED cross SAFE Housing etc. The estimated cost will be \$500. No one will help. He has a 3 year old

Answer:

DEP has no information on cleaning or testing performed by building management - someone from DEP will contact him to schedule a visit for sampling dust on roof

Comments:

Please add building address to list for cleaning. DEP will go out to check roof for dust. son and ~~grandchildren~~ cannot afford to pay to have it cleaned

Caller Information:

First Name: JACK PII Last Name: ROSENBERG PII

Address 1: 19 VESTRY ST Apt. PII

Address 2: _____ Borough: Manhattan

City New York State: NY Zip: 10016

Phone #1 PII Phone #2 () _____

Follow up:

Referral/Follow-Up Needed? (circle one) YES NO

Referral Agency/Organization: DEP

DEP Reference # 485745

NYC DEP BANHazmat Exec Fax:7185953744

Apr 19 '02 15:44 P.03

88-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4088

Service Request Inspection Detail**Report Date** 04/19/2002 04:28 PM**Submitted By****Page 1****Service #** 438745**Problem** BWICH WTC RELATED (HOT LINE)**Address** PII**Cross Streets** HOLLAND TUNNEL EXIT
HUDSON ST**Compass Direction****Building ID**

10028

Block 00220**Lot** 0028**CMS#****Location****Area****Sub-Area** 101**District****Parcel****# of Calls** 1**Duration of Call** 00:00**Call Date** 04/17/2002 17:53**Taken By** 4757**MORALES, JANET****Responsibility** BHZ**BANHAZMAT (AIR,NOISE,HAZ.MAT)****Priority****Scheduled Date****Start Date****Inspector****Inspection Date****Due Date**☐ **No Work Orders Required****Resolution Code****Resolution Date****Asset****Avg Insp Duration**☐ **Customer Contact Req****Avg Insp Days** 0**Budget #****Avg Insp Hrs** 0**Avg Insp Mins** 0**Problem Comment** DEP has not received any information from the owner regarding this building.

This complaint has been forwarded to the Asbestos Unit for appropriate action.

Last Name BOBROWSKY**First Name, MI** JACK**Address** APT 5**City, State/Province, ZIP/PC**☐ **Foreign****Day Phone**

PII

Evening Phone**Reference #****Caller Comments** HEAVY DUST CONDITION ON ROOF COMING INSIDE HIS APT

There are no work orders for this service number

There are no assets