

13597 x

Name of Operator Reena Date: 3/19/02 Time: 2:05

Category: (circle one)

Environment

Cleaning - Dust

Health

Specific Contaminant

School

Other _____

Question:

He lives at building 2 blocks south of WTC and the building is full of dust especially the apartments. The landlord and the landlord's lawyer have said that the building has been tested and no asbestos was found but they refuse to show them any information. One tenant had her apartment tested and asbestos was found. In the DEP packet, his address is not shown as a building that was cleaned and tested.

No one lives there yet due to dust.

Comments:

- gave him the www.ny1.com site with specific info about the WTC Resource Guide
- [DEP - call ^{beforehand} because no one is in building]
- gave him Red Cross hotline #
- told him DEP would come check the building

Caller Information:

First Name: PII - Tenant Representative

Address 1: 106 Greenwich Apt _____

Address 2: _____

City NY State: NY Zip: _____

Phone #1 (PII) (212) 406-1295 Phone #2 () _____

Follow up:

Referral/Follow-Up Needed? (circle one) YES NO

Referral Agency/Organization: Need DEP to check the building for asbestos.

DEP Reference # 422357 3/26/02

3/26/02 - left message on (212) 406-1295 - read report Verbaing suggested that if they have further questions to call again

BWTCH Howard

NYC DEP

69-17 Junction Blvd.
Corona, NY 11388
(718)DEP-HELP Fax (718)595-4098

Service Request Inspection Detail

Report Date 03/26/2002 05:29 PM

Submitted By

Page 1

Service # 422367

Problem BWCH WTC RELATED (HOT LINE)

Address 106 GREENWICH ST 1

10006

Cross Streets RECTOR ST

CARLISLE ST

Compass Direction

Building ID 10010

Block 00053

Lot 0036

CMRD 101

Location

Area

Sub-Area 101

District

Parcel

of Calls 1

Duration of Call 00:00

Call Date 03/19/2002 17:52

Taken By 2862

FREYRE, RICARDO

Responsibility BHZ

BANHAZMAT (AIR,NOISE,HAZ,MAT)

Scheduled Date 03/19/2002 17:52

Priority

Start Date 03/19/2002 17:52

Inspector 5397

PLUMPTRE, ALPHONSO

Inspection Date 03/22/2002 13:30

Due Date

☐ No Work Orders Required

Resolution Code B2

ASBESTOS,NO VIOLATION

Resolution Date 03/22/2002 13:40

Asset

Avg Insp Duration

☐ Customer Contact Req

Budget #

Avg Insp Days 0

Avg Insp Hrs 0

Avg Insp Mins 0

Problem Comments DEP HAS NOT RECEIVED ANY INFORMATION FROM THE OWNER.

THIS COMPLAINT WAS FORWARDED TO THE ASBESTOS UNIT FOR APPROPRIATE ACTION.

LEFT MESSAGE ON 3/20/02 AT 9:00 AM

I INSPECTED APARTMENTS 5,8,10,4 AND 1. IN # 5 THE EXTERIOR WASHING OF THE WINDOWS ALLOWED SOME MATERIALS TO COME INTO THE APARTMENT LIKEWISE IN APARTMENTS 8 AND 10. IN APARTMENT 4 THERE ARE STILL DUSTS ON THE FLOOR AND THE WINDOWSILLS. LATER ON I CONTACTED THE MANAGING AGENT MS. WILLIAMS WHO PROMISED TO SEND CREW TO RECLEAN THE APARTMENTS AND ENTIRE HALLWAYS INCLUDING AIR MONITORING AFTER CLEANUP.

Initial Call

Last Name GARRAWAY

Title

First Name, MI SAELWYN

Address 106 GREENWICH STREET

City, State/Province, ZIP/PC

☐ Foreign

Day Phone (212)406-1285 x

Evening Phone

P11

Call Date 03/19/2002 17:52

Reference #

Caller Comments

CALLER INDICATES THAT HER BUILDING IS FULL OF DUST. MANAGEMENT SAYS THAT THE BUILDING WAS TESTED BUT IS REFUSING TO GIVE HER THE RESULTS. DEP HAS NO RECORD THAT HER BUILDING HAS BEEN CLEANED OR TESTED. THE BUILDING IS PRESENTLY VACANT DUE TO THE DUST IN THE BUILDING. ONE APARTMENT THAT WAS SUPPOSEDLY TESTED CAME BACK POSITIVE FOR ASBESTOS. REQUESTS THAT BUILDING BE CHECKED

THIS WAS CALLED IN BY KAREN ELLIS

Work Order

Work Order #

Activity

Asset

Project

Act Type

Act Group

Initiated

Scheduled

Completed

Status

Main Type

There are no work orders for this service number

P.03

17:51

Mar 26 '02

NYC DEP BANHAZMAT Exec Fax:7185953744

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4085

Service Request Inspection Detail

Report Date 03/19/2002 08:50 PM

Submitted By

Page 1

Service # 422357
Problem BWTCH WTC RELATED (HOT LINE)
Address 106 GREENWICH ST 1
10006
Cross Streets RECTOR ST
CARLISLE ST
Compass Direction
Building ID 10010 Block 00053 Lot 0036 CMBD 101

Location
Area
Sub-Area 101 District Parcel

of Calls 1 Duration of Call 00:00 Call Date 03/19/2002 17:52
Taken By 2882 FREYRE, RICARDO
Responsibility BHZ BANHAZMAT (AIR, NOISE, HAZ. MAT) Priority
Scheduled Date Start Date
Inspector Inspection Date
Due Date ☐ No Work Orders Required
Resolution Code Resolution Date
Asset
Avg Insp Duration 3/26 Inspection done 3/22
Avg Insp Days 0 (file faxed)
Avg Insp Hrs 0
Avg Insp Mins 0
☐ Customer Contact Req
Budget #

Problem Comments

Initial Caller

Last Name
First Name, MI
Address

PII

City, State/Province, ZIP/PC

☐ Foreign

Day Phone

PII

Evening Phone (848)314-8714 X

Call Date 03/19/2002 17:52

Reference #

Caller Comments

CALLER INDICATES THAT HER BUILDING IS FULL OF DUST. MANAGEMENT SAYS THAT THE BUILDING WAS TESTED BUT IS REFUSING TO GIVE HER THE RESULTS. DEP HAS NO RECORD THAT HER BUILDING HAS BEEN CLEANED OR TESTED. THE BUILDING IS PRESENTLY VACANT DUE TO THE DUST IN THE BUILDING. ONE APARTMENT THAT WAS SUPPOSEDLY TESTED CAME BACK POSITIVE FOR ASBESTOS. REQUESTS THAT BUILDING BE CHECKED

THIS WAS CALLED IN BY KAREN ELLIS

Work Order #	Activity	Asset	Asst Type	Asst Group	Initiated	Scheduled To Type	Completed	Source	Maint Type
--------------	----------	-------	-----------	------------	-----------	-------------------	-----------	--------	------------

There are no work orders for this service number

Assets	From Type	Unit ID	To Type	Unit ID	#	Qualifier
--------	-----------	---------	---------	---------	---	-----------

There are no assets