

14142X

Name of Operator Rose Marchetti Date: 4/18/02 Time: 11:30 AM

Category: (circle one)

Environment

Cleaning

Health

Indoor Air

Specific Contaminant

School

Old WTC

Other _____

IAQ

Question:

Caller plans to move to 110 Fulton Street.

Answer:

Did bulk testing + general clean-up; no Air or Testing
no interior debris

Comments:

Am cking DEP for a clearer understanding
of results.

Caller Information:

First Name:

PII

Last Name:

PII

Address 1:

Apt _____

Address 2:

Borough: _____

City _____

State: _____

Zip: _____

Phone #1:

PII

Phone #2 (_____) _____

(cell phone)

Follow up:

Referral/Follow-Up Needed? (circle one)

YES

NO

Referral Agency/Organization:

DEP

DEP Reference #

437126

BWTC H
4/19/02
Cha

NYC DEP 88-17 Junction Blvd. Corona, NY 11368 (718)DEP-HELP Fax (718)595-4055		Service Request Inspection Detail																																									
Report Date 04/19/2002 04:48 PM		Submitted By																																									
Page 1																																											
Service # 437126 Problem BWTC WTC RELATED (HOT LINE) Address 110 FULTON ST 1 10038 Cross Streets WILLIAM ST DUTCH ST Compass Direction Building ID 10011 Block 00078 Lot 0018 CMB																																											
Location Area District Sub-Area 101 Parcel																																											
<table style="width: 100%; border: none;"> <tr> <td style="width: 25%;"># of Calls 1</td> <td style="width: 25%;">Duration of Call 00:00</td> <td style="width: 25%;">Call Date 04/19/2002 15:17</td> <td style="width: 25%;"></td> </tr> <tr> <td>Taken By 7146</td> <td>MAYFIELD, CHERELLE</td> <td></td> <td></td> </tr> <tr> <td>Responsibility BHZ</td> <td>BANHAZMAT (AIR, NOISE, HAZ. MAT)</td> <td>Priority</td> <td></td> </tr> <tr> <td>Scheduled Date</td> <td></td> <td>Start Date</td> <td></td> </tr> <tr> <td>Inspector</td> <td></td> <td>Inspection Date</td> <td></td> </tr> <tr> <td>Due Date</td> <td></td> <td>☐ No Work Orders Required</td> <td></td> </tr> <tr> <td>Resolution Code A8</td> <td>CLOSED AFTER RESEARCH</td> <td>Resolution Date 04/19/2002 18:48</td> <td></td> </tr> <tr> <td>Asset</td> <td></td> <td>☐ Customer Contact Req</td> <td></td> </tr> <tr> <td>Avg Insp Duration</td> <td></td> <td>Budget #</td> <td></td> </tr> <tr> <td style="border: 1px solid black; padding: 2px;"> Avg Insp Days 0 Avg Insp Hrs 0 Avg Insp Mins 0 </td> <td></td> <td></td> <td></td> </tr> </table>				# of Calls 1	Duration of Call 00:00	Call Date 04/19/2002 15:17		Taken By 7146	MAYFIELD, CHERELLE			Responsibility BHZ	BANHAZMAT (AIR, NOISE, HAZ. MAT)	Priority		Scheduled Date		Start Date		Inspector		Inspection Date		Due Date		☐ No Work Orders Required		Resolution Code A8	CLOSED AFTER RESEARCH	Resolution Date 04/19/2002 18:48		Asset		☐ Customer Contact Req		Avg Insp Duration		Budget #		Avg Insp Days 0 Avg Insp Hrs 0 Avg Insp Mins 0			
# of Calls 1	Duration of Call 00:00	Call Date 04/19/2002 15:17																																									
Taken By 7146	MAYFIELD, CHERELLE																																										
Responsibility BHZ	BANHAZMAT (AIR, NOISE, HAZ. MAT)	Priority																																									
Scheduled Date		Start Date																																									
Inspector		Inspection Date																																									
Due Date		☐ No Work Orders Required																																									
Resolution Code A8	CLOSED AFTER RESEARCH	Resolution Date 04/19/2002 18:48																																									
Asset		☐ Customer Contact Req																																									
Avg Insp Duration		Budget #																																									
Avg Insp Days 0 Avg Insp Hrs 0 Avg Insp Mins 0																																											
Problem Comment: The owner indicated to DEP that both Bulk and air testing were done. The results of that testing were not provided to DEP. The owner also indicated that a General clean-up of the building was done. Additionally, a visual survey performed by DEP staff on 3/02 indicated no evidence of WTC debris.																																											
<table style="width: 100%; border: none;"> <tr> <td style="width: 25%;">Last Name</td> <td style="width: 25%; border: 1px solid black; text-align: center; font-size: 2em;">PII</td> <td style="width: 25%;"></td> <td style="width: 25%;"></td> </tr> <tr> <td>First Name, MI</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Address</td> <td></td> <td></td> <td></td> </tr> <tr> <td>City, State/Province, ZIP/PC</td> <td></td> <td></td> <td></td> </tr> <tr> <td>☐ Foreign</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Day Phone</td> <td style="border: 1px solid black; text-align: center; font-size: 1.5em;">PII</td> <td>Evening Phone</td> <td></td> </tr> <tr> <td>Reference #</td> <td></td> <td></td> <td></td> </tr> </table>				Last Name	PII			First Name, MI				Address				City, State/Province, ZIP/PC				☐ Foreign				Day Phone	PII	Evening Phone		Reference #															
Last Name	PII																																										
First Name, MI																																											
Address																																											
City, State/Province, ZIP/PC																																											
☐ Foreign																																											
Day Phone	PII	Evening Phone																																									
Reference #																																											
Caller Comments CALLER WANTED TO KNOW ABOUT AIR QUALITY IN HIS APARTMENT IN THIS BUILDING AND WHAT KIND OF CLEAN UP WAS DONE.																																											
There are no work orders for this service number																																											