

Name of Operator B Macdonald Date: 3-13-02 Time: 3PM HSE 13466

Category: (circle one)

Environment

Cleaning

Health

Specific Contaminant

School

Other

Indoor Air

Answer:

1AQ

Question:

VISIBLE DUST, INFLUENCE
FROM OPENING ON 7TH FL.
WAS CHECKED OUT. ADVISED: WE WILL
CONTACT DEP RE TO REQUEST VISIT; THEY CAN
CONTACT LL FOR COPY OF REPORT;
CAN CHECK BACK WITH RE LL
REPORT IN 1 WEEK.

Comments:

Caller Information:

First Name:

PII

Last Name:

PII

Address 1:

198 Broadway

Apt 7TH FL

CITIZEN'S
UNION

Address 2:

City:

State:

Zip:

10088

Phone:

PII

Phone #2 ()

Follow up:

Referral/Follow-Up Needed? (circle one)

YES

NO

Referral Agency/Organization:

DEP - BWH - DOH

DEP Reference #

420273

MADE REFERRAL 3-13-02

NYC DEP

66-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)695-4000

Service Request Inspection Detail

Report Date 03/14/2002 02:46 PM

Submitted By

Page 1

Service # 420273

Problem BWTCH WTC RELATED (HOT LINE)

Address 198 BROADWAY 1
10038Cross Streets DEY ST
FULTON ST

Compass Direction

Building ID 10012

Block 00070

Lot 0010

CMBD 101

Location

Area District

Sub-Area Parcel

101

of Calls 1

Duration of Call 00:00

Call Date 03/13/2002 18:53

Taken By 6957

WILLIAMS, CHERYL E.

Responsibility BHZ

BANHAZMAT (AIR,NOISE,HAZ.MAT)

Scheduled Date

Priority

Inspector

Start Date

Due Date

Inspection Date

Resolution Code

☐ No Work Orders Required

Asset

Resolution Date

Avg Insp Duration

☐ Customer Contact Req

Avg Insp Days 0

Budget #

Avg Insp Hrs 0

Avg Insp Mins 0

Problem Comments DEP HAS NOT RECEIVED ANY INFORMATION FROM THE OWNER.

THIS COMPLAINT HAS BEEN FORWARDED TO THE ASBESTOS UNIT FOR APPROPRIATE ACTION.

Initial Caller

Last Name

First Name, MI

Address

City, State/Province, ZIP/PC

☐ Foreign

Day Phone

(212)227-0342 x13

Evening Phone

Call Date 03/13/2002 16:53

Reference #

Caller Comments VISIBLE DUST FROM 7TH FL CEILING///CHECK FOR POTENTIAL ASBESTOS

Work Order

Work Order #

Activity

Asset

Act Type

Act Group

Initiated

Scheduled

Completed

Source

Main Type

Priority

Problem

Project

Pr Type

Unit ID

To Type

Unit ID

Unit ID

Unit ID

There are no work orders for this service number

Assets

Asset From Type Unit ID To Type Unit ID # Qualifier

There are no assets

Linked Requests

Service # Problem

Problem Date

Address

Location

P.02

14:46

Mar 14 '02

NYC DEP BANHAZMAT Exec Fax:7185953744