

Gilsenan, Michael

From: Theodorellys, Penny
Sent: Thursday, March 27, 2003 3:52 PM
To: Gilsenan, Michael
Subject: FW: 114 Liberty aka 119 Cedar Street, Manhattan

FYI

-----Original Message-----

From: Rammohan, Ramasubbu
Sent: Thursday, March 27, 2003 3:43 PM
To: Radhakrishnan, Krish
Cc: Theodorellys, Penny; Lutchmedial, Carlstien; Plumptre, Alphonso
Subject: 114 Liberty aka 119 Cedar Street, Manhattan

Here are the pictures from the Pizza Parlor today. There are two ceilings 6"to 8" apart with wire mesh, plaster and sprayon on them above the drop ceiling. The lower wire mesh ceiling's spray on appears to be encapsulated by green bridge encapsulant, deteriorated and dislodged on top of the drop ceiling at various locations. Several ceiling tiles were removed and the sprayon insulation came down on the floor. I have collected four of the dislodged spray on material from the floor and one big plaster chunk on the drop ceiling.



104-0424_IMG.JPG 104-0423_IMG.JPG 104-0424_IMG.JPG 104-0425_IMG.JPG 104-0426_IMG.JPG 104-0427_IMG.JPG











