

FINDINGS REPORT


FOR

59 MAIDEN LANE ASSOCIATES, LLC
59 MAIDEN LANE
NEW YORK, NY

RE: DUST BULK/WIPE SAMPLING

AT

59 MAIDEN LANE
NEW YORK, NY 10038

aka
66 John St


SEPTEMBER 9, 2002

3002/041

GLOMAR CORP
35 EAST MAIN STREET
ELMSFORD, NY 10523
(914) 345-1170

RECEIVED
SEP 17 2002
59 MAIDEN LANE

TABLE OF CONTENTS

<u>SECTION</u>	<u>TITLE</u>
-----------------------	---------------------

I.	INTRODUCTION/SUMMARY
-----------	-----------------------------

II.	DUST BULK/WIPE SAMPLING CRITERIA, METHODS
------------	--

APPENDIX A: DUST BULK/WIPE SAMPLE LOCATIONS AND ANALYSIS

**RE: DUST BULK/WIPE SAMPLING
59 Maiden Lane
New York, NY**

**ALL RIGHTS RESERVED. NO PART OF THIS REPORT MAY BE REPRODUCED,
STORED IN A RETRIEVAL SYSTEM OR TRANSMITTED BY ANY MEANS,
MECHANICAL PHOTOCOPYING, RECORDING OR OTHERWISE, WITHOUT THE
WRITTEN PERMISSION OF GLOMAR CORP. AND 59 MAIDEN LANE ASSOCIATES,
LLC.**

I. INTRODUCTION/SUMMARY

Glomar Corp., Asbestos Testing and Consulting, was contracted by 59 Maiden Lane Associates, LLC to perform Dust/Bulk Wipe Sampling on the outside window sills on various floors of the building at 59 Maiden Lane, New York, NY.

Testing was performed to determine the presence or absence of asbestos in the Dust of the Bulk/Wipe Samples collected on the window sills that may still be present on the building as a result of the massive dust created by the claps of the World Trade Center Buildings on September 11, 2001.

Testing took place on July 5 and 8, 2002.

Glomar Corp. Technician, Mr. Sean Murray, was the on-site Technician.

All Bulk/Wipe Samples were collected by Glomar Corp and analyzed by Scientific Labs, New York, NY, a New York State approved Environmental Testing Laboratory. All samples were analyzed utilizing Phase Light Microscopy (PLM) and/or Transmission Electron Microscopy (TEM) analysis. This report relates ONLY to the analysis expressed as "asbestos present" or "no asbestos visible".

Sampling was performed on the outside window sill on selected windows facing John Street side of the building on the 7th, 8th, 9th, and 14th Floors.

II. DUST BULK/WIPE SAMPLING CRITERIA, METHODS and ANALYSIS

The Dust Bulk/Wipe Samples were prepared and analyzed by using Standard Operating Procedure developed by Scientific Laboratories, Inc. After preparation, using non-quantitative matrix reduction if necessary, the presence or absence of asbestos is determined by PLM and/or TEM as indicated on the attached summary tables.

See Appendix A for Dust Bulk/Wipe Sample Locations and Analysis

APPENDIX A

GLOMAR CORP


**35 East Main Street
Elmsford, NY 10523**

SciLab Job#: 202071471
Client Name: GLOMAR CORP.

Page 1 of 1


Table I
Summary of Bulk Asbestos Analysis Results
59 Maiden Lane, New York City (7th Floor) Wipes

SciLab Sample #	Client Sample# Location	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	Asbestos by PLM/DS	Asbestos by TEM
01	01 7-1 Williams Side Of Bldg. Middle Window Sill		----	----	----	----	Chrysotile Present	NA
02	02 7-2 Williams Side Of Bldg. 10th Window From John St.		----	----	----	----	Chrysotile Present	NA
03	03 7-3 John St. Side Of Bldg. Last Window Corner John Williams		----	----	----	----	NVA	Chrysotile Present
04	04 7-4 John St. Side Middle Window		----	----	----	----	Chrysotile Present	NA
05	05 7-5 End Window Towards Broadway		----	----	----	----	Chrysotile Present	NA

Analyzed by: Jonathan M. Teda ; Date Analyzed 7/7/02

Quantitative Analysis (Semi/Full): Bulk Asbestos Analysis - PLM by EPA 600/M4-82-020 per 40 CFR (NVLAP Lab#200546-0); TEM (Semi/Full) by EPA 600/R-93/116 (not covered by NVLAP Bulk accreditation); or ELAP 198.1/198.4 for New York samples (NYSDOH ELAP#11480); NAD = no asbestos detected during a quantitative analysis; NA = not analyzed; Trace = <1%; Quantitation for beginning weights of <0.1 grams should be considered as qualitative only; Qualitative Analysis: Asbestos analysis results of "Present" or "NVA = No Visible Asbestos" represents results for Qualitative PLM or TEM Analysis only (no accreditation coverage available from any regulatory agency for qualitative analyses); AIHA Lab#102843.

Warning Note: PLM limitation, only TEM will resolve fibers <0.25 micrometers in diameter. TEM bulk analysis is representative of the fine grained matrix material and may not be representative of non-uniformly dispersed debris for which PLM evaluation is recommended (i.e. soils and other heterogenous materials).

Reviewed By: 

202071471

117 EAST 30TH STREET
NEW YORK, NY 10016

Company: GLOMAR		Address:						P.O.#:
Project Information		Analysis		Turnaround Time				Air Filter
Name: 59 MAIDEN LANE, NYC 7TH FL - (WIPE)	Type	6-8hr	12hr	24hr	48hr	72hr	5day	Other
	TEM/AHERA							MCE
	TEM/Level II							PC
	TEM/Chatfield							25mm
	TEM/Dust							37mm
	TEM/Water							0.45um
Number:	PCM							0.80um
Manager:	PLM				X			Other:
Site (City/State):	Lead							
	Other							X
Results to: Office		Return Samples Yes No						
Invoice to:		Phone 914,345-2170						
Written report to:		Fax						
COMMENTS: Wipe Samples (Please Dewet)		Pager						
Sample I.D.	Sample Location	Start Time	Stop Time	Total Time	Liters/Min	Air Volume	Date Collected	
From Window Sills Discard Sample								
01	7-1 - Williams Side of Bldg - Middle Window Sill						7-5-02	
02	7-2 Williams Side of Bldg 10th Window from John St.						7-5-02	
03	7-3 JOHN ST. SIDE OF BLDG EAST Window Corner John William						7-5-02	
04	7-4 - JOHN ST SIDE - Middle Window						7-5-02	
05	7-5 - END WINDOW TOWARDS BRGY						7-5-02	
Relinquished By (Signature) _____		Date 7/5/02		Received By (Signature) _____		Date 7/5		

Sub Job#: 202071471
Client Name: GLOMAR CORP.

Page 1 of 1

Table I
Summary of Bulk Asbestos Analysis Results
59 Maiden Lane, New York City (7th Floor) Wipes

SciLab Sample #	Client Sample# Location	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	Asbestos by PLM/DS	Asbestos by TEM
01	01 7-1 Williams Side Of Bldg. Middle Window Sill		----	----	----	----	Chrysotile Present	NA
02	02 7-2 Williams Side Of Bldg. 10th Window From John St.		----	----	----	----	Chrysotile Present	NA
03	03 7-3 John St. Side Of Bldg. Last Window Corner John Williams		----	----	----	----	NVA	NA
04	04 7-4 John St. Side Middle Window		----	----	----	----	Chrysotile Present	NA
05	05 7-5 End Window Towards Broadway		----	----	----	----	Chrysotile Present	NA

Analyzed by: Christine M. Tappen *Christine M. Tappen*; Date Analyzed 7/7/02

Quantitative Analysis (Semi/Full): Bulk Asbestos Analysis - PLM by EPA 600/M4-82-020 per 40 CFR (NVLAP Lab#200546-0); TEM (Semi/Full) by EPA 600/R-93/116 (not covered by NVLAP Bulk accreditation); or ELAP 198.1/198.4 for New York samples (NYSDOH ELAP#11480); NAD = no asbestos detected during a quantitative analysis; NA = not analyzed; Trace = <1%; Quantitation for beginning weights of <0.1 grams should be considered as qualitative only; Qualitative Analysis: Asbestos analysis results of "Present" or "NVA = No Visible Asbestos" represents results for Qualitative PLM or TEM Analysis only (no accreditation coverage available from any regulatory agency for qualitative analyses); AIHA Lab#102843.

Warning Note: PLM limitation, only TEM will resolve fibers <0.25 micrometers in diameter. TEM bulk analysis is representative of the fine grained matrix material and may not be representative of non-uniformly dispersed debris for which PLM evaluation is recommended (i.e. soils and other heterogenous materials).

Reviewed By: *Lance Tappen*



SCIENTIFIC LABORATORIES, INC.

117 EAST 30TH STREET

NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

202071471

Company: GLOMAR		Address:		P.O.#:							
Project Information		Analysis		Turnaround Time							
Name: 59 MAIDEN LANE, NYC 7TH FL. (WIPES)		Type	6-8hr	12hr	24hr	48hr	72hr	5day	Other	Air Filter Information	
		TEM/AHERA								MCE	
		TEM/Level II								PC	
		TEM/Chatfield								25mm	
		TEM/Dust								37mm	
		TEM/Water								0.45um	
Number:	PCM									0.80um	
Manager:	PLM									Other:	
Site (City/State):	Lead										
	Other										
Results to: Office		Return Samples		Yes		No					
Invoice to:		Phone		Fax		Pager					
Written report to:		914,345-2170									
COMMENTS: Wipe Samples (Please DO NOT)											
From Window Sills		Discard Samples		Sample Location		Start Time		Stop Time		Total Time	
										Liters/Min	
										Air Volume	
										Date Collected	
01	7-1 - Williams Side of Bldg - Middle Window Sill										7-5-02
02	7-2 Williams Side of Bldg 10th Window from John St.										7-5-02
03	7-3 John St. Side of Bldg East Window corner John St.										7-5-02
04	7-4 - John St Side - Middle Window										7-5-02
05	7-5 - End Window Towards Bldg										7-5-02
Relinquished By (Signature)		Date		Received By (Signature)		Date					
		7/5/02				2:30				7/5	

SciLab Job#: 202071658
Client Name: GLOMAR CORP.

Page 1 of 2

Table I
Summary of Bulk Asbestos Analysis Results
59 Maiden Lane, NYC, 8th Floor/ Window Sills/ Wipes - Amended Report 07/12/02

SciLab Sample #	Client Sample# Location	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	Asbestos by PLM/DS	Asbestos by TEM
01	06 Mr. Hyden Blades Office- Window Sill		----	----	----	----	Chrysotile Present	NA
02	07 Sylvia Ireland's Office- Window Sill		----	----	----	----	Chrysotile Present	NA
03	08 G-Kraus Friedbergs Office- Window Sill		----	----	----	----	Chrysotile Present	NA
04	09 Gregory Tatars Office- Window Sill		----	----	----	----	Chrysotile Present	NA
05	010 Corner Area- Window Sill		----	----	----	----	Chrysotile Present	NA
06	011 Mr. Vincent's Office- Window Sill		----	----	----	----	Chrysotile Present	NA
07	012 Window Sill Adj. Copy Machine		----	----	----	----	Chrysotile Present	NA
08	013 John St. Window- Window Sill		----	----	----	----	Chrysotile Present	NA
09	014 John St. Side Last Window Sill		----	----	----	----	Chrysotile Present	NA

SciLab Job#: 202071658

Client Name: GLOMAR CORP.

Page 2 of 2

Table I

Summary of Bulk Asbestos Analysis Results


59 Maiden Lane, NYC, 8th Floor/ Window Sills/ Wipes - Amended Report 07/12/02

SciLab Sample #	Client Sample# Location	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	Asbestos by PLM/DS	Asbestos by TEM
10	015 Pat Hussy's Office Window Sill		----	----	----	----	Chrysotile Present	NA

Analyzed by: Richard Bailey  : Date Analyzed 7/9/02

Quantitative Analysis (Semi/Full): Bulk Asbestos Analysis - PLM by EPA 600/M4-82-020 per 40 CFR (NVLAP Lab#200546-0); TEM (Semi/Full) by EPA 600/R-93/116 (not covered by NVLAP Bulk accreditation); or ELAP 198.1/198.4 for New York samples (NYSDOH ELAP#11480); NAD = no asbestos detected during a quantitative analysis; NA = not analyzed; Trace = <1%; Quantitation for beginning weights of <0.1 grams should be considered as qualitative only; Qualitative Analysis: Asbestos analysis results of "Present" or "NVA = No Visible Asbestos" represents results for Qualitative PLM or TEM Analysis only (no accreditation coverage available from any regulatory agency for qualitative analyses); AIHA Lab#102843.

Warning Note: PLM limitation, only TEM will resolve fibers <0.25 micrometers in diameter. TEM bulk analysis is representative of the fine grained matrix material and may not be representative of non-uniformly dispersed debris for which PLM evaluation is recommended (i.e. soils and other heterogenous materials).

Reviewed By: 



SCIENTIFIC LABORATORIES, INC.

117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

202071658

Company: Glomar		Address:		P.O.#:			
Project Information		Analysis		Turnaround Time			
Name: 59 MAIDEN LANE, NYC 8TH FL (WIPES)		Type	6-8hr	12hr	24hr		
Number:		TEM/AHERA					
Manager:		TEM/Level II					
Site (City/State):		TEM/Chatfield					
		TEM/Dust					
		TEM/Water					
		PCM					
		PLM		X			
		Lead					
		Other					
Results to: Office		Return Samples		Yes X	No — Hold.		
Invoice to:		Phone		Fax 914/345-2170			
Written report to: (WIPES)		Do NOT DISCARD		Fax 914/345-2170			
COMMENTS: From Window Sills - UNTIL - Notice		Pager					
Sample I.D.	Sample Location	Start Time	Stop Time	Total Time	Liters/Min	Air Volume	Date Collected
* C6	MR HYDEN BLADES OFFICE - WINDOW SILL						7-8
* C7	SYLVIA FRELANDS OFFICE - WINDOW SILL						7-8
* C8	G-KRAUS FRIEDBERGS OFFICE WINDOW SILL						7-8
C9	GREGORY TATARS OFFICE WINDOW SILL						7-8
C10	CORNER AREA - WINDOW SILL						7-8
C11	MR VINCENTS OFFICE - WINDOW SILL						7-8
C12	WINDOW SILL ADJ COPY MACHINE						7-8
C13	JOHN ST WINDOW RANDOM WINDOW SILL						7-8
C14	JOHN ST - SIDE - LAST WINDOW SILL						
C15	PAT HUSSYS OFFICE WINDOW SILL						
Relinquished By (Signature)		Date		Received By (Signature)		Date	
		7/8/03		L.C.		7/8	

**SCIENTIFIC LABORATORIES, INC.**

117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos Report

GLOMAR CORP.
Attn: Glenn Ferdico
35 East Main St.
Elmsford, NY 10523

Date Received 07/08/2002 SciLab Job No. 202071659

Date Examined 07/09/2002 P.O. # Ferdico

Page 1 of 3

RE: 59 Maiden Lane NYC - 9th Floor - (AMENDED REPORT
7/29/02)

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
026	202071659-01	Yes	<1.%
Location: From John St. Side- Middle Window Sill			
Description: , Heterogeneous, Dust Wipe			
Asbestos Types: Chrysotile Present			
Other Material:			
027	202071659-02	No	NVA
Location: Corridor- 7th Window From Williams Side- John St.			
Description: , Heterogeneous, Dust Wipe			
Asbestos Types:			
Other Material: NAD			
028	202071659-03	Yes	<1.%
Location: Ivan Carrols Office			
Description: , Heterogeneous, Dust Wipe			
Asbestos Types: Chrysotile Present			
Other Material:			
029	202071659-04	Yes	<1.%
Location: John St. Side Adj. To Corridor			
Description: , Heterogeneous, Dust Wipe			
Asbestos Types: Chrysotile Present			
Other Material:			
030	202071659-05	Yes	<1.%
Location: Corner Window- John St. & Williams			
Description: , Heterogeneous, Dust Wipe			
Asbestos Types: Chrysotile Present			
Other Material:			



SCIENTIFIC LABORATORIES, INC.

117 EAST 30TH STREET
NEW YORK, NY 10016
TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos Report

GLOMAR CORP.
Attn: Glenn Ferdico
35 East Main St.
Elmsford, NY 10523

Date Received 07/08/2002 SciLab Job No. 202071659
Date Examined 07/09/2002 P.O. # Ferdico
Page 2 of 3
RE: 59 Maiden Lane NYC - 9th Floor - (AMENDED REPORT
7/29/02)

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
031	202071659-06	Yes	<1.0%
Location: Last Window- Rightside John St.			
Description: , Heterogeneous, Dust Wipe			
Asbestos Types: Chrysotile Present			
Other Material:			
032	202071659-07	Yes	<1.0%
Location: Mr. Leo Coles Office Esq.			
Description: , Heterogeneous, Dust Wipe			
Asbestos Types: Chrysotile Present			
Other Material:			
033	202071659-08	Yes	<1.0%
Location: AA Stahl Esq. Office			
Description: , Heterogeneous, Dust Wipe			
Asbestos Types: Chrysotile Present			
Other Material:			
034	202071659-09	Yes	<1.0%
Location: Random Window Williams Side			
Description: , Heterogeneous, Dust Wipe			
Asbestos Types: Chrysotile Present			
Other Material:			
035	202071659-10	Yes	<1.0%
Location: Window Towards Bway- On John St. Side			
Description: , Heterogeneous, Dust Wipe			
Asbestos Types: Chrysotile Present			
Other Material:			



SCIENTIFIC LABORATORIES, INC.

117 EAST 30TH STREET
NEW YORK, NY 10016
TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos Report

GLOMAR CORP.
Attn: Glenn Ferdico
35 East Main St.
Elmsford, NY 10523

Date Received 07/08/2002 SciLab Job No. 202071659

Date Examined 07/09/2002 P.O. # Ferdico

Page 3 of 3

RE: 59 Maiden Lane NYC - 9th Floor - (AMENDED REPORT
7/29/02)

Reporting Notes:

Analyzed by: Richard Bailey

Richard Bailey
*NAD/NSD = no asbestos detected; NA = not analyzed; NA/PS = not analyzed / positive stop; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #200546-0) and ELAP PLM Analysis Protocol 198.1 for New York samples (NYSDOH ELAP Lab # 11480); Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). National Institute of Standards and Technology Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This PLM report relates ONLY to the items tested. AIHA# 102843; VT Cert# AL016055

Reviewed By:

Glenn Ferdico

Sub Job#: 202071659
Client Name: GLOMAR CORP.

Page 1 of 2

Table I
Summary of Bulk Asbestos Analysis Results
59 Maiden Lane, NYC/ 9th Floor - Amended Report 07/12/02

SciLab Sample #	Client Sample# Location	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	Asbestos by PLM/DS	Asbestos by TEM
01	026 From John St. Side- Middle Window Sill		----	----	----	----	Chrysotile Present	Chrysotile Present
02	027 Corridor- 7th Window From Williams Side- John St.		----	----	----	----	NVA	NA
03	028 Ivan Carrols Office		----	----	----	----	Chrysotile Present	NA
04	029 John St. Side Adj. To Corridor		----	----	----	----	Chrysotile Present	NA
05	030 Corner Window- John St. & Williams		----	----	----	----	Chrysotile Present	NA
06	031 Last Window- Rightside John St.		----	----	----	----	Chrysotile Present	NA
07	032 Mr. Leo Coles Office Esq.		----	----	----	----	Chrysotile Present	NA
08	033 AA Stahl Esq. Office		----	----	----	----	Chrysotile Present	NA
09	034 Random Window Williams Side		----	----	----	----	Chrysotile Present	NA


1

Sub Job#: 202071659
Client Name: GLOMAR CORP.

Page 2 of 2


Table I
Summary of Bulk Asbestos Analysis Results
59 Maiden Lane, NYC/ 9th Floor - Amended Report 07/12/02

SciLab Sample #	Client Sample# Location	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	Asbestos by PLM/DS	Asbestos by TEM
10	035 Window Towards Bway- On John St. Side		----	----	----	----	Chrysotile Present	NA

Analyzed by: Jonathan M. Teda ; Date Analyzed 7/9/02

Quantitative Analysis (Semi/Full): Bulk Asbestos Analysis - PLM by EPA 600/M4-82-020 per 40 CFR (NVLAP Lab#200546-0); TEM (Semi/Full) by EPA 600/R-93/116 (not covered by NVLAP Bulk accreditation); or ELAP 198.1/198.4 for New York samples (NYSDOH ELAP#11480); NAD = no asbestos detected during a quantitative analysis; NA = not analyzed; Trace = <1%; Quantitation for beginning weights of <0.1 grams should be considered as qualitative only; Qualitative Analysis: Asbestos analysis results of "Present" or "NVA = No Visible Asbestos" represents results for Qualitative PLM or TEM Analysis only (no accreditation coverage available from any regulatory agency for qualitative analyses); AIHA Lab#102843.

Warning Note: PLM limitation, only TEM will resolve fibers <0.25 micrometers in diameter. TEM bulk analysis is representative of the fine grained matrix material and may not be representative of non-uniformly dispersed debris for which PLM evaluation is recommended (i.e. soils and other heterogeneous materials).

Reviewed By: 



SCIENTIFIC LABORATORIES, INC.

117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

202071659

Company: Glomar		Address:							P.O.#:	
Project Information		Analysis		Turnaround Time					Air Filter	
Name: 59 MAIDEN LANE, NYC QTR		Type	6-8hr	12hr	24hr	48hr	72hr	Sday	Other	Information
		TEM/AHERA								MCE
		TEM/Level II								PC
		TEM/Chatfield								25mm
		TEM/Dust								37mm
		TEM/Water								0.45um
Number:	PCM									0.80um
Manager:	PLM									Other:
Site (City/State):	Lead									
	Other									
Results to: QTR					Return Samples Yes ☒ No ☒ Hold					
Invoice to:					Phone 718-385-2745					
Written report to:					Fax 718-385-2745					
COMMENTS: Wipes from Window Sills.					Pager 1					
Sample I.D.	Sample Location	DO NOT	Start Time	Stop Time	Total Time	Liters/Min	Air Volume	Date Collected		
	Hold Samples - Dispute									
026	From John St Side - Middle Window Sill							7-8		
027	Corridor - 1st Window from Williams Side - John St									
028	IVAN CARROL'S OFFICE -									
029	John St Side Adj to Corridor									
030	Corner Window - John St + Williams.									
031	LAST Window - Right Side John St									
032	Mr Leo Coles OFFICE ESQ.									
033	AA STAHL ESQ'S OFFICE									
034	RANDOM Window Williams Side									
035	Window Towards BWAY - on John St Side									
Relinquished By (Signature)		Date		Received By (Signature)		Date				
		7/8/03				2315		7/8		

Sc Job#: 202071656
Client Name: GLOMAR CORP.

Page 1 of 2

Table I
Summary of Bulk Asbestos Analysis Results
59 Maiden Lane, NYC/ 9th Floor/ Wipes

SciLab Sample #	Client Sample# Location	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	Asbestos by PLM/DS	Asbestos by TEM
01	16 From Window Sill Random Center		----	----	----	----	Chrysotile Present	NA
02	17 Staircase C/ Window Sill		----	----	----	----	Chrysotile Present	NA
03	18 Mary Darosa's Office Window Sill		----	----	----	----	Chrysotile Present	NA
04	19 Jim Marcrow's Office		----	----	----	----	Chrysotile Present	NA
05	20 From John St. End Window		----	----	----	----	NVA	NVA
06	21 From Corridor Adj. Desk		----	----	----	----	Chrysotile Present	NA
07	22 6th Window From Bway		----	----	----	----	NVA	NA
08	23 Jim Savage Office Sill		----	----	----	----	Chrysotile Present	NA
09	24 Along Corridor Of Windows		----	----	----	----	NVA	NA


Sc Job#: 202071656
Client Name: GLOMAR CORP.

Page 1 of 2

Table I **Summary of Bulk Asbestos Analysis Results**


59 Maiden Lane, NYC/ 9th Floor/ Wipes

SciLab Sample #	Client Sample# Location	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	Asbestos by PLM/DS	Asbestos by TEM
10	25 Corner Of John St. & Williams Window Sill		---	---	---	---	Chrysotile Present	NA

Analyzed by: Jonathan M. Teda  : Date Analyzed 7/9/02

Quantitative Analysis (Semi/Full): Bulk Asbestos Analysis - PLM by EPA 600/M4-82-020 per 40 CFR (NVLAP Lab#200546-0); TEM (Semi/Full) by EPA 600/R-93/116 (not covered by NVLAP Bulk accreditation); or ELAP 198.1/198.4 for New York samples (NYSDOH ELAP#11480); NAD = no asbestos detected during a quantitative analysis; NA = not analyzed; Trace = <1%; Quantitation for beginning weights of <0.1 grams should be considered as qualitative only; Qualitative Analysis: Asbestos analysis results of "Present" or "NVA = No Visible Asbestos" represents results for Qualitative PLM or TEM Analysis only (no accreditation coverage available from any regulatory agency for qualitative analyses); AIHA Lab#102843.

Warning Note: PLM limitation, only TEM will resolve fibers <0.25 micrometers in diameter. TEM bulk analysis is representative of the fine grained matrix material and may not be representative of non-uniformly dispersed debris for which PLM evaluation is recommended (i.e. soils and other heterogenous materials).

Reviewed By: 



SCIENTIFIC LABORATORIES, INC.

117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

202071656

Company: Glomar		Address:		P.O.#:			
Project Information		Analysis		Turnaround Time			
Name: 59 MAIDEN LANE, NYC 9TH F (WIPES)		Type	6-8hr	12hr	24hr		
Number:		PCM					
Manager:		PLM					
Site (City/State):		Lead					
		Other					
Results to: Office		Return Samples		Yes ☒ No ☐ - Hold			
Invoice to:		Phone		212 345-2170			
Written report to:		Fax					
COMMENTS: WIPES From Window Sills -		Pager		1			
Sample I.D.	Sample Location	Start Time	Stop Time	Total Time	Liters/Min	Air Volume	Date Collected
016	From Window Sill - Random Center						7-8
017	STAIRCASE @ Window Sill						↓
018	MARY DAROSA'S OFFICE Window Sill						
019	Jim MARCROWS OFFICE -						
020	From JOHN ST - END WINDOW						
021	From Corridor Adj DESKS.						
022	6th Window from Buggy.						
023	Jim SAVAGES OFFICE Sill						
024	Along Corridor of Windows						
025	Corner of John St + Williams Window Sill						
Requisitioned By (Signature)		Date		Received By (Signature)		Date	
		7/8/02				7/8	

Sub Job#: 202071657

Page 2 of 2

Client Name: GLOMAR CORP.

Table I
Summary of Bulk Asbestos Analysis Results
 59 Maiden Lane, NYC 14th Floor/ Window Sills

SciLab Sample #	Client Sample# Location	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	Asbestos by PLM/DS	Asbestos by TEM
01	036 John St.- Far Left Side		----	----	----	----	Chrysotile Present	NA
02	037 John St.- 6th Window From Broadway		----	----	----	----	Amosite Present Chrysotile Present	NA
03	038 John St.- 8th Window From Broadway		----	----	----	----	Anthophyllite Present Chrysotile Present	NA
04	039 John St.- 12th Window From Broadway		----	----	----	----	Chrysotile Present	NA
05	040 William St. Side Last Window		----	----	----	----	Chrysotile Present	NA
06	041 William St. Side 2nd Window Off John St.		----	----	----	----	Chrysotile Present	NA
07	042 William St. Side 4th Window Off John St.		----	----	----	----	Chrysotile Present	NA
08	043 Random -John St. Northeast		----	----	----	----	Chrysotile Present	NA
09	044 Random -John St. Northwest		----	----	----	----	Anthophyllite Present Chrysotile Present	NA

1

Sub Job#: 202071657
Client Name: GLOMAR CORP.

Page 2 of 2


Table I
Summary of Bulk Asbestos Analysis Results
59 Maiden Lane, NYC 14th Floor/ Window Sills

SciLab Sample #	Client Sample# Location	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	Asbestos by PLM/DS	Asbestos by TEM
10	045 Center Of John St.		----	----	----	----	Chrysotile Present	NA

Analyzed by: John P. Koubiadis ; Date Analyzed 7/9/02

Quantitative Analysis (Semi/Full): Bulk Asbestos Analysis - PLM by EPA 600/M4-82-020 per 40 CFR (NVLAP Lab#200546-0); TEM (Semi/Full) by EPA 600/R-93/116 (not covered by NVLAP Bulk accreditation); or ELAP 198.1/198.4 for New York samples (NYSDOH ELAP#11480); NAD = no asbestos detected during a quantitative analysis; NA = not analyzed; Trace = <1%; Quantitation for beginning weights of <0.1 grams should be considered as qualitative only; Qualitative Analysis: Asbestos analysis results of "Present" or "NVA = No Visible Asbestos" represents results for Qualitative PLM or TEM Analysis only (no accreditation coverage available from any regulatory agency for qualitative analyses); AIHA Lab#102843.

Warning Note: PLM limitation, only TEM will resolve fibers <0.25 micrometers in diameter. TEM bulk analysis is representative of the fine grained matrix material and may not be representative of non-uniformly dispersed debris for which PLM evaluation is recommended (i.e. soils and other heterogenous materials).

Reviewed By: 



SCIENTIFIC LABORATORIES, INC.

117 EAST 30TH STREET

NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

202071657

Company: <u>Stroman</u>		Address:		P.O.#:			
Project Information		Analysis		Turnaround Time			
Name: <u>59 MAIDEN</u> <u>14TH FL (WIPES)</u>		Type	6-8hr	12hr	24hr		
Number:		TEM/AHERA					
Manager:		TEM/Level II					
Site (City/State):		TEM/Chatfield					
		TEM/Dust					
		TEM/Water					
		PCM					
		PLM					
		Lead					
		Other					
Results to: <u>STF</u>		Return Samples		Yes	No		
Invoice to:		Phone		<u>914/345-2120</u>			
Written report to:		Fax		<u>914/345-2120</u>			
COMMENTS: <u>Wipes From Window Sills.</u>		Pager		<u>1</u>			
Sample I.D.	Sample Location	Start Time	Stop Time	Total Time	Liters/Min	Air Volume	Date Collected
036	John St - Far Left Side						7-8
037	John St @ 6th Window from Bway						
038	John St 8th Window from Bway						
039	John St 12th Window from Bway						
040	William St Side Last Window						
041	William St Side 2nd Window off John St						
042	William St Side 4th Window off John St						
043	Pandora - John St - Northeast						
044	Pandora - John St - Northwest						
045	Center of John St.						
Relinquished By (Signature)		Date		Received By (Signature)		Date	
<u>[Signature]</u>		7/8/02		<u>[Signature]</u>		7/8	

