



THE CITY OF NEW YORK OFFICE OF THE COMPTROLLER
1 CENTRE STREET, NEW YORK, N.Y. 10007-2341

William C. Thompson, Jr.
COMPTROLLER

826 - 147

Date: 8/23/2005
RE: Departmental Report Request
Name: ANTONIO VITTORIOSO
Claim number: 2005PD004599
Occurrence date: 12/29/2004
Agency: DEPARTMENT OF ENVIRONMENTAL
PROTECTION(DEP)

S. PENNER, LEGAL, D.E.P. L/O: BKLYN -
35 BAY 7 S
SEE HANSEN SEARCH. IS IT POSSIBLE TO
HAVE SUCH
DAMAGE WHEN H2O IS TURNED BACK ON?

First request: 05/24/2005

Please send all departmental reports and/or information that you may have regarding the allegations made in the attached notice of claim.

In the event that a contractor and/or insurance is involved please consider this a priority request and supply the relevant information as soon as possible.

If you have any questions concerning this request please call the number below.

MELANIE COLMAN *(M2C1)*
Bureau of Law & Adjustment

PROPERTY DAMAGE DIVISION

PHONE: *212-669-8754*

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Inspection Detail

Report Date 03/04/2005 10:25 AM

Submitted By

Page 1

Service # 983162

Problem WA1 POSSIBLE WATER MAIN BREAK (USE COMMENTS)

Address 52 BAY 7 ST 3

Cross Streets 86 ST
BENSON AVE

Compass Direction

Building ID 3166001 Block 06357 Lot 0056 CMBD 311

Location

Area Sub-Area 311 BKLYN COMMUNITY BOARD 11 District Parcel

# of Calls	1	Duration of Call	00:00	Call Date	12/23/2004 12:12
Template Type				A/P #	
Taken By	6311	SPIEGEL, ELVIRA		Source	
Responsibility	WMK	WATER MAINTENANCE - BROOKLYN		Priority	Z DEFAULT PRIORITY
Scheduled Date	12/27/2004 02:00			Start Date	12/23/2004 21:25
Inspector	1155	AMBROSINO, ALFRED		Inspection Date	12/27/2004 02:00
Due Date				☐ No Work Orders Required	
Resolution Code	WMR	MAIN RESTORED TO SERVICE		Resolution Date	12/29/2004 23:00

Asset

Avg Insp Duration

Avg Insp Days	0
Avg Insp Hrs	0
Avg Insp Mins	0

Service Request Progress

Schedule By
Start By
Complete By
Resolve By

☐ Customer Contact Requested

Budget #

Map #

Project #

Title MR
Last Name MINUTELLO
First Name, MI R,
Address

City, State/Province, ZIP/PC

☐ Foreign

Day Phone (718)833-5561 x

Caller Comments water coming from wall also water flooding basement at 50 bay 7 st

Reference #

Evening Phone

Call Date 12/23/2004 12:12

There are no calls for this service number

Problem Comments 52 BAY 7ST 86ST/BENSON AVE

12/23/04 2125-2140 AMBROSINO/TUCCIARELLI TR#272

FOUND FRESH DIRT PUSHED UP IN STREET S/W SIDE W/S/O BAY 7ST 200' N/O BENSON AVE I/F/O 50. N/E 50, 52,48,49. HDYT I/F/O 46 HAS NOISE
SIGN ON DOOR AT 50 FOR DEP TO CALL TONY (718)232-1214 CALLED # N/A RI
UD DD 12/27/04

12/24/04 1100-1155 ESPOSITO/BELLAFIGLIO TR#260

AT LOC FOUND 50 GETTING MED LK IN PIT-CK LIVE HAS NOISE CK 45,49,46 ALL HAVE NOISE HDYT HAS SL/NOISE RECC SUPV TO GEOPHONE
FOR SPOT TO DIG. RI
UD DD 12/27/04

12/27/04 0200-0240 ALLEN/PUGLISI TR#272

MET SUPV GEOPHONE AREA ON BAY 7TH + 86ST RECC DIG OVER MAIN 5FT S ON BLDG LINE 6FT EOW BAY 7TH ST. AS PER SUPV.
UD DD 12/27/04

There are no assets

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

COMPLETED Water Main Work Order

Report Date 03/04/2005 10:25 AM

Submitted By

Page 1

Work Order # 989295 Activity WA01B REPAIR BROKEN MAIN

Location/Address 52 BAY 7 ST 3
11228

Cross Streets 86 ST
BENSON AVE

Compass Direction

Building ID 3166001 Block 06357 Lot 0056 CMBD 311

Main ID WV 311 To WND DUMMY

Qualifier
Area 3 BROOKLYN District
Sub-area 311 BKLYN COMMUNITY BOARD 11 Location
Map #

Main Line Type	Diameter	0.00	Length	0.00
Pipe Type	Depth	0.00	Frost Depth	0.00
Pipe Class	Pipe Schedule		Description	
Joint Type	Joint Length	0.00	Locator Wire	No
Dir From Endpt1	Friction Factor	0.000	Corrosion Factor	0.000
Dir From Endpt2	Soil Type			
Pressure Zone	Manufacturer			
Service Status				
X Coord				
Y Coord	As Built		Parcel	
Z Coord	Date Installed		Service Connects	0
Ownership	Surface Cover			
Budget #				

Initiated By 1105 FRANTZ ALEXIS Initiated Date 12/27/2004 Scheduled
Assigned To 6554 JOHN THOMAS Service # 983162 Due

Authorization	1101	ALEXANDER, BARRY		
Budget #				
Crew	W3	WATER - 3 LABORERS		
Maint Type				
Priority				
Problem	WMC	CIRCULAR BREAK		
Project			Out of Service	☐
Source			Potential Service Request	☐
Last Activity	WA01B	REPAIR BROKEN MAIN	Last Activity Completed	02/16/2005
WO Responsibility	WRK			

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

COMPLETED Water Main Work Order

Report Date 03/04/2005 10:25 AM

Submitted By

Page 2

Work Order #	989295	Activity	WA01B	REPAIR BROKEN MAIN
--------------	--------	----------	-------	--------------------

Work Order Comments

52 BAY 7ST 86ST/BENSON AVE

12/23/04 2125-2140 AMBROSINO/TUCCIARELLI TR#272

FOUND FRESH DIRT PUSHED UP IN STREET S/W SIDE W/S/O BAY 7ST 200' N/O BENSON AVE I/F/O 50. N/E 50, 52, 48, 49. HDYT I/F/O 46 HAS
NOISE SIGN ON DOOR AT 50 FOR DEP TO CALL TONY (718)232-1214 CALLED # N/A RI
UD DD 12/27/04

12/24/04 1100-1155 ESPOSITO/BELLAFIORE TR#260

AT LOC FOUND 50 GETTING MED LK IN PIT-CK LIVE HAS NOISE CK 45, 49, 46 ALL HAVE NOISE HDYT HAS SL/NOISE RECC SUPV TO GEOPHONE
FOR SPOT TO DIG. RI
UD DD 12/27/04

12/27/04 0200-0240 ALLEN/PUGLISI TR#272

MET SUPV GEOPHONE AREA ON BAY 7TH + 86ST RECC DIG OVER MAIN (8") 5FT S ON BLDG LINE 6FT EOW BAY 7TH ST. AS PER SUPV.
UD DD 12/27/04

CHANGED ACTIVITY FROM WA06J TO WA01B.

UD BA 12/30/04

12/29/04 15:00-23:00 24 M/HRS

THOMAS SADALLAH, WILLIAMS, BROWN

SET UP T.S.Z. GEOPHONED AREA, MADE TEST HOLE, GOT A GOOD PUSH. OPENED EXCAV. TO 5X3, REMOVED DEBRIS. UNABLE TO BEAT
WATER (N-15 ASSISTED IN S/D). MADE EMERGENCY NOTIFICATION. DUG DOWN CONTROLLING WATER WITH PUMP. EXPOSED 8" CIRCULAR
BREAK. CLEANED AROUND MAIN, INSTALLED SHORT 8"S/S CLAMP. RESTORED WATER: NO LEAK. B/F, TAMED, B/T. READY FOR H.P.
U/D MR 12/30/04 LOG #5948