



TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☒ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

8840

1 Client: DEP	2. Project Name DEP CLEAN-UP	3. Project # 229060002	4. Project Monitor: Paul Pavlizi	4c. Rotameter Number: HP-097
5. Date: 9-15-02	2a. Project Address 125 Cedar ST	3a. Task # 2	4a. Air Sampler: Ruben HGO 3112	
6. Abatement Location: From 1st FL to Penthouse	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture Nuclepore Lot # _____	9. Type: a. ☐ Background b. ☐ Pre-Abate	c. ☒ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
				Field Blank									
				Field Blank									
16			✓	on hallway Penthouse	10:37	1437	240	10.0	6.0	6.0	2400		
17			✓	on hallway 22 nd FL	10:38	1438	240	10.0	6.0	6.0	2400		
18			✓	on hallway 11 th FL	10:40	1440	240	10.0	6.0	6.0	2400		
19			✓	on hallway 10 th FL	10:41	1441	240	10.0	6.0	6.0	2400		
20			✓	on hallway 9 th FL	10:43	1443	240	10.0	6.0	6.0	2400		
21			✓	on hallway 8 th FL	10:45	1445	240	10.0	6.0	6.0	2400		
22			✓	on hallway 7 th FL	10:48	1448	240	10.0	6.0	6.0	2400		
23			✓	on hallway 6 th FL	10:50	1450	240	10.0	6.0	6.0	2400		
24			✓	on hallway 5 th FL	10:52	1452	240	10.0	6.0	6.0	2400		
25			✓	on hallway 4 th FL	10:54	1454	240	10.0	6.0	6.0	2400		
26			✓	on hallway 3 rd FL	10:55	1455	240	10.0	6.0	6.0	2400		
27			✓	in front clean Rm Dec	10:56	1456	240	10.0	6.0	6.0	2400		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
R. Acosta	FD	9/16/02	8:00

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	ATL-JEM		23. Date:	24. Time:
a. Analyzed By:	R. D. King		9/1/02	11:00
b. QC By:				
c. Lab Batch #:				
28. Comments:				

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079
Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

 Page 2 of 4
TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: DEP

2. Project Name: DEP CLEAN-UP 3. Project #: 22906-0002 4. Project Monitor: Paul Padilla 4c. Rotameter Number: HP-097

2a. Project Address: 125 Cedar St 3a. Task #: 2 4a. Air Sampler: Ruben Acosta

5. Date: 9-15-02 6. Abatement Location: From 1st FL. To Penhouse

7. ☐ PCM (0.8 micron MCE) 8. ☒ TEM (0.45 micron MCE) 9. Type: c. ☒ Abatement f. ☐ Environmental

Cassette/Filter Manufacture _____ Cassette/Filter Manufacture: Nuclepore a. ☐ Background d. ☐ Post-Abate g. ☐ Ambient

Lot # _____ Lot # _____ b. ☐ Pre-Abate e. ☐ OSHA h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
				Field Blank									
				Field Blank									
				inside waste room	10:58	14:58	240	10.0	10	10	2400		
28				Hallway PENHOUSE	14:37	18:37	240	10	10	10	2400		
29				" 12 FL	14:38	18:38	240	10	10	10	2400		
30				" 11 FL	14:40	18:40	240	10	10	10	2400		
31				" 10 FL	14:41	18:41	240	10	10	10	2400		
32				" 9 FL	14:43	18:43	240	10	10	10	2400		
33				" 8 FL	14:45	18:45	240	10	10	10	2400		
34				" 7 FL	14:48	18:48	240	10	10	10	2400		
35				" 6 FL	14:50	18:50	240	10	10	10	2400		
36				" 5 FL	14:52	18:52	240	10	10	10	2400		
37				" 4 FL	14:54	18:54	240	10	10	10	2400		
38													

CHAIN OF CUSTODY

18. Relinquished By: R. Acosta 19. Received By: JD 20. Date: 9/16/02 21. Time: 8 am

22. Lab Name: ATC-TEM 23. Date: 9/17/02 24. Time: 14:00

a. Analyzed By: R. Rey b. QC By: _____ c. Lab Batch #: _____

25. Microscope Make/Serial #: _____
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

26. ATC Project Manager: Fred Burkhardt 27. Result To: _____
 Beeper/Phone #'s: _____

28. Comments: _____

Analysis Methodology
 PCM - NIOSH 7400A
 TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

 Page 3 of 4
 TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

Client: <u>DEP</u>	2. Project Name: <u>DEP CLEAN UP</u>	3. Project #: <u>1522806</u>	4. Project Monitor: <u>C Johnson</u>
Date: <u>1502</u>	2a. Project Address: <u>125 CEDAR ST</u>	3a. Task #: <u>0002</u>	4a. Air Sampler: <u>"</u>
6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type: ☒ Abatement
	Cassette/Filter Manufacture _____	Cassette/Filter Manufacture _____	d. ☐ Post-Abate
	Lot # _____	Lot # _____	e. ☐ OSHA
			f. ☐ Environmental
			g. ☐ Ambient
			h. ☐ Other

DAILY AIR SAMPLE RECORD

0. Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
39				Field Blank									
40				Field Blank									
41				Highway 3 FL	1455	1855	240	10	10	10	2400		
42				Highway Cleanup	1456	1856	240	10	10	10	2400		
43				Highway Waste	1458	1858	240	10	10	10	2400		
44				" PCHOUSE	1837	2237	240	10	10	10	2400		
45				" 12 FL	1839	2239	240	10	10	10	2400		
46				" 11 FL	1840	2240	240	10	10	10	2400		
47				" 10 FL	1841	2241	240	10	10	10	2400		
48				" 9 FL	1843	2243	240	10	10	10	2400		
49				" 8 FL	1845	2245	240	10	10	10	2400		
50				" 7 FL	1848	2248	240	10	10	10	2400		
51				" 6 FL	1850	2250	240	10	10	10	2400		
52				" 5 FL	1852	2252	240	10	10	10	2400		

CHAIN OF CUSTODY

8. Relinquished By: <u>[Signature]</u>	19. Received By: <u>JD</u>	20. Date: <u>9/16/02</u>	21. Time: <u>8 am</u>
9. _____	20. _____	21. _____	22. _____
10. _____	21. _____	22. _____	23. _____

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ATC TEM</u>	23. Date: <u>9/17/02</u>	24. Time: <u>14:00</u>	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <u>[Signature]</u>			
b. QC By: _____			
c. Lab Batch #: _____			Analysis Methodology PCM - NIOSH 7400A TEM - AHERA
28. Comments: _____			

6. ATC Project Manager: <u>[Signature]</u>	27. Result To: _____
	Beeper/Phone #'s: _____

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 4 of 4

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: <u>DLP</u>		2. Project Name: <u>DER CLEANUP</u>		3. Project #: <u>1522906</u> <u>0062</u>		4. Project Monitor: <u>C. Johns</u>		4c. Rotameter Number: <u>CJ5001</u>	
		2a. Project Address: <u>128 CEDAR ST</u>		3a. Task #: <u>0002</u>		4a. Air Sampler: <u>---</u>			
5. Date: <u>1-15-02</u>		6. Abatement Location:		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☒ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
53				Field Blank									
				Field Blank <u>CLOSE BLANK</u>									
54				<u>Highway</u> <u>4 FL</u>	<u>1854</u>	<u>2254</u>	<u>240</u>	<u>10</u>	<u>10</u>	<u>10</u>	<u>2400</u>		
55				<u>Highway</u> <u>3 FL</u>	<u>1155</u>	<u>2255</u>	<u>240</u>	<u>10</u>	<u>10</u>	<u>10</u>	<u>2400</u>		
56				<u>Highway D/Car</u> <u>CYCLE RM</u>	<u>1156</u>	<u>2256</u>	<u>240</u>	<u>10</u>	<u>10</u>	<u>10</u>	<u>2400</u>		
57				<u>Highway D/Car</u> <u>WASTE</u>	<u>1858</u>	<u>2258</u>	<u>240</u>	<u>10</u>	<u>10</u>	<u>10</u>	<u>2400</u>		

CHAIN OF CUSTODY

18. Relinquished By: <u>[Signature]</u>	19. Received By: <u>[Signature]</u>	20. Date: <u>9/16/02</u>	21. Time: <u>8:00</u>
I			
II			
III			

16. ATC Project Manager: <u>[Signature]</u>	27. Result To: _____ Beeper/Phone #'s _____
---	--

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ATC-TEM</u>	23. Date: <u>9/17/02</u>	24. Time: <u>14:00</u>	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <u>[Signature]</u>			
b. QC By: _____			
c. Lab Batch #: _____			Analysis Methodology PCM - NIOSH 7400A TEM - AHERA
28. Comments: _____			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)