



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: DEP	2. Project Name DEP Clean-up	3. Project # 15-22506-0002	4. Project Monitor: E. Lemanovich	4c. Rotameter Number: SD-006
2a. Project Address 125 Cedar St. NY		3a. Task # 00002		
5. Date: 9.18.02	6. Abatement Location: Around building	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # 916	9. Type: a. ☐ Background b. ☐ Pre-Abate
		c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA		f. ☐ Environmental g. ☐ Ambient h. ☒ Other Cleaning

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
01				Field Blank									
02				Field Blank									
03				Field Blank									
04			✓	In front of building	06:20	10:10	230	10	10	10	2300		
05			✓	---	06:21	10:11	230	10	10	10	2300		
06			✓	---	06:22	10:12	230	10	10	10	2300		
07			✓	---	06:23	10:13	230	10	10.5	10.25	2357.5		
08			✓	In back of building	06:30	10:20	230	10	10	10	2300		
09			✓	---	06:31	10:21	230	10	10	10	2300		
10			✓	---	06:32	10:22	230	10	10	10	2300		
11			✓	---	06:33	10:23	230	10	10	10	2300		
12			✓	---	06:34	10:24	230	10	10	10	2300		
13			✓	Hallway, clean room of decon	06:39	10:29	230	10	10	10	2300		
14			✓	2 nd Floor	06:40	10:30	230	10	10	10	2300		

CHAIN OF CUSTODY

18. Relinquished By: E. Lemanovich	19. Received By: JR	20. Date: 9.18.02	21. Time: 16:00
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC - TEM	23. Date: 9/20/02	24. Time: 16:00	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: RR			Analysis Methodology PCM - NIOSH 7400A TEM - AHERA
b. QC By:			
c. Lab Batch #:			
28. Comments:			

26. ATC Project Manager: F. Burkhardt	27. Result To: _____ Beeper/Phone #'s _____
---	--

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: DEP 2. Project Name: DEP Clean-up 3. Project #: 15-22906-0002 4. Project Monitor: _____
 2a. Project Address: 125 Cedar St NY 3a. Task #: 55002 4a. Air Sampler: E. Lemanovich 4c. Rotameter Number: \$4-006

5. Date: 9.18.02 6. Abatement Location: Around building 7. ☐ PCM (0.8 micron MCE) 8. ☒ TEM (0.45 micron MCE)
 Cassette/Filter Manufacture _____ Cassette/Filter Manufacture _____
 Lot # _____ Lot # 916

9. Type: c. ☐ Abatement f. ☐ Environmental
 a. ☐ Background d. ☐ Post-Abate g. ☐ Ambient
 b. ☐ Pre-Abate e. ☐ OSHA h. ☒ Other cleaning

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
				Field Blank									
				Field Blank									
<u>15</u>			<u>✓</u>	<u>Restaurant Clean room of deco</u>	<u>08:45</u>	<u>11:33</u>	<u>168</u>	<u>10</u>	<u>10</u>	<u>10</u>	<u>1680</u>		
<u>16</u>			<u>✓</u>	<u>In front of building</u>	<u>10:10</u>	<u>14:10</u>	<u>240</u>	<u>10</u>	<u>10</u>	<u>10</u>	<u>2400</u>		
<u>17</u>			<u>✓</u>	<u>— — —</u>	<u>10:11</u>	<u>14:11</u>	<u>240</u>	<u>10</u>	<u>10</u>	<u>10</u>	<u>2400</u>		
<u>18</u>			<u>✓</u>	<u>— — —</u>	<u>10:12</u>	<u>14:12</u>	<u>240</u>	<u>10</u>	<u>10</u>	<u>10</u>	<u>2400</u>		
<u>19</u>			<u>✓</u>	<u>— — —</u>	<u>10:13</u>	<u>14:13</u>	<u>240</u>	<u>10</u>	<u>10</u>	<u>10</u>	<u>2400</u>		
<u>20</u>			<u>✓</u>	<u>In back of building</u>	<u>10:20</u>	<u>14:20</u>	<u>240</u>	<u>10</u>	<u>10</u>	<u>10</u>	<u>2400</u>		
<u>21</u>			<u>✓</u>	<u>— — —</u>	<u>10:21</u>	<u>14:21</u>	<u>240</u>	<u>10</u>	<u>10.5</u>	<u>10.25</u>	<u>2500</u>		
<u>22</u>			<u>✓</u>	<u>— — —</u>	<u>10:22</u>	<u>14:22</u>	<u>240</u>	<u>10</u>	<u>10</u>	<u>10</u>	<u>2400</u>		
<u>23</u>			<u>✓</u>	<u>— — —</u>	<u>10:23</u>	<u>14:23</u>	<u>240</u>	<u>10</u>	<u>10</u>	<u>10</u>	<u>2400</u>		
<u>24</u>			<u>✓</u>	<u>— — —</u>	<u>10:24</u>	<u>14:24</u>	<u>240</u>	<u>10</u>	<u>10</u>	<u>10</u>	<u>2400</u>		
<u>25</u>			<u>✓</u>	<u>Hallway Clean room of deco</u>	<u>10:29</u>	<u>14:29</u>	<u>240</u>	<u>10</u>	<u>10</u>	<u>10</u>	<u>2400</u>		
<u>26</u>			<u>✓</u>	<u>2nd Floor</u>	<u>10:30</u>	<u>14:30</u>	<u>240</u>	<u>10</u>	<u>10</u>	<u>10</u>	<u>2400</u>		

CHAIN OF CUSTODY

18. Relinquished By: I. Lemanovich 19. Received By: JR 20. Date: 9.18.02 21. Time: 16:00

II _____
 III _____

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM 23. Date: 9/20/02 24. Time: 16:00
 a. Analyzed By: R. King
 b. QC By: _____
 c. Lab Batch #: _____

25. Microscope Make/Serial #: _____
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

26. ATC Project Manager: F. Burkhardt 27. Result To: F. Burkhardt
 Beeper/Phone #'s: _____

28. Comments: _____

Analysis Methodology
 PCM - NIOSH 7400A
 TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

Page 3 of 3

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

8859

1. Client: DEP		2. Project Name: DEP Clean-up		3. Project #: 15-22906-0002		4. Project Monitor:		4c. Rotameter Number: SD-006	
2a. Project Address: 125 Cedar St NY		3a. Task #: 00002		4a. Air Sampler: E. Lemonovic					
5. Date: 9.18.2	6. Abatement Location: Around building	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # 316		9. Type: a. ☐ Background b. ☐ Pre-Abate		c. ☐ Abatement d. ☐ Post Abate e. ☐ OSHA	
								f. ☐ Environmental g. ☐ Ambient h. ☒ Other cleaning	

[illegible]

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I <i>E. Lemmonville</i>		<i>9/18/02</i>	
II	<i>TD</i>	<i>9/18/02</i>	<i>16:00</i>
III			

22. Lab Name: <i>ATC-TEM</i>	23. Date:	24. Time:
a. Analyzed By: <i>R. Remy</i>	<i>9/20/0</i>	<i>16:00</i>
b. QC By:		
c. Lab Batch #:		

26. ATC Project Manager: F. Burkhardt	27. Result To: F. Burkhardt
	Beeper/Phone #'s

28. Comments:

25. Microscope Make/Serial #: _____
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology

PCM - NIOSH 7400A
 TEM - AHERA

NY-1 (1701)