



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 4

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client: **DEP**
 2. Project Name: **DEP Clean-up**
 3. Project #: **15-22906-0009**
 4. Project Monitor: **E. Lemnarchik**
 5a. Project Address: **185 Cedar St NY**
 5b. Task #: **00001**
 4a. Air Sampler: **T. Amstislavskiy**
 4c. Ref. Meter Number: **HR-22**
 5. Date: **10.28.09**
 6. Abatement Location: **Apartment # 9S, 8N, 3S, 2N**
 7. ☒ PCM (0.8 micron MCE)
 8. ☐ TEM (0.45 micron MCE)
 9. Type:
 a. ☐ Background c. ☐ Abatement
 b. ☐ Pre-Abate d. ☐ Post-Abate
 e. ☐ OSHA
 f. ☐ Environmental
 g. ☐ Ambient
 h. ☒ Other: **cleaning**

DAILY AIR SAMPLE RECORD

10. Sample ID Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
01				Field Blank								0/100	
02, 03				Field Blank								0/100	
04		✓		Apartment # 9 South	20:30	02:30	360	10	10	10	3600	1/100	0.001
05		✓		— " —	20:32	02:32	360	10	10	10	3600	30/100	0.004
06		✓		— " —	20:34	02:34	360	10	10	10	3600	33/100	0.004
07		✓		— " —	20:36	02:36	360	10	10	10	3600	40/100	0.005
08		✓		— " —	20:38	02:38	360	10	10	10	3600	35/100	0.005
09		✓		Apartment # 8 North	20:55	02:55	360	10	10	10	3600	37/100	0.005

CHAIN OF CUSTODY

18. Relinquished By: **E. Lemnarchik**
 19. Received By: **A. Elbany**
 20. Date: **10.29.09**
 21. Time: **1:00 PM**

22. ATC Project Manager: **B. Sallami**
 27. Result To: **B. Sallami**
 28. Reper/Phone #s:

LAB INFORMATION (ATC ELAP # 10879, ATC NYLAP # 1187)

22. Lab Name: **PCM Lab**
 23. Date: **10/29/09**
 24. Time: **16:00**
 25. Analyzed By: **A. Elbany**
 26. QC By:
 27. Lab Batch #: **101821**
 28. Microscope Make/Serial #: **Nikon Labophot 238913**
 29. ☐ Nikon Labophot 238913
 30. ☐ Nikon Labophot 238917
 31. ☐ Nikon Labophot 239079
 32. Analysis Methodology:
 33. **PCM - NIOSH 7400A**
 34. TEM - AHERA

WHITE - File

YELLOW - Cites/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1.01)



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 4

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client: DEP 2. Project Name: DEP Clean-up 3. Project #: 15-22906-0008 4. Project Monitor: E. Lemanovich 5. Rotameter Number: HR-28

2a. Project Address: 125 Cedar St NY 3a. Task #: 00001 4a. Air Sampler: T. Amstislavskiy

5. Date: 10-28-08 6. Abatement Location: Apartment # 9S, 8N, 3S, 2N 7. ☒ PCM (0.3 micron MCE) 8. ☐ TEM (0.45 micron MCE)

9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☒ Other Clean-up

10. 01344108

DAILY AIR SAMPLE RECORD

2123633594

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. SWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
10		V		Apartment # 8 North	20:57	02:57	360	10	10	10	3600	28/100	0.004
11		V		— " —	20:59	02:59	360	10	10	10	3600	23/100	0.003
12		V		— " —	21:01	03:01	360	10	10	10	3600	22/100	0.003
13		V		— " —	21:03	03:03	360	10	10	10	3600	33/100	0.004
14		V		Apartment # 3 South	21:20	03:20	360	10	10	10	3600	23/100	0.003
15		V		— " —	21:22	03:22	360	10	10	10	3600	25/100	0.003

CHAIN OF CUSTODY

18. Relinquished By: E. Lemanovich 19. Received By: A. Elbert 20. Date: 10-29-08 21. Time: 10:00 AM

22. ATC Project Manager: B. Sallami 27. Result To: B. Sallami 28. Desper/Phone #s: _____

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: PCM Lab 23. Date: 10/29/08 24. Time: 16:00

a. Analyzed By: A. Elbert b. QC By: _____ c. Lab Batch #: 101821

25. Microscope Make/Serial #: Nikon Labophot 238913
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology: PCM - NIOSH 7400A
TEM - AHERA

26. Comments: _____

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 4

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: DEP		2. Project Name: DEP Clean-up		3. Project #: 15-22306-0002		4. Project Monitor: E. Lemanovic		4c. Rotameter Number: 11R-22	
		2a. Project Address: 125 Cedar St NY		3a. Task #: 00001		4a. Air Sampler: T. Amstorslovsky			
5. Date: 10.28.02		6. Abatement Location: Apartments: # 3S, 2N, 3S, 2N		7. ☒ PCM (0.8 micron NCE) Cassette/Fiber Manufacturer: 01344108		8. ☐ TEM (0.45 micron NCE) Cassette/Fiber Manufacturer: _____		9. Type: a. ☐ Background b. ☐ Pre-Abate	
						c. ☐ Abatement d. ☐ Post Abate		f. ☐ Environmental g. ☐ Ambient	
						e. ☐ OSHA		h. ☒ Other Cleaning	

DAILY AIR SAMPLE RECORD

10. Sample ID Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus blank	17. Fiber Conc. F/CC
		12a. NVA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
16		✓		Apartment # 3 South	21:24	03:24	360	10	10	10	3600	14/100	0.002
17		✓		---	21:26	03:26	360	10	10	10	3600	15/100	0.002
18		✓		---	21:28	03:28	360	10	10	10	3600	11/100	0.001
19		✓		Apartment # 2 North	21:45	03:45	360	10	10	10	3600	100/96	0.014
20		✓		---	21:47	03:47	360	10	10	10	3600	69/100	0.009
21		✓		---	21:49	03:49	360	10	10	10	3600	46/100	0.006

CHAIN OF CUSTODY

18. Relinquished By: E. Lemanovic	19. Received By: A. Elbert	20. Date: 10.29.02	21. Time: 7:00 PM
II			
III			

ATC Project Manager:

26. ATC Project Manager: B. Saleem	27. Result To: B. Saleem
Deeper/Phone #'s: _____	

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: _____	23. Date: _____	24. Time: _____	25. Microscope Make/Serial #: _____
a. Analyzed By: _____			☐ Nikon Labophot 238913
b. QC By: _____			☐ Nikon Labophot 238917
c. Lab Batch #: 101821			☐ Nikon Labophot 239079
28. Comments: _____			Analysis Methodology PCM - NIOSH 7400A TEM - AHERA

WHITE - File

YELLOW - Client Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 4 of 4

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: DEP		2. Project Name: DEP. Clean-up		3. Project #: 15-22306-000		4. Project Monitor: E. Lemamovich		4c. Reframetr Number: HR-22	
		2a. Project Address: 125 Cedar St. NY		3a. Task #: 00001		4a. Air Sampler: T. Anstislowski			
5. Date: 10.28.02		6. Abatement Location: Apartment # 9S, 8N, 3S, 2N		7. ☒ PCM (0.1 micron MCE) Cassette/Filtr Manufacturer: 01344108		8. ☐ TEM (0.15 micron MCE) Cassette/Filtr Manufacturer:		9. Type: a. ☐ Background d. ☐ Post Abate b. ☐ Pre Abate e. ☐ OSHA	
								c. ☐ Abatement f. ☐ Environmental g. ☐ Ambient h. ☒ Other (Clean-up)	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol (liters)	16. # Fibers/Folds Minus Blank	17. Fiber Conc. f/cc
		12a. RWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
22		✓		Apartment # 2 North	21:51	03:51	360	10	10	10	3600	100/97	0.014
23		✓		— " —	21:53	03:53	360	10	10	10	3600	69/100	0.009

CHAIN OF CUSTODY

18. Relinquished By: E. Lemamovich		19. Received By: A. Elbert		20. Date: 10.29.02	21. Time: 10:00
16. ATC Project Manager: B. Sallawi		27. Resn To: B. Sallawi			
		Beeper/Phone #'s: _____			

LAB INFORMATION (ATC ELAP # 10079, ATC NVLAP # 1187)

22. Lab Name: PCM Lab		23. Date: 10/29/02	24. Time: 10:00	25. Microscope Make/Serial #: Nikon Labophot 239913 ☐ Nikon Labophot 239913 ☐ Nikon Labophot 239917 ☐ Nikon Labophot 239079
a. Analyzed By: A. Elbert				
b. QC By: _____				
c. Lab Batch #: 101821				
28. Comments: _____				26. Analysis Methodology: PCM - NIOSH 7400A TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NYC-1 (1/01)