



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 8

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: D E P	2. Project Name: D E P Clean-up	3. Project #: 22106-0002	4. Project Manager: S. Stannjober	4c. Rotameter Number: HP-22
2a. Project Address: 125 Cedar St. NY NY 10002	3a. Task #: 10002	4a. Air Sampler: RUBEN ROSTA		
5. Date: 10/08/02	6. Abatement Location: Apts. 5th Floor	7. ☒ PCM (0.1 micron MPP) Canister/Filter Manufacturer: 100	8. ☐ TEM (0.3 micron MPP) Canister/Filter Manufacturer: 100	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☒ Other: Clean

DAILY AIR SAMPLE RECORD

0. Sample ID Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min)			15. Total Air Vol (liters)	16. # Fibers/Fields MAAS Blank	17. Fiber Conc. F/OC
		12a. TWA	12b. GWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
A01				Field Blank								0/100	
A02				Field Blank								0/100	
45S03		✓		5th Floor Apartment S	1630	2230	360	10.0	10.0	10.0	3600	63/100	0.009
45S04		✓		5th Floor Apartment South	1632	2232	360	10.0	10.0	10.0	3600	48/100	0.007
45S05		✓			1634	2234	360	10.0	10.0	10.0	3600	51/100	0.007
45S06		✓			1636	2236	360	10.0	10.0	10.0	3600	46/100	0.006
45S07		✓			1638	2238	360	10.0	10.0	10.0	3600	17/100	0.002
45N08		✓		5th Floor Apartment North	1647	2247	360	10.0	10.0	10.0	3600	16/100	0.002
45N09		✓			1650	2250	360	10.0	10.0	10.0	3600	37/100	0.005
45N10		✓			1651	2251	360	10.0	10.0	10.0	3600	24/100	0.003
45N11		✓			1654	2254	360	10.0	10.0	10.0	3600	2/100	0.00031A
45N12		✓			1656	2256	360	10.0	10.0	10.0	3600	5/100	0.00031A
45I3		✓		5th FL. Hallway	1700	2300	360	10.0	10.0	10.0	3600	4/100	0.0003
45I4		✓		5th FL. Stairway	1701	2301	360	10.0	10.0	10.0	3600	13/100	0.002

CHAIN OF CUSTODY

8. Relinquished By: S. Stannjober	9. Received By: A. Elbaum	20. Date: 10/09/02	21. Time: 15:00
11. R. Rosta			

5. ATC Project Manager:

B. Sallemi27. Result To: **B. Sallemi**

Beepers/Phone #'s

LAB INFORMATION (ATC ELAP # 10879, ATC NYLAP # 1087)

22. Lab Name: PCM Lab	23. Date: 10/09/02	24. Time: 15:00	25. Microscope Make/Serial #: Nikon Labphot 238913
a. Analyzed By: A. Elbaum			
b. QC Sy:			
c. Lab Batch #: 101.533			
28. Comments:			
Analysis Methodology: PCM - NIOSH 7400A TEM - AHERA			

WHITE - File

YELLOW - Client Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 8

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client: DEP	2. Project Name: DEP Clean - up	3. Project #: 22-106-0002	4. Project Manager: S. Stangobere	4c. Rotameter Number: HP-22
5. Date: 10/08/02	6. Abatement Location: 4th FL Apartments	7. ☒ PCM #318888888 Case/Fiber Number: 108	8. ☐ TEV (as shown NOE) Case/Fiber Number: 108	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☒ Other: Clean

DAILY AIR SAMPLE RECORD

0. Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Filters/Folds Minus Blank	17. Filter Conc. FCC
		12a. PMA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
A4S15		✓		4th FL Apartments South	1716	2316	360	10.0	10.0	10.0	3600	9/100	<0.001
A4S16		✓			1718	2318	360	10.0	10.0	10.0	3600	5/100	<0.001
A4S17		✓			1720	2320	360	10.0	10.0	10.0	3600	1/100	<0.001
A4S18		✓			1722	2322	360	10.0	10.0	10.0	3600	8/100	<0.001
A4S19		✓			1724	2324	360	10.0	10.0	10.0	3600	2/100	<0.001
A4N20		✓		4th FL Apartments North	1726	2326	360	10.0	10.0	10.0	3600	3/100	<0.001
A4N21		✓			1728	2328	360	10.0	10.0	10.0	3600	4/100	<0.001
A4N22		✓			1730	2330	360	10.0	10.0	10.0	3600	6/100	<0.001
A4N23		✓			1732	2332	360	10.0	10.0	10.0	3600	1/100	<0.001
A4N24		✓			1734	2334	360	10.0	10.0	10.0	3600	12/100	0.002
A4A25		✓		4th FL Hallway	1736	2336	360	10.0	10.0	10.0	3600	6/100	<0.001
A4A26		✓		4th FL Stairway	1737	2337	360	10.0	10.0	10.0	3600	9/100	<0.001

CHAIN OF CUSTODY

8. Requested By: S. Stangobere	19. Received By: A. Elkan	20. Date: 10/08/02	21. Time: 15:00
11. A. Acosta			
26. ATC Project Manager: B. Sallemi	27. Result To: B. Sallemi	28. Comments:	
Beeper/Phone #s			

LAB INFORMATION (ATC E-AP # 10879, ATC N-AP # 1187)

22. Lab Name: PCM Lab	23. Date: 10/08/02	24. Time: 15:00
a. Analyzed By: A. Elkan		
b. QC By:		
c. Lab Batch #:	101533	
25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 238918		
Analysis Methodology: PCM, NIOSH 7000A TEM - AMERA		

WHITE - File

YELLOW - Client Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

10/11/2002 18:50 FAX 212 353 8308

ATC

023



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 5 of 8

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 46 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client: DEP	2. Project Name: DEP Clean-up	3. Project #: 2266002	4. Project Manager: S. Stampobere	Ac. Rotameter Number: HP-22
5. Date: 10/08/02	6. Abatement Location: 3rd FL Apartments	7. ☒ PCM (as per NIOSH) Corrected for Moisture Lab # 108	8. ☐ TEM (as per NIOSH) Corrected for Moisture Lab #	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☒ Other: Cleaning

DAILY AIR SAMPLE RECORD

10. Sample ID Number	11. Pump Number	12. Sample Location		13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Inlets Minus Blank	17. Rbse Conc. FCC
		12a. NWA	12b. ONWA	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
A53												
A3S27		✓		1812	2412	360	10.0	10.0	10.0	3600	7/100	<0.001
A3S28		✓		1814	2414	360	10.0	10.0	10.0	3600	3/100	<0.001
A3S29		✓		1816	2416	360	10.0	10.0	10.0	3600	5/100	<0.001
A3S30		✓		1818	2418	360	10.0	10.0	10.0	3600	9/100	<0.001
A3S31		✓		1820	2420	360	10.0	10.0	10.0	3600	7/100	<0.001
A3N32		✓		1822	2422	360	10.0	10.0	10.0	3600	14/100	0.002
A3N33		✓		1824	2424	360	10.0	10.0	10.0	3600	3/100	<0.001
A3N34		✓		1826	2426	360	10.0	10.0	10.0	3600	5/100	<0.001
A3N35		✓		1828	2428	360	10.0	10.0	10.0	3600	4/100	<0.001
A3N36		✓		1830	2430	360	10.0	10.0	10.0	3600	2/100	<0.001
A337		✓		1832	2432	360	10.0	10.0	10.0	3600	2/100	<0.001
A338		✓		1833	2433	360	10.0	10.0	10.0	3600	3/100	<0.001

CHAIN OF CUSTODY

18. Relinquished By: S. Stampobere	19. Received By: A. Elbert	20. Date: 10/08/02	21. Time: 7:00
26. ATC Project Manager: B. Sallemi	27. Result To: B. Sallemi	30. Project/Phone #s	

LAB INFORMATION (ATC ELAP # 10879 ATC NYLAP # 1187)

22. Lab Name: PCM Lab	23. Date: 10/08/02	24. Time: 11:00
a. Analyzed By: A. Elbert	25. Microscope Make/Serial #: Nikon Labophot 238913	
b. QC By:	☐ Nikon Labophot 238917	
c. Lab Batch #: 101534	☐ Nikon Labophot 239079	
28. Comments:		
Analysis Methodology: PCM - NIOSH 7400A TEM - AHERA		

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

10/11/2002 16:51 FAX 212 353 8308

ATC

024



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 7 of

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: DEP	2. Project Name: DEP Clean-up	3. Project #: 22906-002	4. Project Manager: R. Stampberg	4c. Reframer Number: HP-22
2a. Project Address: 125 Cedar St. NY NY	3a. Task #: 00002	4a. Air Sampler: Ruben Kosta		
5. Date: 10/08/02	6. Abatement Location: 2nd FL. Apartments	7. ☒ PCM ☐ Other Case #/File No.: 108	8. ☐ TEM ☐ Other: ☐ MOC Case #/File No.: 108	9. Type: a. ☐ Background c. ☐ Abatement i. ☐ Environmental b. ☐ Pre-Abate d. ☐ Post Abate j. ☐ Ambient e. ☐ OSHA h. ☒ Other: Clean

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol (liters)	16. # Fibers/Fields (minus blank)	17. Fiber Conc. /PC
		12a. WCA	12b. DMA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg		
A51				Field Blank							0/100	
A52				Field Blank							0/100	
A2S39		✓		2nd FL Apartments South	1840	2440	360	10.0	10.0	10.0	3600	12/100 0.002
A2S40		✓			1842	2442	360	10.0	10.0	10.0	3600	10/100 0.001
A2S41		✓			1844	2444	360	10.0	10.0	10.0	3600	7/100 <0.001
A2S42		✓			1846	2446	360	10.0	10.0	10.0	3600	8/100 <0.001
A2S43		✓			1848	2448	360	10.0	10.0	10.0	3600	7/100 <0.001
A2N44		✓		2nd FL Apartments North	1850	2450	360	10.0	10.0	10.0	3600	9/100 <0.001
A2N45		✓			1852	2452	360	10.0	10.0	10.0	3600	8/100 <0.001
A2N46		✓			1854	2454	360	10.0	10.0	10.0	3600	9/100 <0.001
A2N47		✓			1856	2456	360	10.0	10.0	10.0	3600	12/100 0.002
A2N48		✓			1858	2458	360	10.0	10.0	10.0	3600	7/100 <0.001
A2-49		✓		2nd FL. Hallway	1900	0100	360	10.0	10.0	10.0	3600	3/100 <0.001
A1-50		✓		1st FL. Hallway	1902	0102	360	10.0	10.0	10.0	3600	6/100 <0.001

CHAIN OF CUSTODY

18. Forfeited By:	19. Received By:	20. Date:	21. Time:
R. Stampberg	A. Elbert	10/08/02	7:00
A. Elbert			

LAB INFORMATION (ATC ELAP # 10679, ATC NMLAP # 1187)

22. Lab Name: PCM Lab	23. Date: 10/08/02	24. Time: 11:00	25. Microscope Make/Serial #: Nikon Labphot 238917
a. Analyzed By: A. Elbert			☐ Nikon Labphot 238917
b. QC By:			☐ Nikon Labphot 239079
c. Lab Batch #:	101534		
26. ATC Project Manager: R. Sallemi			27. Result To: R. Sallemi Receives/Phone #:
28. Comments:			Analysis (Methodology): PCM - NIOSH 7400A TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

10/11/2002 16:52 FAX 212 353 8308

ATC

025