



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 4

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☒ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

Client: DEP		2. Project Name: DEP Clean-up		3. Project #: 15-22306-0002		4. Project Monitor:		4c. Rotameter Number: SD-006	
		2a. Project Address: 125 Cedar St. NY		3a. Task #: 00002		4a. Air Sampler: E. Lewanovich			
Date: 7.07.02		6. Abatement Location:		7. ☒ PCM (0.8 micron MCE) Cassette/Fiber Manufacturer: _____ Lot #: 01283108		8. ☐ TEM (0.45 micron MCE) Cassette/Fiber Manufacturer: _____ Lot #: _____		9. Type: a. ☐ Background d. ☐ Post-Abate b. ☐ Pre-Abate e. ☐ OSHA	
								1. ☐ Environmental 2. ☐ Ambient 3. ☐ Other	

AILY AIR SAMPLE RECORD

Fiberglass

Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fibers Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
B-PH-01		✓		13 Floor Pent house	16:31	22:55	384	10	10	10	3840	4/100	<0.001
B-PH-02		✓		---	16:33	22:56	383	10	10	10	3830	3/100	<0.001
B-PH-03		✓		---	16:35	22:57	382	10	10	10	3820	3/100	<0.001
B-PH-04		✓		---	16:37	22:58	381	10	10	10	3810	2/100	<0.001
B-PH-05		✓		---	16:39	22:59	380	10	10	10	3800	3/100	<0.001
B-12W-06		✓		12 Floor Apartment North	16:44	23:05	381	10	10	10	3810	4/100	<0.001
B-12W-07		✓		---	16:46	23:06	380	10	10	10	3800	3/100	<0.001
B-12W-08		✓		---	16:48	23:07	379	10	10	10	3790	5/100	<0.001
B-12W-09		✓		---	16:50	23:08	378	10	10	10	3780	4/100	<0.001
B-12W-10		✓		---	16:52	23:09	377	10	10	10	3770	1/100	<0.001
B-12SW-11		✓		12 Floor Apartment SW	16:57	23:12	375	10	10	10	3750	52/100	<0.001
B-12SW-12		✓		---	16:59	23:13	374	10	10	10	3740	105/100	<0.001

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
E. Lewanovich	A. Elbert	10.6.2	11:20
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC	23. Date:	24. Time:	25. Microscope Make/Serial #: Nikon Labophot 238913 ☐ Nikon Labophot 238913 ☐ Nikon Labophot 239079
a. Analyzed By: Phog	10/07/02	1850	
b. QC By:			
c. Lab Batch #: 101526			
26. Comments:			Analysis Methodology: ☒ PCM - NIOSH 7400B 0.1 TEM - AHERA

26. ATC Project Manager:	27. Result To:
B. Sallemi	B. Sallemi
	Beep/Phone #'s: _____

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

10/11/2002 16:10 FAX 212 353 8306

ATC

0002



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 4

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☒ 24 hrs ☐ 72 hrs ☐ Other

OBJECT INFORMATION

Client: DEP	2. Project Name: DEP Clean-up	3. Project #: 15-22306-0002	4. Project Monitor:	4c. Rotameter Number: SD-006
	2a. Project Address: 125 Cedar St NY	3a. Task #: 00002	4a. Air Sampler: E. Lemanovich	
Date: 10.08	6. Abatement Location:	7. ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacture: 51283108 Lot #:	8. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture: Lot #:	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

Fiberglass

Sample I.D. Number	Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
B-12SW-13		V		12 Floor Apartment SW	17:01	23:14	373	10	10	10	3730	4100	<0.001
B-12SE-14		V		12 Floor Apartment SE	17:05	23:17	372	10	10	10	3720	5100	<0.001
B-12SE-15		V		---	17:07	23:18	371	10	10	10	3710	4100	<0.001
B-12SE-16		V		---	17:09	23:19	370	10	10	10	3700	8100	<0.001
B-12SE-17		V		---	17:11	23:20	369	10	10	10	3690	8100	<0.001
B-12SE-18		V		---	17:13	23:21	368	10	10	10	3680	5100	<0.001
B-11W-19		V		11 Floor Apartment North	17:19	23:24	365	10	10	10	3650	7100	<0.001
B-11W-20		V		---	17:21	23:25	364	10	10	10	3640	6100	<0.001
B-11W-21		V		---	17:23	23:26	363	10	10	10	3630	7100	<0.001
B-11W-22		V		---	17:25	23:27	362	10	10	10	3620	5100	<0.001
B-11W-23		V		---	17:27	23:28	361	10	10	10	3610	4100	<0.001
B-11S-24		V		11 Floor Apartment South	17:33	23:35	362	10	10	10	3620	4100	<0.001

CHAIN OF CUSTODY

8. Relinquished By: E. Lemanovich	19. Received By: A. Elbert	20. Date: 10.8.2	21. Time: 11:00
I			
II			

5. ATC Project Manager:

B. Sallemi

27. Result To:

B. Sallemi

Beeper/Phone #s:

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC	23. Date: 10/08/02	24. Time: 18:50	25. Microscope Make/Serial #: OLYMPUS CNA/1015 ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: Elbert			
b. QC By:			
c. Lab Batch #: 101526			28. Comments:
Analysis Methodology: ✓ PCM - NIOSH 7400A B ok TEM - AHERA			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 4

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☒ 24 hrs ☐ 72 hrs ☐ Other

OBJECT INFORMATION

Client: DEP	2. Project Name: DEP Clean - up	3. Project #: 15-22906-0002	4. Project Monitor:	4c. Rotameter Number: SD-006
	2a. Project Address: 125 Cedar St NY	3a. Task #: 00002	4a. Air Sampler: E. Lemanovich	
Date: 2.0.02	6. Abatement Location:	7. ☒ PCM (as per MCE) Cassette/Fiber Manufacture Lot #: 01283106	8. ☐ TEM (as per MCE) Cassette/Fiber Manufacture Lot #:	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

Fiberglass

Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (Meters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. TWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
B-11S-25		✓		11 Floor Apartment South	17:35	23:36	361	10	10	10	3610	16/100	0.002
B-11S-26		✓		---	17:37	23:37	360	10	10	10	3600	5/100	<0.001
B-11S-27		✓		---	17:38	23:39	360	10	10	10	3600	9/100	<0.001
B-11S-28		✓		---	17:41	23:41	360	10	10	10	3600	8/100	<0.001
B-10N-29		✓		10 Floor Apartment North	17:51	23:51	366	10	10	10	3660	10/100	0.001
B-10N-30		✓		---	17:55	23:55	365	10	10	10	3650	5/100	<0.001
B-10N-31		✓		---	17:55	23:59	364	10	10	10	3640	4/100	<0.001
B-10N-32		✓		---	17:57	24:00	363	10	10	10	3630	3/100	<0.001
B-10N-33		✓		---	17:59	00:01	362	10	10	10	3620	5/100	<0.001
B-10S-34		✓		10 Floor Apartment South	18:27	00:38	368	10	10	10	3680	5/100	<0.001
B-10S-35		✓		---	18:29	00:36	367	10	10	10	3670	7/100	<0.001
B-10S-36		✓		---	18:31	00:37	366	10	10	10	3660	3/100	<0.001

CHAIN OF CUSTODY

18. Relinquished By: E. Lemanovich	19. Received By: A. Elbert	20. Date: 10.8.2	21. Time: 11:00 AM
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC	23. Date: 10/02/02	24. Time: 1850	25. Microscope Make/Serial #: Nikon Labophot 238913
a. Analyzed By: Rhop			☐ Nikon Labophot 238917
b. QC By:			☐ Nikon Labophot 239079
c. Lab Batch #: 101526			
28. Comments:			Analysis Methodology: ☒ PCM - NIOSH 7400A B TEM - AHERA

26. ATC Project Manager: B. Sallemi	27. Result To: B. Sallemi Beeper/Phone #s:
--	--

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

10/11/2002 16:12 FAX 212 353 8306

ATC

1004



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 4 of 4

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☒ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: DEP		2. Project Name: DEP Clean-up		3. Project #: 15-22906-0002		4. Project Monitor:		4c. Rotameter Number:	
		2a. Project Address: 125 Cedar St NY		3a. Task #: 80002		4a. Air Sampler: E. Lemawrich			
5. Date: 0.07.02		6. Abatement Location:		7. ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacturer: _____ Lot #: 01283108		8. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacturer: _____ Lot #: _____		9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

0. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
				Field Blank									
				Field Blank									
FB-105-37		✓		10 Floor Apartment South	18:33	00:38	365	10	10	10	3650	14/100	0.002
FB-105-38		✓		---	18:35	00:39	364	10	10	10	3640	6/100	<0.001
39, 40				Blanks							-	0/100, 0/100	-
41, 42				Blanks							-	0/100, 0/100	-

CHAIN OF CUSTODY

18. Relinquished By: E. Lemawrich		19. Received By: A. Elbert		20. Date: 10.3.2	21. Time: 11am
II					
III					

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC		23. Date: 10/02/02	24. Time: 12:50
a. Analyzed By: Phogys			
b. QC By:			
c. Lab Batch #: 101526			
28. Comments:			
25. Microscope Make/Serial #: NIKON LABOPHOT 238913 ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079			
26. ATC Project Manager: B. Sallemi			
27. Result To: B. Sallemi Beeper/Phone #s: _____			
25. Analysts Methodology: ☒ PCM - NIOSH 7400A B. Sallemi TEM - AHERA			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)