

030913828

TRC**ASBESTOS AIR MONITORING DATA AND CHAIN OF CUSTODY FORM**

Client Lower Manhattan Development Corporation		Project Manager Arnel Javal		Laboratory/Location EMSL	Turnaround Time ☐ Immediate ☒ 3 Hours ☐ 6 Hours ☐ 12 Hours ☐ 24 Hours ☐ Other
Project Name & Location 130 Liberty Street New York, New York Cellar - A		Project Monitor/Air Sampling Technician <i>V. QUIZHP1</i>		Rotometer Number TRC-0130- <i>9</i>	Type ☐ Background ☐ Final Clearance ☐ Environmental ☐ Work Area Prep ☐ OSHA ☐ Ambient ☐ Abatement ☐ Other
Project Number 116146-0000-0000-00006	2 nd Shift 06/03/09	Cassette Filter Manufacturer Lot	Cassette Filter Manufacturer Lot	Cassette Filter Manufacturer Lot	

AIR SAMPLE INFORMATION

Sample I.D. Number	Pump #	OWA	Sample Location	Time (24 Hr. Clock)			Flow Rate (L/Min.)			Total Air Volume (liters)	# Fibers/Filters Minus Blank	Fiber/Structure Conc.
				Start	End	Total (Minutes)	Start	End	Avg			
P-06/03/09-481	1	OWA	Cellar A, Critical Barrier across from storage room	150	2110	360	3.9	3.64	3.42	1231		
P-06/03/09-482	2	OWA	Cellar A, Critical Barrier east of Stairwell A	151	2111	360	3.9	3.64	3.42	1231		
P-06/03/09-483	3	OWA	Service Elevator, Cellar A	152	2113	361	3.9	3.64	3.42	1235		
P-06/03/09-484	4	OWA	Stair A, Cellar A	153	2115	362	3.9	3.64	3.42	1238		
P-06/03/09-485	5	OWA	Cellar A, Outside Waste Decon	154	2116	362	3.9	3.64	3.42	1238		
P-06/03/09-486	6	OWA	Cellar A, Inside Waste Decon	155	2117	362	3.9	3.64	3.42	1238		
P-06/03/09-487	7	OWA	Cellar A between Stairwells	156	2119	363	3.9	3.64	3.42	1241		
P-06/03/09-488	8	OWA	Entrance to Stairwell B	157	2120	363	3.9	3.64	3.42	1241		
P-06/03/09-489	9	OWA	Cellar A, Electrical Room	159	2122	363	3.9	3.64	3.42	1241		
P-06/03/09-490	10	OWA	Pathway to North Hoist	1520	2123	363	3.9	3.64	3.42	1241		
P-06/03/09-491	11	OWA	Cellar A, Coin vault	1522	2125	363	3.9	3.64	3.42	1241		
P-06/03/09-492	12	OWA	10' North of Stairwell B entrance	1523	2127	364	3.9	3.64	3.42	1245		
P-06/03/09-493	13	OWA	Outside cellar A, Bank 1	1505	2134	389	3.9	3.64	3.42	1330		
P-06/03/09-494	14	OWA	Outside cellar A, Bank 2	1500	2132	386	3.9	3.64	3.42	1320		
P-06/03/09-495	15	OWA	FDNY Door	1504	2131	387	3.9	3.64	3.42	1324		
P-06/03/09-496	16	OWA	Cellar A, Critical Barrier	1503	2133	390	3.9	3.64	3.42	1334		
P-06/03/09-497			Field Blank									
P-06/03/09-498			Field Blank									

CHAIN OF CUSTODY

Requisitioned By <i>V. QUIZHP1</i>	Date 6/3/09	Time 10:30	Received By <i>Rita Nelson</i>	Date 6/4/09	Time 12:55AM	Lab ELAP No. <i>6904</i>	Date 6/4/09	Time 1:55PM	Microscope Make/Serial No.
						QC By <i>[Signature]</i>			
						Lab Batch No.			

Transmit Results To 130airsampleresults@trcsolutions.com	Fax No. 212) 221-7840	Pager No.	Comments	Analysis Methodology, PCM - NIOSH 7400A TEM - AHERA TEM - NIOSH 74
---	--------------------------	-----------	----------	---

ajaval@trcsolutions.com