



ASBESTOS AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Client New York City Law Department		Project Manager Nitin Dave		Laboratory/Location SCILAB	Turnaround Time ☐ Immediate ☐ 3 Hours ☐ 6 Hours ☒ 2 Hours ☒ 4 Hours ☐ Other _____
Project Name & Location 100 Church St.		Project Monitor/Air Sampling Technician Gerald Stanley / Sean Gressler			
Project Number 35052-0000-00007	Date 2/16/02	Rotometer Number NKC #7	☒ PCM (0.8) micron MCE Cassette Filter Manufacturer: _____ Lot _____	☐ Cassette Filter Manufacturer: _____ Lot _____	Type ☐ Background ☐ Post-Abatement ☐ Environmental ☐ Pre-Abatement ☒ OSHA ☐ Ambient ☐ Abatement ☐ Other _____

AIR SAMPLE INFORMATION

Sample I.D. Number	Pump #	Sample Location	Time (24 Hr. Clock)			Flow Rate (L/Min.)			Total Air Volume (liters)	# Fibers/Fields Minus Blank	Fiber/Structure Conc.
			Start	End	Total (Minutes)	Start	End	Avg.			
GS-21602-OSHA-0620		JOSHUA FIGUEROA	0845	1745	540	2	2	2	1080		
GS-21602-OSHA-0621		CEASAR RODRIGUEZ	0846	1746	540	2	2	2	1080		
GS-21602-OSHA-0622		BLANK									
GS-21602-OSHA-0623		BLANK									

CHAIN OF CUSTODY

Relinquished By:	Date	Time	Received By	Date	Time	Lab ELAP No.	Date	Time	Microscope Make/Serial No.
G. Stanley	2/16/02		L.C.	2/18	0705	Analyzed By			
						QC By			
						Lab Batch No.			

Transmit Results To Nitin Dave	Fax No. 1-212-349-4648	Pager No. 1-917-549-3382	Comments: <div style="font-size: 2em; font-weight: bold;">202022696</div>	Analysis Methodology PCM - NIOSH 7400A TEM - AHERA TEM - NIOSH 7404