



ASBESTOS AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Client New York City Law Department		Project Manager Nitin Dave		Laboratory/Location SCILAB		Turnaround Time ☐ Immediate ☐ 3 Hours ☐ 6 Hours ☒ 24 Hours	
Project Name & Location 100 Church St.		Project Monitor/Air Sampling Technician Gerald Stanley				☐ 24 Hours ☐ Other	
Project Number 35052-0000-00007	Date 3/7/02	Rotometer Number NYC #7	☒ PCM (0.8) micron MCE	☐ Cassette Filter Manufacturer: _____ Lot: _____		Type ☐ Background ☐ Post-Abatement ☐ Environmental ☐ Pre-Abatement ☒ OSHA ☐ Ambient ☐ Abatement ☐ Other	
			Cassette Filter Manufacturer: _____ Lot: _____				

AIR SAMPLE INFORMATION

Sample I.D. Number	Sample Location	Time (24 Hr. Clock)			Flow Rate (L/Min.)			Total Air Volume (liters)	# Fibers/Fields Minus Blank	Fiber/Structure Conc.
		Start	End	Total (Minutes)	Start	End	Avg.			
GS-3/7/02-OSHA-0329	LUIS BUENO	0614	1114	300	2	2	2	600		
GS-3/7/02-OSHA-0330	FRANCISCO VALERA	0616	1116	300	2	2	2	600		
GS-3/7/02-OSHA-0331	LUIS BUENO	1230	1730	300	2	2	2	600		
GS-3/7/02-OSHA-0332	FRANCISCO VALERA	1233	1733	300	2	2	2	600		
GS-3/7/02-OSHA-0333	Blank									
GS-3/7/02-OSHA-0334	Blank									

02031844

CHAIN OF CUSTODY

Relinquished By:	Date	Time	Received By	Date	Time	Lab ELAP No.	Date	Time	Microscope Make/Serial No.
G. Stanley	3/7/02		G. Fleming	3/8/02	10:40	11480	3/8/02	10:40	
						Analyzed By M Brothers			
						QC By			
						Lab Batch No.			

Transmit Results To	Fax No.	Pager No.	Comments:	Analysis Methodology
Nitin Dave	1-212-349-4648	1-917-549-3382		PCM - NIOSH 7400A TEM - AHERA TEM - NIOSH 7404