

SCILAB 30077 203032390

Client: TRC Environmental Corporation

Table I

Summary of Transmission Electron Microscopy (TEM) Results for Asbestos (ASTM D5755 Dust Microvac)

35052-0000-00017; New York City Law Department ; 100 Church Street, NY, NY

SciLab Sample #	Client Sample #	Surface Area Sampled (sq. cm)	Dilution Factor	Asbestos Structures Detected	* Analytical Sensitivity on Grid (Str / sq mm)	Structure Density on Grid (Str / sq mm)	* Analytical Sensitivity on Surface (Str / sq. cm)	Limit Of Detection (Str/ sq. cm)	Structure Density on Surface (Str/ sq. cm)	Type of Asbestos
01	GS031503MV2001 20th Floor North Hallway Outside W. Men's Bath	100.0	0.06000	0	25	<25	891	891	<891	NSD
02	GS031503MV2002 20th Floor North Hallway Outside Elevator Bank	100.0	0.06000	0	25	<25	891	891	<891	NSD
03	GS031503MV2003 20th Floor North Hallway Outside Copy Center	100.0	0.06000	0	25	<25	891	891	<891	NSD
04**	GS031503MV2004 Field Blank				1					

structure density represented by the detection of 1 structure

* not analyzed

NSD: No Asbestos Structures Detected

Reviewed By: _____

; Analyzed By: _____

Aleksandr Barengolts

Date: 3/16/03