



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 5**TURNAROUND TIME**
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☒ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____
PROJECT INFORMATION

1. Client: <u>40 RECTOR ST</u>		2. Project Name <u>5554 25/29 40 RECTOR ST</u>		3. Project # <u>59442-59470</u> <u>19834-33</u>		4. Project Monitor: <u>R. FISHMAN</u>		4c. Rotameter Number: <u>SD024</u>	
		2a. Project Address <u>40 RECTOR ST, NY, NY</u>				4a. Air Sampler: <u>R. FISHMAN</u>			
5. Date: <u>09-24-01</u>		6. Abatement Location: <u>19th FLOOR</u>		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>MIMI</u> Lot # <u>48/307/617</u>		9. Type: a. ☐ Background c. ☐ Abatement b. ☐ Pre-Abate d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
<u>09-24-01</u>				Field Blank <u>Open 30sec</u>									
<u>09-24-02</u>				Field Blank <u>Open 30sec</u>									
<u>-03</u>				<u>19th FLOOR - MICROFISHE</u> <u># TRAINING RM - NE section</u>	<u>1107</u>	<u>1335</u>	<u>148</u>	<u>10.0</u>	<u>10.0</u>	<u>10</u>	<u>1480</u>		
<u>-04</u>				<u>19th floor - MICROFISHE</u> <u># TRAINING RM - by mgr desk</u>	<u>1108</u>	<u>1337</u>	<u>149</u>	<u>10.0</u>	<u>10.0</u>	<u>10</u>	<u>1490</u>		
<u>-05</u>				<u>Hallway 19th floor by</u> <u>entrance from freight elev</u>	<u>1109</u>	<u>1340</u>	<u>151</u>	<u>10.0</u>	<u>10.0</u>	<u>10</u>	<u>1510</u>		
<u>-06</u>				<u>GEOFF JOHNSON DESIGN COMP</u> <u>suite 1920 - NW section</u>	<u>1110</u>	<u>1342</u>	<u>152</u>	<u>10.0</u>	<u>10.0</u>	<u>10</u>	<u>1520</u>		
<u>-07</u>				<u>GEOFF JOHNSON DESIGN COMP</u> <u>suite 1920 - SE section</u>	<u>1112</u>	<u>1344</u>	<u>152</u>	<u>10.0</u>	<u>10.0</u>	<u>10</u>	<u>1520</u>		
<u>-08</u>				<u>Sealed Blank</u>									

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
<u>I R. FISHMAN</u>		<u>09-24-01</u>	
<u>II</u>	<u>JD</u>	<u>9/25/01</u>	<u>8:00</u>
<u>III</u>			

26. ATC Project Manager: <u>M. TERJESEN</u>	27. Result To: <u>PR. mngt</u> Beeper/Phone #'s _____
--	--

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By:			
b. QC By:			
c. Lab Batch #:			Analysis Methodology PCM - NIOSH 7400A TEM - AHERA
28. Comments:			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/00)



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 5

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☒ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: <u>40 RECTOR ST,</u>		2. Project Name: <u>40 RECTOR ST</u>		3. Project #: <u>19834-33</u>		4. Project Monitor: _____		4c. Rotameter Number: <u>SD024</u>	
		2a. Project Address: <u>40 RECTOR ST, NY, NY,</u>				4a. Air Sampler: <u>R. FISCHMAN</u>			
5. Date: <u>09-24-01</u>		6. Abatement Location: <u>18TH FLOOR</u>		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>MMI</u> Lot # <u>78/307/617</u>		9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other _____	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
				Field Blank									
				Field Blank									
-09				FIRST BROKERS SECURITY INC - SOUTH WEST SECTION	1124	1355	151	10.0	10.0	10	1510		<17.7
-10				FIRST BROKERS SECURITY INC - NORTH WEST SECTION	1126	1356	150	10.0	10.0	10	1500		<17.7
-11				GYM - NORTH EAST SECTION	1130	1358	148	10.0	10.0	10	1480		<17.7
-12				GYM - SOUTH EAST SECTION	1132	1359	147	10.0	9.0	9.5	13965		<17.7
-13				Hallway by entrance to First Brok. sec INC	1135	1400	145	10.0	10.0	10	1450		<17.7

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I <u>R. FISCHMAN</u>		<u>09/24/01</u>	
II	<u>JD</u>	<u>9/25/01</u>	<u>8:00</u>
III			

26. ATC Project Manager:

M. TERJESEN

27. Result To:

Pr. mgr

Beeper/Phone #'s _____

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ATC-TEM</u>	23. Date:	24. Time:	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <u>RKJ</u>	<u>9/25/01</u>	<u>12:00</u>	
b. QC By: _____			
c. Lab Batch #: _____			

28. Comments:

Analysis Methodology

PCM - NIOSH 7400A

TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/00)



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 5

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☒ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: 40 RECTOR ST
 2. Project Name: 40 RECTOR ST
 2a. Project Address: 40 RECTOR ST, NY, NY
 3. Project #: 19834-33
 4. Project Monitor: R. FISHMAN
 4c. Rotameter Number: SD 024
 5. Date: 09-24-01
 6. Abatement Location: 10th FLOOR
 7. ☐ PCM (0.8 micron MCE)
 Cassette/Filter Manufacture _____
 Lot # _____
 8. ☒ TEM (0.45 micron MCE)
 Cassette/Filter Manufacture MMI
 Lot # 18/307/617
 9. Type:
 a. ☐ Background c. ☐ Abatement
 b. ☐ Pre-Abate d. ☐ Post-Abate
 e. ☐ OSHA f. ☐ Environmental
 g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

0. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
-14				Roath middle section office 1012	1527	1740	133	10.0	10.0	10	1330		
-15				NW corner office Mrs Gorelik #1011	1530	1742	132	10.0	10.0	10	1320		
-16				West side office # 1008 Castillo	1532	1744	132	10.0	10.0	10	1320		
-17				Hallway by commissio of HR - south side	1535	1745	130	10.0	10.0	10	1300		
-18				East side by entrance to office # 1021	1538	1747	129	10.0	10.0	10	1290		

CHAIN OF CUSTODY

3. Relinquished By: R. FISHMAN
 19. Received By: JA
 20. Date: 09-24-01
 21. Time: 8:00

i. ATC Project Manager:

27. Result To: PR. merge
 Beeper/Phone #'s _____

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TE/14
 a. Analyzed By: RRM
 b. QC By: _____
 c. Lab Batch #: _____
 23. Date: 9.25.01
 24. Time: 15:00
 25. Microscope Make/Serial #: _____
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079
 Analysis Methodology
 PCM - NIOSH 7400A
 TEM - AHERA

28. Comments:

WHITE - File

YELLOW - Client/Report

PINK - Lab

GREEN - Report

(1/00)



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 4 of 5

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☒ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: 40 Rector St
 2. Project Name: 40 Rector St
 3. Project #: 19834-33
 4. Project Monitor: R. Fishman
 4c. Rotameter Number: SD024
 2a. Project Address: 40 Rector St. NY, NY
 5. Date: 07-24-01
 6. Abatement Location: 9th Floor
 7. ☐ PCM (0.8 micron MCE)
 Cassette/Filter Manufacture _____ Lot # _____
 8. ☒ TEM (0.45 micron MCE)
 Cassette/Filter Manufacture MMI Lot # 98/307/617
 9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

0. Sample I.D. Number	11. Pump Number	12. Sample Location	13. Time (24 hrs clock)	14. Flow Rate (L/min.)	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA 12b. OWA	13a. Start 13b. End 13c. Total	14a. Start 14b. End 14b. Avg			
			Field Blank				
			Field Blank				
-19			North east corner MR. PARIFICO office	1600 1815 135	10.0 10.0 10	1350	
-20			North west corner MR. J. CHIN office	1602 1816 134	10.0 10.0 10	1340	
-21			East middle section office #907	1605 1818 133	10.0 10.0 10	1330	
-22			Rm 915 Mrs J. Faerlauer office	1607 1820 133	10.0 10.0 10	1330	
-23			South west corner Rm 901 Mr. R. Willis office	1610 1821 131	10.0 10.0 10	1310	

CHAIN OF CUSTODY

Relinquished By: R. Fishman
 19. Received By: JA
 20. Date: 07-24-01
 21. Time: 8:00

ATC Project Manager:

M. FERJESSEN

27. Result To:

PR. MUGR
Beeper/Phone #'s _____

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: _____
 a. Analyzed By: _____
 b. QC By: _____
 c. Lab Batch #: _____
 23. Date: _____
 24. Time: _____
 25. Microscope Make/Serial #: _____
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079
 Analysis Methodology
 PCM - NIOSH 7400A
 TEM - AHERA
 28. Comments: _____

WHITE - File

YELLOW - Client/Report

PINK - Lab

GREEN - ROD

N (00)



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 5 of 5

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☒ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

Client: 40 RECTOR ST 2. Project Name 40 Rector St 3. Project # 19834-33 4. Project Monitor: _____
 2a. Project Address 40 Rector St, NY, NY 4a. Air Sampler: R. FISHMAN 4c. Rotameter Number: SD024
 Date: 9-24-01 6. Abatement Location: 8th FLOOR 7. ☐ PCM (0.8 micron MCE) 8. ☒ TEM (0.45 micron MCE) 9. Type: _____
 Cassettes/Filter Manufacture _____ Cassettes/Filter Manufacture MMI a. ☐ Background c. ☐ Abatement f. ☐ Environmental
 Lot # _____ Lot # 18/307/517 b. ☐ Pre-Abate d. ☐ Post-Abate g. ☒ Ambient
 e. ☐ OSHA h. ☐ Other _____

AILY AIR SAMPLE RECORD

J. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
<u>9-24-29</u>				Field Blank <u>Open 30 Sec</u>									
				Field Blank									
<u>-24</u>				<u>ICL - North west</u>	<u>1910</u>	<u>2120</u>	<u>130</u>	<u>10.0</u>	<u>10.0</u>	<u>10</u>	<u>1300</u>		
				<u>CORNER OFFICE of HR-SECRETARY</u>									
<u>-25</u>				<u>ICL - Ken Heckart office</u>	<u>1913</u>	<u>2122</u>	<u>129</u>	<u>10.0</u>	<u>10.0</u>	<u>10</u>	<u>1290</u>		
				<u>- north west section</u>									
<u>-26</u>				<u>ICL - north middle</u>	<u>1915</u>	<u>2125</u>	<u>130</u>	<u>10.0</u>	<u>10.0</u>	<u>10</u>	<u>1300</u>		
				<u>section staff lounge</u>									
<u>-27</u>				<u>North east corridor</u>	<u>1917</u>	<u>2126</u>	<u>129</u>	<u>10.0</u>	<u>10.0</u>	<u>10</u>	<u>1290</u>		
				<u>JACK MILLER office</u>									
<u>-28</u>				<u>TAXI & LIMOUSIN commission</u>	<u>1921</u>	<u>2128</u>	<u>127</u>	<u>10.0</u>	<u>10.0</u>	<u>10</u>	<u>1270</u>		
				<u>By JAMES Webster cubical</u>									

CHAIN OF CUSTODY

Relinquished By: R. FISHMAN 19. Received By: _____ 20. Date: 09/24/01 21. Time: _____
 _____ _____ 9/25/01 8:00
 _____ _____ _____ _____

ATC Project Manager:

M. TERJESEN

27. Result To: _____

Beeper/Phone #s _____

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: _____ 23. Date: _____ 24. Time: _____
 a. Analyzed By: _____
 b. QC By: _____
 c. Lab Batch #: _____
 25. Microscope Make/Serial #: _____
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079
 26. Analysis Methodology
 PCM - NIOSH 7400A
 TEM - AHERA
 28. Comments: _____

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NYC (10)