

AMBIENT GROUP, INC.  
10 MORRIS AVENUE  
GLEN COVE, NY 11542

## DUST CHARACTERIZATION LABORATORY DATA REPORT

PROJECT ID: 211368  
CLIENT: CRG MANAGEMENT  
LOCATION: 60 BROAD STREET  
TECHNICIAN: CRAIG KAMBACK

DATE COLLECTED: 9/17/01  
DATE RECEIVED: 9/17/01  
DATE ANALYZED: 9/18/01

| FIELD ID<br>LABORATORY ID | DESCRIPTION                             | SAMPLE<br>CONSTITUENTS | PERCENT OF<br>SAMPLE ** |
|---------------------------|-----------------------------------------|------------------------|-------------------------|
| 211368-01<br>DB1852       | 23RD FLOOR: RECEPTION DESK              | CELLULOSE              | 20.0%                   |
|                           |                                         | CEMENT DUST            | 50.0%                   |
|                           |                                         | CARBON PARTICLES       | 10.0%                   |
|                           |                                         | DECAYED ORGANIC MATTER | 20.0%                   |
|                           |                                         | TOTAL                  | 100.0%                  |
| 211368-02<br>DB1853       | 23RD FLOOR: CONFERENCE ROOM             | CELLULOSE              | 20.0%                   |
|                           |                                         | CEMENT DUST            | 50.0%                   |
|                           |                                         | CARBON PARTICLES       | 10.0%                   |
|                           |                                         | DECAYED ORGANIC MATTER | 20.0%                   |
|                           |                                         | TOTAL                  | 100.0%                  |
| 211368-03<br>DB1854       | 10TH FLOOR: DAISY'S DESK                | CELLULOSE              | 20.0%                   |
|                           |                                         | CEMENT DUST            | 50.0%                   |
|                           |                                         | CARBON PARTICLES       | 10.0%                   |
|                           |                                         | DECAYED ORGANIC MATTER | 20.0%                   |
|                           |                                         | TOTAL                  | 100.0%                  |
| 211368-04<br>DB1855       | 10TH FLOOR: ADJACENT TO WORK STATION 16 | CELLULOSE              | 20.0%                   |
|                           |                                         | CEMENT DUST            | 50.0%                   |
|                           |                                         | CARBON PARTICLES       | 10.0%                   |
|                           |                                         | DECAYED ORGANIC MATTER | 20.0%                   |
|                           |                                         | TOTAL                  | 100.0%                  |

Signed for Ambient Group Inc. by,

*Tarek Fata*  
TAREK FATA

ND = None Detected, NA = Not Analyzed. There are two (2) types of dust sample submitted for analysis: Settled = Samples submitted on tape/bulk, Airborne = Samples submitted in Air-D-Cell Cassettes. All results disclosed in this report relate only to the items tested. No reproduction of all or any portion of this report shall occur without written approval of Ambient Group Inc. Unless otherwise directed by the Client, Ambient Group Inc. will retain the samples listed in this report for five (5) days, after which time they may be disposed of in accordance with applicable regulations.

SEP-19-01 WED 04:17 PM AMBIENT GROUP INC

FAX NO. 212 768 1540

P. 03

CONFIDENTIAL INSURANCE INFORMATION,  
SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CITY\_21MC100\_013508329