



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

8730 17/20 915-934

1. Client: <u>NYC - BOE</u>		2. Project Name: <u>PS 126 M / 20 Catherine St. NY, NY</u>		3. Project #: <u>14584-0872</u>		4. Project Monitor: <u>H. Antonyan</u>		4c. Rotameter Number: <u>HP-128</u>	
5. Date: <u>8/21/02</u>		6. Abatement Location: <u>Throughout the building & Roof</u>		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>MMI</u> Lot # <u>02106916</u>		9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
18				Field Blank									
19				Field Blank									
01		1		1st floor lobby	06:31	10:31	240	8.0	8.0	8.0	1920		
02		1		Cafeteria	06:36	10:37	241	8.0	8.0	8.0	1928		
03		1		Auditorium	06:42	10:42	240	8.0	8.0	8.0	1920		
04		1		1st floor Hallway	06:47	10:50	243	8.0	8.0	8.0	1944		
05		1		1st floor Classroom # 125	06:51	10:53	242	8.0	8.0	8.0	1936		
06		1		1st floor Classroom # 123	06:57	11:00	243	8.0	8.0	8.0	1944		

CHAIN OF CUSTODY

18. Relinquished By: <u>I H. Antonyan</u>	19. Received By: <u>JD</u>	20. Date: <u>8/21/02</u>	21. Time: <u>17:00</u>
26. ATC Project Manager: _____		27. Result To: _____ Beeper/Phone #'s: _____	

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ATC-TEM</u>	23. Date: <u>8/21/02</u>	24. Time: <u>10:45</u>	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <u>RADY</u>			
b. QC By: _____			
c. Lab Batch #: _____			Analysis Methodology PCM - NIOSH 7400A TEM - AHERA
28. Comments: _____			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003421912



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1. Client: NYC-BOE 2. Project Name: P.S. 126 M 3. Project #: 14584-0872 4. Project Monitor: _____
 2a. Project Address: 80 Catherine St. NY, NY 3a. Task #: _____ 4a. Air Sampler: H. Antonian 4c. Rotameter Number: HP-128
 5. Date: 8/21/02 6. Abatement Location: Throughout the building & Roof 7. ☒ PCM (0.8 micron MCE) 8. ☒ TEM (0.45 micron MCE)
 Cassette/Filter Manufacture: _____ Cassette/Filter Manufacture: MMI
 Lot #: _____ Lot #: 02106916 9. Type: ☐ Abatement f. ☐ Environmental
☐ Background d. ☐ Post-Abate g. ☒ Ambient
☐ Pre-Abate e. ☐ OSHA h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg		
<u>20</u>				Field Blank <u>Sealed Blank</u>								
				Field Blank								
<u>07</u>		<u>1</u>		<u>2nd floor Hallway</u>	<u>07:02</u>	<u>11:05</u>	<u>243</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1944</u>	
<u>08</u>		<u>1</u>		<u>2nd floor Classroom # 203</u>	<u>07:06</u>	<u>11:07</u>	<u>241</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1928</u>	
<u>09</u>		<u>1</u>		<u>2nd floor Classroom # 237</u>	<u>07:11</u>	<u>11:11</u>	<u>240</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1920</u>	
<u>10</u>			<u>1</u>	<u>Roof (Central)</u>	<u>07:17</u>	<u>11:19</u>	<u>242</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1936</u>	
<u>11</u>			<u>1</u>	<u>Outside of Main Entrance</u>	<u>07:25</u>	<u>11:28</u>	<u>243</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1944</u>	
<u>12</u>		<u>1</u>		<u>3rd floor Hallway</u>	<u>12:00</u>	<u>16:00</u>	<u>240</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1920</u>	

CHAIN OF CUSTODY

18. Relinquished By: I H. L. Long 19. Received By: JD 20. Date: 8/21/02 21. Time: 1700
 II
 III
 26. ATC Project Manager: _____ 27. Result To: _____
 Beeper/Phone #'s: _____

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM 23. Date: 8/21/02 24. Time: 10:45
 a. Analyzed By: RKJ
 b. QC By: _____
 c. Lab Batch #: _____
 25. Microscope Make/Serial #: _____
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079
 28. Comments: _____
 Analysis Methodology
 PCM - NIOSH 7400A
 TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003421913



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1. Client: NYC-BOE
 2. Project Name: PS 126M/1A 893
 2a. Project Address: 80 Catherine St. NY, NY
 3. Project #: 14584-0872
 3a. Task #: _____
 4. Project Monitor: _____
 4a. Air Sampler: H. Antonyan
 4c. Rotameter Number: HP-128
 5. Date: 8/21/02
 6. Abatement Location: throughout the building
 7. ☐ PCM (0.8 micron MCE)
 Cassette/Filter Manufacture: _____
 Lot #: _____
 8. ☒ TEM (0.45 micron MCE)
 Cassette/Filter Manufacture: MMI
 Lot #: 02106916
 9. Type: _____
 a. ☐ Background b. ☐ Pre-Abate
 c. ☐ Abatement d. ☐ Post-Abate
 e. ☐ OSHA f. ☐ Environmental
 g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
13		1		3rd floor Classroom # 319	12:04	16:04	240	8.0	8.0	8.0	1920		
14		1		3rd floor Classroom # 325	12:07	16:07	240	8.0	8.0	8.0	1920		
15		1		4th floor Hallway	12:11	16:12	241	8.0	8.0	8.0	1928		
16		1		4th floor Classroom # 443	12:14	16:15	241	8.0	8.0	8.0	1928		
17		1		4th floor Classroom # 429	12:17	16:17	240	8.0	8.0	8.0	1920		

CHAIN OF CUSTODY

18. Relinquished By: I H. Antonyan
 19. Received By: JD
 20. Date: 8/21/02
 21. Time: 17:00
 26. ATC Project Manager: _____
 27. Result To: _____
 Beeper/Phone #'s: _____

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEI
 a. Analyzed By: Rilly
 b. QC By: _____
 c. Lab Batch #: _____
 23. Date: 8/22/02
 24. Time: 10:45
 25. Microscope Make/Serial #: _____
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079
 Analysis Methodology
 PCM - NIOSH 7400A
 TEM - AHERA
 28. Comments: _____

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL

CITY_21MC100_003421914