



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 2

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1. Client: NYC/BOE
 2. Project Name: Murray Bergtraum HS
 2a. Project Address: 411 West 1st St NY NY
 3. Project #: 15584-878
 3a. Task #: 01
 4. Project Monitor: Jim Anastasiadis
 4c. Rotameter Number: SD-003
 5. Date: 9.09.02
 6. Abatement Location: Entire
 7. ☐ PCM (0.8 micron MCE)
 Cassette/Filter Manufacture: X
 Lot #:
 8. ☒ TEM (0.45 micron MCE)
 Cassette/Filter Manufacture: MNT
 Lot #: 02105916
 9. Type:
 a. ☐ Background c. ☐ Abatement
 b. ☐ Pre-Abate d. ☐ Post-Abate
 e. ☐ OSHA f. ☐ Environmental
 g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg		
<u>B-1, B-2</u>				Field Blank								
				Field Blank								
<u>01</u>				<u>outside the bldg.</u>	<u>1400</u>	<u>1600</u>	<u>240</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1920</u>	
<u>02</u>				<u>1 FL Hallway</u>	<u>1403</u>	<u>1603</u>	<u>240</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1928</u>	
<u>03</u>				<u>Auditorium</u>	<u>1408</u>	<u>1608</u>	<u>239</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1912</u>	
<u>04</u>				<u>RM # 159</u>	<u>1413</u>	<u>1612</u>	<u>239</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1912</u>	
<u>05</u>				<u>Room # 111</u>	<u>1416</u>	<u>1615</u>	<u>239</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1912</u>	
<u>06</u>				<u>Room # 203</u>	<u>1420</u>	<u>1620</u>	<u>240</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1920</u>	
<u>07</u>				<u>Room # 207</u>	<u>1424</u>	<u>1624</u>	<u>240</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1920</u>	
<u>08</u>				<u>2 FL Hallway</u>	<u>1428</u>	<u>1629</u>	<u>241</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1928</u>	
<u>09</u>				<u>Cafeteria</u>	<u>1432</u>	<u>1633</u>	<u>241</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1928</u>	
<u>10</u>				<u>Room # 359</u>	<u>1438</u>	<u>1638</u>	<u>240</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1920</u>	
<u>11</u>				<u>Room # 351</u>	<u>1441</u>	<u>1641</u>	<u>240</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1920</u>	
<u>12</u>				<u>3 FL Hallway</u>	<u>1444</u>	<u>1644</u>	<u>240</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1920</u>	

CHAIN OF CUSTODY

18. Relinquished By: [Signature]
 19. Received By: [Signature]
 20. Date: 9/10/02
 21. Time: 8:00

26. ATC Project Manager: V. Efstathiou
 27. Result To: V. Efstathiou
 Beeper/Phone #'s: (846) 772-1155

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: TEC
 a. Analyzed By: [Signature]
 b. QC By: [Signature]
 c. Lab Batch #:
 23. Date: 9/10/02
 24. Time: 10:50
 25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079
 Analysis Methodology
 PCM - NIOSH 7400A
TEM - AHERA

28. Comments:
 WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003422241



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 2

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other As Is

PROJECT INFORMATION

1. Client: NYC/BOE 2. Project Name: Murray Berghtraum HS 3. Project #: 14584-888 4. Project Monitor: [Signature] 4c. Rotameter Number:

2a. Project Address: 411 Pearl St WNY 3a. Task #: 01 4a. Air Sampler: Time Analysis

5. Date: 9.9.02 6. Abatement Location: Entire 7. ☐ PCM (0.8 micron MCE) 8. ☐ TEM (0.45 micron MCE)

Cassette/Filter Manufacture: [Signature] Cassette/Filter Manufacture: MMI 9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

Lot #: Lot #: 02105916

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location	13. Time (24 hrs clock)	14. Flow Rate (L/min.)	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA 12b. OWA	13a. Start 13b. End 13c. Total	14a. Start 14b. End 14b. Avg			
B-3			Field Blank				
B-4			Field Blank Sealed Blank				
13			ROOM # 409	1650 2050 240	8	8	1920
14			ROOM # 406	1654 2054 240	8	8	1920
15			4 FL Hallway	1657 2057 240	8	8	1920
16			ROOM # 506	1701 2102 241	8	8	1928
17			ROOM # 504	1705 2106 241	8	8	1928
18			SFL Hallway	1709 2110 241	8	8	1928
19			BSMT Hallway	1714 2114 240	8	8	1920
20			BSMT ROOM # 59	1718 2118 240	8	8	1920
21			BSMT ROOM # 55	1722 2123 241	8	8	1928
22			1 FL Lobby	1738 2137 239	8	8	1912
23			ROOF	1745 2144 239	8	8	1912

CHAIN OF CUSTODY

18. Relinquished By: [Signature] 19. Received By: [Signature] 20. Date: 9/10/02 21. Time: 8:00

26. ATC Project Manager: [Signature] 27. Result To: Y. Efstathiou Beeper/Phone #'s: 609 882 1155

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: [Signature] 23. Date: 9/10/02 24. Time: 10:00

a. Analyzed By: [Signature] b. QC By: c. Lab Batch #:

25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079

Analysis Methodology: PCM - NIOSH 7400A TEM - AHERA

28. Comments:

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL

CITY_21MC100_003422242