



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 2

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1. Client: NYC/BOE
 2. Project Name: 8828 23/27 2102-2128
 2a. Project Address: Murray Bergtraum US 411 East 5th St NY NY
 3. Project #: 19534-888
 3a. Task #: 01
 4. Project Monitor: Y. E. J. Stathion
 4a. Air Sampler: SD-003
 4c. Rotameter Number: SD-003
 5. Date: 9.09.02
 6. Abatement Location: Entire
 7. ☐ PCM (0.8 micron MCE)
 Cassette/Filter Manufacture: X
 Lot #:
 8. ☒ TEM (0.45 micron MCE)
 Cassette/Filter Manufacture: MNT
 Lot #: 02105916
 9. Type:
 a. ☐ Background c. ☐ Abatement f. ☐ Environmental
 b. ☐ Pre-Abate d. ☐ Post-Abate g. ☒ Ambient
 e. ☐ OSHA h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
B-1, B-2				Field Blank									
				Field Blank									
01				outside the bldg.	1400	1600	240	8	8	8	1920		
02				1 FL Hallway	1403	1603	240	8	8	8	1928		
03				Auditorium	1408	1608	239	8	8	8	1912		
04				RM # 159	1413	1612	239	8	8	8	1912		
05				Room # 111	1416	1615	239	8	8	8	1912		
06				Room # 203	1420	1620	240	8	8	8	1920		
07				Room # 207	1424	1624	240	8	8	8	1920		
08				2 FL Hallway	1428	1629	241	8	8	8	1928		
09				Cafeteria	1432	1633	241	8	8	8	1928		
10				Room # 359	1438	1638	240	8	8	8	1920		
11				Room # 351	1441	1641	240	8	8	8	1920		
12				3 FL Hallway	1444	1644	240	8	8	8	1920		

CHAIN OF CUSTODY

18. Relinquished By: [Signature]
 19. Received By: [Signature]
 20. Date: 9/10/02
 21. Time: 8:45

26. ATC Project Manager: Y. E. J. Stathion
 27. Result To: Y. E. J. Stathion
 Beeper/Phone #'s: (646) 872-1155

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: TEM
 a. Analyzed By: [Signature]
 b. QC By: [Signature]
 c. Lab Batch #:
 23. Date: 9/10/02
 24. Time: 10:50
 25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079
 Analysis Methodology
 PCM - NIOSH 7400A
TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003422345



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 2

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other As Is

PROJECT INFORMATION

1. Client: NYC/BOB 2. Project Name: Murray Bergthron MS 3. Project #: 14584-888 4. Project Monitor: Jim Musfist

2a. Project Address: 411 Pearl St WNYC 3a. Task #: 01 4a. Air Sampler: Jim Musfist

5. Date: 9.9.02 6. Abatement Location: Entire 7. ☐ PCM (0.8 micron MCE) 8. ☐ TEM (0.45 micron MCE)

Cassette/Filter Manufacture: X Cassette/Filter Manufacture: MMI 9. Type: c. ☐ Abatement f. ☐ Environmental

Lot #: X Lot #: 02105916 a. ☐ Background d. ☐ Post-Abate g. ☒ Ambient

b. ☐ Pre-Abate e. ☐ OSHA h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
B-3				Field Blank									
B-4				Field Blank Sealed Blank									
13				ROOM # 409	1650	2050	240	8	8	8	1920		
14				ROOM # 406	1654	2054	240	8	8	8	1920		
15				4 FL Hallway	1657	2057	240	8	8	8	1920		
16				ROOM # 506	1701	2102	241	8	8	8	1928		
17				ROOM # 504	1705	2106	241	8	8	8	1928		
18				SFL Hallway	1709	2110	241	8	8	8	1928		
19				BSMNT Hallway	1714	2114	240	8	8	8	1920		
20				BSMNT ROOM # 59	1718	2118	240	8	8	8	1920		
21				BSMNT ROOM # 55	1722	2123	241	8	8	8	1928		
22				1 FL Lobby	1738	2137	239	8	8	8	1912		
23				ROOF	1745	2144	239	8	8	8	1912		

CHAIN OF CUSTODY

18. Relinquished By: IV 19. Received By: JR 20. Date: 9/10/02 21. Time: 8:00

II

III

26. ATC Project Manager: Y. Efstathiou 27. Result To: Y. Efstathiou

Beeper/Phone #'s: 646 882-1155

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: VE 23. Date: 9/10/02 24. Time: 10:50

a. Analyzed By: VE b. QC By: VE c. Lab Batch #: VE

25. Microscope Make/Serial #: Nikon Labophot 238913
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
 PCM - NIOSH 7400A
 TEM - AHERA

28. Comments:

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL

CITY_21MC100_003422346