

ATC ASSOCIATES, INC.

Page 1 of 5TIME 10:12

INDOOR AIR QUALITY FIELD REPORT

LOCATION 131M, 100 Hester St. Mbk.DATE 8-22-02PROJECT NO. 19125-0246
4461T

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
4th Railway by Elev.	0	82.8	59.2	541	1	34	0.1
R424	0	85.5	57.7	438	1	41	0.2
R421 B	0	86.1	53.9	427	2	34	0.2
R429	0	86.4	57.4	419	2	35	0.2
R435	1	87.4	51.3	579	2	33	0.2
R444	0	88.7	50.2	444	2	34	0.3
R403	0	89.0	43.5	569	1	39	0.0
R404 C	0	88.7	43.8	567	1	38	0.1
R406	0	88.5	43.8	510	1	40	0.1
Staircase 5 4th fl.	0	88.6	50.2	523	2	36	0.2
Guideline levels ASHRAE/AIHA		68-75°F/winter 73-79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: W. Uedineh Date: 8-22-02

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003422568

ATC ASSOCIATES, INC.

Page 2 of 5TIME 11:03

INDOOR AIR QUALITY FIELD REPORT

LOCATION 15131th, 100 Hester St, Mount. DATE 8-22-02 PROJECT NO. 19125-0346
44677-

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
3rd. H. Railway by Lockers	0	88.6	50.2	744	2	31	0.2
R342	0	89.3	47.3	468	2	32	0.1
R332	0	89.1	46.0	430	2	33	0.1
R321A	0	87.2	46.1	824	2	30	0.1
R312	0	86.3	43.0	518	2	29	0.2
R304A	0	86.8	41.2	583	1	32	0.0
R308	0	86.5	42.0	554	1	36	0.0
R327	0	87.1	45.7	546	1	32	0.1
R336	0	88.0	45.0	481	1	30	0.0
Staircase 43rd. fl.	0	83.3	43.3	645	1	45	0.1
Guideline levels ASHRAE/AIHA		68-75°F/winter 73-79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: W. Heedrich Date: 8-22-02CONFIDENTIAL,
SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CITY_21MC100_003422569

ATC ASSOCIATES, INC.

Page 3 of 5TIME 12:57

INDOOR AIR QUALITY FIELD REPORT

LOCATION PS 131M, 100 Hester St, N.Y.C. DATE 8-22-02 PROJECT NO. 19125
41617 - 0346

Location	Occup.	Temperature (F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
2nd fl. Hallway by Roof Wind	0	87.6	46.6	1134	1	52	0.0
R226	0	87.7	44.9	715	1	46	0.0
R227	2	87.8	45.2	656	1	33	0.0
R248D	0	87.9	45.0	547	1	37	0.0
R242	0	88.1	44.8	554	1	41	0.0
Library	0	84.0	42.4	488	1	34	0.0
R223	0	82.8	43.8	461	1	38	0.0
R221B	0	82.7	44.0	469	1	26	0.0
R214	0	83.7	45.4	585	1	71	0.0
Staircase 2nd fl.	7	84.3	47.5	727	1	78	0.0
Guideline levels ASHRAE/AIHA		68-75°F/winter 73-79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: W. Medved Date: 8-22-02CONFIDENTIAL,
SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CITY_21MC100_003422570

TIME 13:49

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 4 of 5

LOCATION PS 131 N, 100 Hester St, Manhattan DATE 8-22-02 PROJECT NO. 19125
41677-0346

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
Lobby	3	83.5	48.4	501	1	27	0.0
General off.	4	82.5	47.7	573	1	31	0.0
Auditorium	0	78.3	48.4	528	1	14	0.0
Hallway by Aud.	1	76.9	49.0	570	1	16	0.0
R115	0	78.4	48.9	659	1	16	0.0
R106	19	78.1	49.0	715	1	18	0.0
R103	0	78.2	49.4	678	1	16	0.0
R101	2	78.4	49.9	716	1	18	0.0
R102	0	78.0	48.8	655	1	18	0.0
Common area 1st fl.	3	79.1	55.2	662	1	30	0.0
Guideline levels ASHRAE/AIHA		68-75°F/winter 73-79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) ☐ Does ☐ Does not meet established indoor air quality guidelines.Signature: Dr. Weidner Date: 8-22-02

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003422571

ATC ASSOCIATES, INC.

Page 5 of 5TIME 14:46

INDOOR AIR QUALITY FIELD REPORT

LOCATION PS 131M, 100 Hester St, Manh. DATE 8-22-02 PROJECT NO. 19125
44617 0346

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
Cafeteria	96	83.4	58.7	622	1	43	0.0
Kitchen	6	85.2	56.0	560	2	29	0.0
Staircase ^{1st fl.} 3	0	83.6	52.8	484	2	32	0.0
Gym (BSM)	0	85.2	55.4	700	1	30	0.1
BSM office	9	83.9	41.6	1193	2	27	0.0
BSM Hallway	0	84.6	49.2	885	2	26	0.1
Staircase 41 BSM	0	84.5	53.8	766	2	26	0.2
Ext. Main Entr.		81.8	50.5	410	2	38	0.0
Ext. Sockets of Main Entr.		82.6	50.4	406	2	39	0.1
Ext. North of Main Entr.		83.5	50.2	411	2	38	0.1
Guideline levels ASHRAE/AIHA		68-75°F/winter 73-79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: W. Uedineh Date: 8-22-02

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003422572