



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1 Client <u>NYC-BOE</u>	2 Project Name <u>PS 1M</u>	3 Project # <u>14584-0869</u>	4 Project Monitor <u>H. Antonyan</u>	4c Rotameter Number <u>HP-128</u>
5 Date <u>8/24/02</u>	6 Abatement Location <u>Throughout the bldg. & Roof</u>	7 ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____	8 ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>MMI</u> Lot # <u>02106916</u>	9 Type a ☐ Background b ☐ Pre-Abate c ☐ Abatement d ☐ Post-Abate e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other

DAILY AIR SAMPLE RECORD

10 Sample ID Number	11 Pump Number	12 Sample Location	13 Time (24 hrs clock)	14 Flow Rate (L/min)	15 Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc F/CC
		12a IWA 12b OWA 12c Sample Coordinates	13a Start 13b End 13c Total	14a Start 14b End 14b Avg			
<u>19</u>		Field Blank					
<u>20</u>		Field Blank					
<u>01</u>		<u>Outside by Main entrance</u>	<u>07:00 11:00 240</u>	<u>8.0 8.0 8.0</u>	<u>1920</u>		
<u>02</u>		<u>First floor lobby area</u>	<u>07:03 11:04 241</u>	<u>8.0 8.0 8.0</u>	<u>1928</u>		
<u>03</u>		<u>Cafeteria</u>	<u>07:06 11:06 240</u>	<u>8.0 8.0 8.0</u>	<u>1920</u>		
<u>04</u>		<u>Play area</u>	<u>07:10 11:10 240</u>	<u>8.0 8.0 8.0</u>	<u>1920</u>		
<u>05</u>		<u>Auditorium</u>	<u>07:13 11:14 241</u>	<u>8.0 8.0 8.0</u>	<u>1928</u>		
<u>06</u>		<u>2nd floor Hallway</u>	<u>07:17 11:17 240</u>	<u>8.0 8.0 8.0</u>	<u>1920</u>		

CHAIN OF CUSTODY

18 Relinquished By <u>H. Antonyan</u>	19 Received By <u>RRly</u>	20 Date <u>8/24/02</u>	21 Time <u>22:00</u>
27 Result To _____ Beeper/Phone #'s _____			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22 Lab Name <u>ATC TEM</u>	23 Date <u>8/25/02</u>	24 Time <u>14:20</u>	25 Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a Analyzed By <u>RRly</u>	b QC By	c Lab Batch #	Analysis Methodology PCM - NIOSH 7400A TEM - AHERA
28 Comments			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003431216



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1 Client <u>NYC - BOE</u>		2 Project Name <u>PS 1 M</u>		3 Project # <u>14584-0869</u>		4 Project Monitor <u>H Antonyan</u>		4c Rotameter Number <u>HP-128</u>	
		2a Project Address <u>8 Henry Street NYM</u>		3a Task #					
5 Date <u>8/24/02</u>		6 Abatement Location <u>Throughout the bldg and Roof</u>		7 ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8 ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>MMI</u> Lot # <u>02106916</u>		9 Type a ☐ Background d ☐ Post-Abate b ☐ Pre-Abate e ☐ OSHA	
								c ☒ Abatement f ☐ Environmental g ☒ Ambient h ☐ Other	

DAILY AIR SAMPLE RECORD

10 Sample ID Number	11 Pump Number	12 Sample Location		12c Sample Coordinates	13 Time (24 hrs clock)			14 Flow Rate (L/min)			15 Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc F/CC
		12a IWA	12b OWA		13a Start	13b End	13c Total	14a Start	14b End	14b Avg			
<u>21</u>				Field Blank <u>Sealed Blank</u>									
				Field Blank									
<u>07</u>		<u>1</u>		<u>Rm. 213</u>	<u>07:20</u>	<u>11:20</u>	<u>240</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1920</u>		
<u>08</u>		<u>1</u>		<u>Rm 202</u>	<u>07:24</u>	<u>11:24</u>	<u>240</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1920</u>		
<u>09</u>		<u>1</u>		<u>3rd floor Hallway</u>	<u>07:28</u>	<u>11:29</u>	<u>241</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1928</u>		
<u>10</u>		<u>1</u>		<u>Rm. 313</u>	<u>07:31</u>	<u>11:33</u>	<u>242</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1936</u>		
<u>11</u>		<u>1</u>		<u>Rm. 301</u>	<u>11:32</u>	<u>15:32</u>	<u>240</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1920</u>		
<u>12</u>		<u>1</u>		<u>4th floor Hallway</u>	<u>11:35</u>	<u>15:35</u>	<u>240</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1920</u>		

CHAIN OF CUSTODY

18 Relinquished By <u>I H. Antonyan</u>		19 Received By <u>RLK</u>		20 Date <u>8/24/02</u>	21 Time <u>22:00</u>
II					
III					

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22 Lab Name <u>ATC-TEM</u>		23 Date <u>8/24/02</u>	24 Time <u>14:20</u>
a Analyzed By <u>RLK</u>			
b QC By			
c Lab Batch #			
25 Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079			
28 Comments 			
Analysis Methodology PCM - NIOSH 7400A TEM - AHERA			

26 Project Manager 		27 Result To 	
		Beeper/Phone #'s 	

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1.01)

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003431217



8759

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1 Client <u>NYC-BOE</u>	2 Project Name <u>PS 1 M</u>	3 Project # <u>14384-0869</u>	4 Project Monitor <u>H. Antonysen</u>	4c Rotameter Number <u>HP-128</u>
5 Date <u>8/24/02</u>	6 Abatement Location <u>8 Henry Street, NY</u>	7 ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____	8 ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>MMI</u> Lot # <u>02106916</u>	9 Type a ☐ Background b ☐ Pre-Abate c ☐ Abatement d ☐ Post-Abate e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other

DAILY AIR SAMPLE RECORD

10	11	12 Sample Location			13 Time (24 hrs clock)			14 Flow Rate (L/min)			15	16	17
Sample ID Number	Pump Number	12a IWA	12b OWA	12c Sample Coordinates	13a Start	13b End	13c Total	14a Start	14b End	14b Avg	Total Air Vol (liters)	# Fibers/Fields Minus Blank	Fiber Conc F/CC
				Field Blank									
				Field Blank									
13		1		Rm 413	11:40	15:40	240	8.0	8.0	8.0	1920		
14		1		Rm. 402	11:43	15:43	240	8.0	8.0	8.0	1920		
15		1		5th floor Hallway	11:50	15:50	240	8.0	8.0	8.0	1920		
16		1		Rm. 503	11:53	15:53	240	8.0	8.0	8.0	1920		
17		1		Rm. 501	11:56	15:56	240	8.0	8.0	8.0	1920		
18			1	Roof	12:02	15:59	237	8.0	8.0	8.0	1896		

CHAIN OF CUSTODY

18 Relinquished By <u>H. Antonysen</u>	19 Received By <u>RRJ</u>	20 Date <u>8/24/02</u>	21 Time
I			
II			
III			
26 ATC Project Manager	27 Result To _____ Beeper/Phone #'s _____		

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22 Lab Name <u>ATC TEM</u>	23 Date <u>8/25/02</u>	24 Time <u>14:20</u>	25 Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a Analyzed By <u>RRJ</u>			
b QC By			
c Lab Batch #			
28 Comments			Analysis Methodology PCM - NIOSH 7400A TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY 1 (1/01)

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003431218