



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page _____ of _____

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

002

PROJECT INFORMATION

1. Client: 11 Park PL		2. Project Name: 11 Park Place NY NY		3. Project #: Emergency		4. Project Monitor: Y. M. Austin/Buskirk		4c. Rotameter Number: SD-132	
5. Date: 9/23/01		6. Abatement Location: Lobby		7. ☒ PCM (0.6 micron MCE) Cassette/Filter Manufacturer: MMB Lot #: 01046915		8. ☐ TEM (0.45 micron MCE) Cassette/Filter/Manufacturer: LF Lot #: _____		9. Type: a. ☐ Background b. ☐ Pre-Abate	
						c. ☒ Abatement d. ☐ Post-Abate e. ☐ OSHA		f. ☐ Environmental g. ☐ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample ID Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. DWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
L-01				Field Blank								0/100	
				Field Blank									
L-02		V		Lobby North Entrance	1600	1800	120	15	15	15	1800	7/100	<0.003
L-03		V		Lobby South Entrance	1801	1801	120	15	15	15	1800	5/100	<0.003
L-04		V		Lobby Middle of Elevator	1803	1803	120	15	15	15	1800	4/100	<0.003

CHAIN OF CUSTODY

18. Reimbursed By: [Signature]		19. Received By: M. A. C. L.		20. Date: 9/23/01		21. Time: 2030	
22. ATC Project Manager: David Chang		27. Result To: David Chang Beeper/Phone #s: _____					

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: a. Analyzed By: M. A. C. L.		23. Date: 9/23/01		24. Time: 2350		25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☒ Nikon Labophot 239079	
c. Lab Batch #: 97082		28. Comments: PCM - NIOSH 7400A TEM - AHERA					

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_014583311