

SciLab Job #: 202013091

Client Name: TRC Environmental Corporation

Table I

Summary of Transmission Electron Microscopy (TEM) Results for Asbestos (ASTM 5755 Dust)

35052-0000-00002; New York City Law Department; 100 Church Street

SciLab Sample #	Client Sample #	Surface Area Sampled (sq. cm)	Dilution Factor	Asbestos Structures Detected	* Analytical Sensitivity on Grid (Str / sq mm)	Structure Density on Grid (Str / sq mm)	* Analytical Sensitivity on Surface (Str / sq. cm)	Structure Density on Surface (Str/ sq. cm)	Type of Asbestos
01	JD012302MV0201	100.0	0.100	6	25	150.0	535	3,210	chrysotile
	2nd Floor Dell Computer - Inside OPTIPLEX GXI Ser. #US4ZK								
02	JD012302MV0202	100.0	0.010	10	10	100.0	2,140	21,400	chrysotile
	2nd Floor Dell Computer - Inside OPTIPLEX GXI Ser. #US851								
03	JD012302MV0203	100.0	0.010	101	11.1	1,122.2	2,377	240,155	chrysotile
	2nd Floor HP Laser Jet Printer Ser. #USDD024099								
04	JD012302MV0204	100.0	0.010	30	10	300.0	2,140	64,200	chrysotile
	2nd Floor HP Laser Jet Printer Ser. #USBK149650								
05	JD012302MV0301	100.0	0.020	12	10	120.0	1,070	12,840	chrysotile
	3rd Floor Dell Computer Serial #U2NFR								
06	JD012302MV0302	100.0	0.020	2	10	20.0	1,070	2,140	chrysotile
	3rd Floor CSS Laboratories Computer Serial #1026								
07	JD012302MV0303	100.0	0.020	3	10	30.0	1,070	3,210	chrysotile
	3rd Floor HP Laser Jet Printer Behind Access Door Ser. #USDD0223457								
08	JD012302MV0304	100.0	0.020	3	10	30.0	1,070	3,210	chrysotile
	3rd Floor HP Laser Jet Printer Behind Access Door Ser. #USD6044387								
09	JD012302MV0601	100.0	0.020	0	10	<10	1,070	<1,070	NSD
	6th Floor Dell Computer Ser. #14A8C								
10	JD012302MV0602	100.0	0.020	8	10	80.0	1,070	8,560	chrysotile
	6th Floor Dell Computer Ser. #2FT3E								
11	JD012302MV0603	100.0	0.020	2	10	20.0	1,070	2,140	chrysotile
	6th Floor Dell Computer Ser. #2FTCA								
12	JD012302MV0604	100.0	0.020	3	10	30.0	1,070	3,210	chrysotile
	6th Floor HP Laser Jet Printer Ser. # USDG0044380								
13**	JD012302MVB1				I				
	Micro-Vac Blank Sample #1								

* structure density represented by the detection of 1 structure

** not analyzed

NSD: No Asbestos Structures Detected

Reviewed By: _____; Analyzed By: Gleason Massey Date: 1/28/02

JAN-28-2002 05:19

SCIENTIFIC LABS

212 679 9392

P.02/04