

**SCIENTIFIC LABORATORIES, INC.**

117 EAST 30TH STREET

NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos Report

TRC Environmental Corporation
Attn: Nitin Dave
134 West 29th Street
Penthouse
New York, NY 10001

Date Received 07/19/2002 SciLab Job No. 202073210
Date Examined 07/21/2002 P.O. # 35052-0000-00009
ELAP Number 11480 Page 1 of 7
RE: 35052-0000-00009; New York City Law Department;
100 Church Street

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
BA071902ABC-01	202073210-01	Yes	6.3 % ¹
1	Location: Room 22 At Stair Inside At Middle Room		
	Description: Grey, Homogeneous, 9x9 Floor Tile		
	Asbestos Types: Chrysotile 6.3 %		
	Other Material: Non-fibrous 28.9 %		
BA071902ABC-02	202073210-02		NA/PS
1	Location: Room 22 15' Southern Of Wall #2		
	Description: 9x9 Floor Tile		
	Asbestos Types:		
	Other Material:		
BA071902ABC-03	202073210-03		NA/PS
1	Location: Room 22 10' Western Of Wall #3		
	Description: 9x9 Floor Tile		
	Asbestos Types:		
	Other Material:		
BA071902ABC-04	202073210-04	Yes	1.5 % ¹
2	Location: Room 22 At Stair Inside The Middle Room		
	Description: Black, Homogeneous, 9x9 Floor Tile Mastic		
	Asbestos Types: Chrysotile 1.5 %		
	Other Material: Non-fibrous 4.6 %		
BA071902ABC-05	202073210-05		NA/PS
2	Location: Room 22 15' Southern Of Wall #2		
	Description: 9x9 Floor Tile Mastic		
	Asbestos Types:		
	Other Material:		

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos ReportTRC Environmental Corporation
Attn: Nitin Dave
134 West 29th Street
Penthouse
New York, NY 10001Date Received 07/19/2002 SciLab Job No. 202073210
Date Examined 07/21/2002 P.O. # 35052-0000-00009
ELAP Number 11480 Page 2 of 7
RE: 35052-0000-00009; New York City Law Department;
100 Church Street

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
BA071902ABC-06	202073210-06		NA/PS

2 Location: Room 22 10' Western Of Wall #3

Description: 9x9 Floor Tile Mastic

Asbestos Types:

Other Material:

BA071902ABC-07	202073210-07	Yes	8.5 % ¹
----------------	--------------	-----	--------------------

3 Location: Room 20 East Side 10' Of Wall #2

Description: Grey, Homogeneous, 9x9 Floor Tile

Asbestos Types: Chrysotile 8.5 %

Other Material: Non-fibrous 29.8 %

BA071902ABC-08	202073210-08		NA/PS
----------------	--------------	--	-------

3 Location: Room 20 South Side 15' Of Wall #3

Description: 9x9 Floor Tile

Asbestos Types:

Other Material:

BA071902ABC-09	202073210-09		NA/PS
----------------	--------------	--	-------

3 Location: Room 20 West Side At Middle

Description: 9x9 Floor Tile

Asbestos Types:

Other Material:

BA071902ABC-10	202073210-10	Yes	3 % ¹
----------------	--------------	-----	------------------

4 Location: Room 20 East Side 10' Of Wall #2

Description: Black, Homogeneous, 9x9 Floor Tile Mastic

Asbestos Types: Chrysotile 3.0 %

Other Material: Non-fibrous 13.7 %

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos ReportTRC Environmental Corporation
Attn: Nitin Dave
134 West 29th Street
Penthouse
New York, NY 10001Date Received 07/19/2002 SciLab Job No. 202073210
Date Examined 07/21/2002 P.O. # 35052-0000-00009
ELAP Number 11480 Page 3 of 7
RE: 35052-0000-00009; New York City Law Department;
100 Church Street

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
BA071902ABC-11	202073210-11		NA/PS

4 Location: Room #20 South Side 15' Of Wall #3

Description: 9x9 Floor Tile Mastic
Asbestos Types:
Other Material:

BA071902ABC-12	202073210-12		NA/PS
----------------	--------------	--	-------

4 Location: Room 20 West Side At The Middle

Description: 9x9 Floor Tile Mastic
Asbestos Types:
Other Material:

BA071902ABC-13	202073210-13	Yes	6 % ¹
----------------	--------------	-----	------------------

5 Location: Room 20 North Side 5' From Entrance

Description: Tan, Homogeneous, 9x9 Floor Tile
Asbestos Types: Chrysotile 6.0 %
Other Material: Non-fibrous 25.5 %

BA071902ABC-14	202073210-14		NA/PS
----------------	--------------	--	-------

5 Location: Room 20 West Side Of Room

Description: 9x9 Floor Tile
Asbestos Types:
Other Material:

BA071902ABC-15	202073210-15		NA/PS
----------------	--------------	--	-------

5 Location: Room 20 South Middle Side

Description: 9x9 Floor Tile
Asbestos Types:
Other Material:

**SCIENTIFIC LABORATORIES, INC.**

117 EAST 30TH STREET

NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos Report

TRC Environmental Corporation
Attn: Nitin Dave
134 West 29th Street
Penthouse
New York, NY 10001

Date Received 07/19/2002 SciLab Job No. 202073210
Date Examined 07/21/2002 P.O. # 35052-0000-00009
ELAP Number 11480 Page 4 of 7
RE: 35052-0000-00009; New York City Law Department;
100 Church Street

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
BA071902ABC-16 6	202073210-16 Location: Room 20 North Side 5' From Entrance	Yes	4 % ¹
Description: Black, Homogeneous, 9x9 Floor Tile Mastic Asbestos Types: Chrysotile 4.0 % Other Material: Non-fibrous 21.3 %			
BA071902ABC-17 6	202073210-17 Location: Room 20 West Side Of Room		NA/PS
Description: 9x9 Floor Tile Mastic Asbestos Types: Other Material:			
BA071902ABC-18 6	202073210-18 Location: Room 20 South Middle Side		NA/PS
Description: 9x9 Floor Tile Mastic Asbestos Types: Other Material:			
BA071902ABC-19 7	202073210-19 Location: Room 20 Southern Middle	No	NAD
Description: Tan, Homogeneous, Insulation Asbestos Types: Other Material: Animal hair 2. %, Cellulose 3. %, Non-fibrous 95. %			
BA071902ABC-20 7	202073210-20 Location: Room 20 Southern Middle	No	NAD
Description: Tan, Homogeneous, Insulation Asbestos Types: Other Material: Animal hair 2. %, Cellulose 3. %, Non-fibrous 95. %			

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos ReportTRC Environmental Corporation
Attn: Nitin Dave
134 West 29th Street
Penthouse
New York, NY 10001Date Received 07/19/2002 SciLab Job No. 202073210
Date Examined 07/21/2002 P.O. # 35052-0000-00009
ELAP Number 11480 Page 5 of 7
RE: 35052-0000-00009; New York City Law Department;
100 Church Street

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
BA071902ABC-21 7	202073210-21 Location: Room 20 Middle Southern	No	NAD
Description: Tan, Homogeneous, Insulation Asbestos Types: Other Material: Animal hair 2. %, Cellulose 3. %, Non-fibrous 95. %			
BA071902ABC-22 8	202073210-22 Location: Room 20 Middle Southern	Yes	7 %
Description: Tan, Homogeneous, Pipe Fitting Insulation Asbestos Types: Chrysotile 7.0 % Other Material: Cellulose 5. %, Fibrous glass 15. %, Non-fibrous 73. %			
BA071902ABC-23 8	202073210-23 Location: Room 20 Middle Southern		NA/PS
Description: Pipe Fitting Insulation Asbestos Types: Other Material:			
BA071902ABC-24 8	202073210-24 Location: Room 20 Middle Southern		NA/PS
Description: Pipe Fitting Insulation Asbestos Types: Other Material:			
BA071902ABC-25 9	202073210-25 Location: Room 25 10' North Of Wall #1	Yes	6.6 % ¹
Description: Black, Homogeneous, 9x9 Floor Tile Asbestos Types: Chrysotile 6.6 % Other Material: Non-fibrous 23.2 %			

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos ReportTRC Environmental Corporation
Attn: Nitin Dave
134 West 29th Street
Penthouse
New York, NY 10001Date Received 07/19/2002 SciLab Job No. 202073210
Date Examined 07/21/2002 P.O. # 35052-0000-00009
ELAP Number 11480 Page 6 of 7
RE: 35052-0000-00009; New York City Law Department;
100 Church Street


Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
BA071902ABC-26 9 Location: Room 25 15' East Of Wall #2 Description: 9x9 Floor Tile Asbestos Types: Other Material:	202073210-26		NA/PS
BA071902ABC-27 9 Location: Room 25 At Center Description: 9x9 Floor Tile Asbestos Types: Other Material:	202073210-27		NA/PS
BA071902ABC-28 10 Location: Room 25 10' North Of Wall #1 Description: Black, Homogeneous, 9x9 Floor Tile Mastic Asbestos Types: Chrysotile 3.0 % Other Material: Non-fibrous 13.4 %	202073210-28	Yes	3 % ¹
BA071902ABC-29 10 Location: Room 25 15' East Of Wall #2 Description: 9x9 Floor Tile Mastic Asbestos Types: Other Material:	202073210-29		NA/PS
BA071902ABC-30 10 Location: Room 25 At Center Description: 9x9 Floor Tile Mastic Asbestos Types: Other Material:	202073210-30		NA/PS

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos ReportTRC Environmental Corporation
Attn: Nitin Dave
134 West 29th Street
Penthouse
New York, NY 10001Date Received 07/19/2002 SciLab Job No. 202073210
Date Examined 07/21/2002 P.O. # 35052-0000-00009
ELAP Number 11480 Page 7 of 7
RE: 35052-0000-00009; New York City Law Department;
100 Church Street**Reporting Notes:**

(1) PLM analysis of NOB inert material.

Analyzed by: John P. Koubiadis 

*NAD/NSD = no asbestos detected; NA = not analyzed; NA/PS = not analyzed / positive stop; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #200546-0) and ELAP PLM Analysis Protocol 198.1 for New York samples (NYSDOH ELAP Lab # 11480); Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). National Institute of Standards and Technology Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This PLM report relates ONLY to the items tested. AIHA# 102843; VT Cert# AL018055

Reviewed By: _____