NYC 9/11 Public Portal Document

ATC ASSOCIATES INC

PROJECT MONITOR LOG

Part 1

1. Client: DEP	2. Project Name: DEP clean-up	4. Project #: 05-22906-0002	5. Work Area(s): Around building
	3. Project Address: 125 Cedar St. NY	4a. Task #: 00002	
6. Contractor: Action Environmental Group	7. Contractor's Foreman: A Coste	8. ATC Representative: E. Lemanovich	9. Date: 3.19.2

Type of Project: _____ Full-Containment _____ Tent-Containment _____ Glovebagging Other _____

Size of Project: _____ Large (> 160 sq. ft., 260 lin. ft. of ACM) _____ Small (< 160 sq. ft., 260 lin. ft.)

Phase of Abatement: _____ Pre-abatement Sampling _____ Prep _____ Removal _____ Cleaning

_____ Encapsulation _____ Waste Load-out _____ Finals

FULL-CONTAINMENT ABATEMENT

Work Area Location (floor, room, section): _____

Preparation of Work Area: _____ Yes (Indicate prep work performed in 1 - 10) _____ N/A (If already completed)

1. Construction of Decon:	____ Yes ____ No	2. Ceiling Poly:	____ Yes ____ No
3. Critical Barriers (CBs):	____ Yes ____ No	4. Wall Poly:	____ Yes ____ No
5. Removal to establish CBs:	____ Yes ____ No	6. Floor Poly:	____ Yes ____ No
7. Negative air:	____ Yes ____ No	8. Pre-cleaning:	____ Yes ____ No
9. Prep work completed:	____ Yes ____ No	10. Temporary Power:	____ Yes ____ No
11. Other _____	____ Yes ____ No	12. Prep-Inspection Passes:	____ Yes ____ No (Explain why)

Removal: _____ Yes (Complete 1 - 5) _____ N/A

1. Type of ACM: _____ Pipe Insulation _____ Duct Insulation _____ Fireproofing _____ Ceiling Tile
_____ Boiler Insulation _____ Transite Boards _____ Floor Tile _____ Other: _____

2. Negative air pressure ≥ 0.02 in. of water:	____ Yes ____ No	3. Amended water used during removal:	____ Yes ____ No
4. Critical barriers intact for shift's duration:	____ Yes ____ No	5. Proper Decon procedures followed:	____ Yes ____ No

Cleaning: _____ Yes (Complete 1 - 6) _____ N/A

1. _____ 1st Stage _____ 2nd Stage _____ 3rd Stage
2. 12/12-hour waiting period after 1st cleaning: _____ Yes _____ No
3. Removal of 1st poly layer after 1st cleaning: _____ Yes _____ No
4. 4/12-hour waiting period after 2nd cleaning: _____ Yes _____ No
5. Removal of 2nd poly layer after 2nd cleaning: _____ Yes _____ No
6. 1/12-hour waiting period after 3rd cleaning: _____ Yes _____ No

TENT-CONTAINMENT ABATEMENT

Work Area Location (floor, room, section): _____

Preparation of Work Area: _____ Yes (Indicate prep work performed in 1 - 6) _____ N/A (If already completed)

1. Construction of Tent:	____ Yes ____ No	2. Pre-cleaning:	____ Yes ____ No
3. Construction of Decon:	____ Yes ____ No	4. Negative Air:	____ Yes ____ No ____ N/A
5. Prep work completed:	____ Yes ____ No	6. Pref-inspection passes:	____ Yes ____ No

Removal:

1. Type of ACM: _____ Pipe Insulation _____ Duct Insulation _____ Fireproofing _____ Ceiling Tile
_____ Boiler Insulation _____ Transite Boards _____ Floor Tile _____ Other: _____
2. Method or Removal: _____ Gross removal within tent _____ Glovebag removal within tent (check 3 through 8)

(If Glovebag Removal Check 3 through 8)

3. Glovebags smoke-tested:	____ Yes ____ No	4. Glovebags attached to smooth surface:	____ Yes ____ No
5. Amended water used:	____ Yes ____ No	6. Removal included cleaning and encapsulation:	____ Yes ____ No
7. Open/damaged ends of insul. sealed:	____ Yes ____ No	8. Glovebags vacuumed, double-bagged:	____ Yes ____ No

Continued on Back

Form NY-8 1/01

CONFIDENTIAL, CITY_21MC100_003446178

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

NYC-WTC_000177440

NYC 9/11 Public Portal Document

WASTE LOAD-OUT

1. ____ (#) of bags
2. Waste washed, double-bagged: ____ Yes ____ No
3. Name of Hauler:
4. Hauler's permit number

FINAL AIR CLEARANCE

1. Aggressive Sampling Techniques: ____ Yes ____ No
2. Area passed final clearance testing: ____ Yes ____ No

HOURLY SUMMARY OF SHIFT'S ABATEMENT:

Time	Activity
06.00	Arrived on site at 125 Cedar St
	Met with representative ATC P. Pavlidis
06.20	Started air monitoring. Flow rate is 10.0 L/m
06.41	
08.10	Checked up flow rate. Everything is OK
09.25	Changed cossettes. Flow rate is 4.0 L/m
09.46	
11.20	Checked up flow rate. Everything is OK
12.55	Checked up work progress
14.10	Air monitoring completed
14.31	
14.55	Filled out paperwork and collected samples
15.00	Left site for ATC lab
16.00	Arrived at lab. To deliver samples
___ - ___	
___ - ___	
___ - ___	
___ - ___	
___ - ___	

PROJECT HOURS: 06:00 to 16:00

AIR SAMPLES COLLECTED: 24 samples + 3 blanks

The undersigned hereby acknowledges that the information on both sides of this project management log is accurate and true to the best of their knowledge.

C Lemanski

(Sign here) ATC Associates Inc. Representative