

WASTE LOAD-OUT

1. ____ (#) of bags
 2. Waste washed, double-bagged: ____ Yes ____ No
 3. Name of Hauler: ____
 4. Hauler's permit number ____

FINAL AIR CLEARANCE

1. Aggressive Sampling Techniques: ____ Yes ____ No
 2. Area passed final clearance testing: ____ Yes ____ No


HOURLY SUMMARY OF SHIFT'S ABATEMENT:

Time	Activity
06:00	Arrived on site at 125 Cedar St.
06:30	Met with representative ATC P. Parbidis
06:54	Started air monitoring. Flow rate is 4.0 L/min.
08:20	Checked up flow rate. Everything is OK.
10:35	Pumps are running at 4.0 L/min.
12:05	Checked up work pumps
13:20	Contractor continues the same type of work
14:00	Air monitoring completed.
14:24	Filled out paperwork and collected samples
14:50	Left site
15:00	
16:00	Arrived at lab. To deliver samples

PROJECT HOURS: 06:00 To 16:00

AIR SAMPLES COLLECTED: 12 samples + 3 blanks

The undersigned hereby acknowledges that the information on both sides of this project management log is accurate and true to the best of their knowledge.



(Sign here)

ATC Associates Inc. Representative

CONFIDENTIAL,

CITY_21MC100_003446215

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008