

ATC Associates

104 East 25 Street, New York, NY 10010

Phone: (212) 353-8280

Fax: (212) 353-8306



Attn: Benjamin Sallemi

ATC Associates Inc.

104 East 25th Street

New York

NY 10010

Fax: (212) 353-3599

Phone: (212) 353-8280

Project: DEP Clean-up Project #: 22906-0002

125 Cedar Street, New York, NY

Received: 9/28/02

8:00:00 AM

ATC Group #: 8906

Analysis Date: 9/28/02

**Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed
by EPA 40 CFR Part 763 Final Rule (AHERA)**

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structures 0.5µ-5 µ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm ²)	(S/cc)	Notes
03 8906 -1	1800.00	0.0450	0	None Detected	0	0	0.0048	<22.24	<0.0048
04 8906 -2	1800.00	0.0450	0	None Detected	0	0	0.0048	<22.24	<0.0048
05 8906 -3	1800.00	0.0450	0	None Detected	0	0	0.0048	<22.24	<0.0048
06 8906 -4	1804.00	0.0450	0	None Detected	0	0	0.0047	<22.24	<0.0047
07 8906 -5	1800.00	0.0450	0	None Detected	0	0	0.0048	<22.24	<0.0048

MARK PEYSAKHOV

Analyzed by:

MICHAEL A. GORYCKI, Ph.D.

Approved by:

Disclaimer: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by ATC Associates Inc. This report may not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. This report relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysis accuracy and precision) is available upon request.

Accredited for NVLAP PLM/TEM #101187-0, NY State ELAP #10879

Page 1 of 1

CONFIDENTIAL,

CITY_21MC100_003446635

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008



AIR MONITORING DATA AND

Page 1

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

CHAIN OF CUSTODY FORM

PROJECT INFORMATION

1. Client: DEP	2. Project Name: DEP Clean up	3. Project #: 8002	4. Project Monitor: C Johnson	4c. Rotameter Number: CS001
2a. Project Address: 125 CEDAR ST	3a. Task #: 8002	4a. Air Sampler: u		
5. Date: 9-27-02	6. Abatement Location: ENTIRE	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture MME Lot # 916	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☒ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location	13. Time (24 hrs clock)	14. Flow Rate (L/min.)	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA 12b. OWA 12c. Sample Coordinates	13a. Start 13b. End 13c. Total	14a. Start 14b. End 14c. Avg			
01		Field Blank					
02		Field Blank					
03		1100 2 FL CLEAN RM	1430 2200 450	04 4 4	1800		
04		1 FL WASTE CLEAN RM	1431 2201 450	04 4 4	1800		
05		STORE WASTE CLEAN RM	1432 2203 450	04 4 4	1800		
06		FRONT of Building EAST SIDE	1434 2205 451	04 4 4	1804		
07		FRONT of Building WEST SIDE	1435 2205 450	04 4 4	1800		
08		CLOSE BLANK					

CHAIN OF CUSTODY

18. Relinquished By: I CSJ	19. Received By: W. H. C.	20. Date: 9/28/02	21. Time: 12:00
II			
III			

26. ATC Project Manager: B. Sullivan	27. Result To: B. Sullivan Beeper/Phone #s _____
--	---

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: DEP	23. Date: 9/28/02	24. Time: 12:00	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: W. H. C.	b. QC By:	c. Lab Batch #:	Analysis Methodology PCM - NIOSH 7400A TEM - AHERA
28. Comments:			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_003446636