

JLC ENVIRONMENTAL CONSULTANTS, INC.
 200 Park Avenue South, Suite 1001, New York, New York 10003
 Phone: (212) 420-8119 Fax: (212) 420-6092

New York City D.E.P.
 5. Junction Blvd.
 Flushing, NY 11373

ELAP Lab Code: 11029
 NIOSH and AIHA Lab Code: 100273
 NVLAP Lab Code: 101953

Project No.: 03-2744
 Analyte: LEAD/ WIPE
 Date Collected: 3/5/2003
 Date Received: 3/6/2003
 Date Analyzed: 3/6/2003
 Batch #: 0303L323

Site:

114 Liberty Street, New York, NY

SUMMARY OF ANALYTICAL RESULTS - DUST WIPE


Sample # Lab # Client's Sample	Description/ Location	Area in Inches (L x W)	Lead Concentration (ug/ft2)
1 2577 01	7th Floor/ Lead Dust/ Floor/ Hallway	12x12	35.5
2 2578 02	7th Floor/ Lead Dust/ Wall/ Living Room/ Lower Right	12x12	<9
3 2579 03	7th Floor/ Lead Dust/ Counter Top/ Kitchen	12x12	<9

Sample Analysis By:

Atomic Absorption Spectrometry (AAS) using an air-acetylene flame with background correction.

Method of Sample Preparation and Analysis

All samples were prepared and analyzed in accordance with the HUD "Guidelines for the Evaluation and Control of Lead Based Paint Hazardous in Housing" Appendix 14.2 and the Environmental Protection Agency Method EPA SW846-3050/7420.



Gulam Machhiwala
 Laboratory Director

Collected By: Shawn Rajkumar
 Analyzed By: Madell Collins

Minimum Detection Limit = <20 ug/ft2

HUD "Guidelines for the Evaluation and Control of Lead-Based Paint Hazardous in Housing" 06/95; define the clearance standards, based on wipe sampling are: *40 ug/ft2 for floors; *250 ug/ft2 for interior window sills; *400 ug/ft2 for window and exterior concrete or other rough