

**ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT**

Page 4 of 4

Time: 1:07 pm LOCATION: PS 150 DATE: 6/5/02 PROJECT NO: 19125-0289

Location	Occupants	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
Resource room	1	78.1	51.7	732	2	21	0
Nurse room	0	77.6	53.7	680	2	16	0
Kitchen	1	78.1	50.6	691	2	16	0
music room	0	78.3	50.3	706	2	19	0
NEXT TO SLOP SINK	0	76.9	44.3	684	2	18	0
404	25	77.7	47.4	1361	2	10	0
403 HALLWAY	0	77.0	44.6	713	2	16	0
Out Doors 403 classroom	0	76.9	45.1	681	2	16	0
Out Doors NEXT TO Boys Rm	0	77.3	46.1	777	2	12	0
Out Doors NEXT TO GIRLS Rm	0	77.4	46.7	771	2	17	0
Guideline levels ASHRAE/AIHA		68 - 75°F/winter 73-79 °F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: [Signature] Date: 6/5/02

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_005759888

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 2 of 4

Time: 1:20 PM LOCATION: PS 15C DATE: 6/5/02 PROJECT NO: 19125-0289

Location	Occupants	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
MAIN REAR	10	75.6	50.2	604	1	16	0
MAIN REAR	1	75.7	50.3	612	1	17	0
NEXT TO WEST STAIRS HALL	3	75.1	50.1	704	1	20	0
MAIN LOBBY	0	75.4	50.3	681	1	11	0
EVS ROOM	1	75.9	47.1	703	1	16	0
MAIN OFFICE	2	75.3	49.9	661	1	15	0
EVIDENCE ROOM	1	75.8	52.1	633	1	15	0
NEXT TO BOYS FIRE HALL	0	75.3	50.1	702	1	10	0
NEXT TO GIRLS FIRE HALL	0	75.1	49.9	599	1	11	0
NEXT TO EAST STAIRS HALL	0	75.1	49.6	586	1	13	0
Guideline levels ASHRAE/AIHA		68 - 75°F/winter 73-79 °F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: [Signature]

Date: 6/5/02

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_005759889

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 3 of 4

Time: 1:40 pm LOCATION: PS 150 DATE: 6/5/02 PROJECT NO: 19125-0289

Location	Occupants	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
Hallway NEXT TO STAFF Rm	0	78.6	45.1	599	1	17	0
402	0	76.7	45.2	1141	1	16	0
401	30	77.0	42.8	1261	1	10	0
Hall BY WEST STAIRS	6	76.7	44.7	937	1	11	0
501	0	74.0	42.0	953	1	16	0
502	0	75.9	41.4	828	1	16	0
503	25	78.8	43.9	1261	1	18	0
504	25	76.9	41.7	1271	1	12	0
504 HALLWAY	0	80.3	49.6	901	1	16	0
Hall BY EAST STAIRS	0	80.4	50.1	944	1	15	0
Guideline levels ASHRAE/AIHA		68 - 75°F/winter 73-79 °F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: _____

Date: 6/5/02

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_005759890

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 4 of 4Time: 2:10 pm LOCATION: P-150DATE: 6/5/02 PROJECT NO: 19125-0289

Location	Occupants	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
<u>OUTSIDE</u>							
<u>SOUTH SIDE</u>	<u>3</u>	<u>84.1</u>	<u>62.3</u>	<u>564</u>	<u>1</u>	<u>18</u>	<u>0</u>
<u>SOUT. EAST CORNER</u>	<u>6</u>	<u>84.1</u>	<u>62.4</u>	<u>512</u>	<u>1</u>	<u>16</u>	<u>0</u>
<u>EAST SIDE</u>	<u>1</u>	<u>84.3</u>	<u>62.3</u>	<u>516</u>	<u>1</u>	<u>16</u>	<u>0</u>
<u>NORTHEAST CORNER</u>	<u>0</u>	<u>83.9</u>	<u>62.3</u>	<u>590</u>	<u>1</u>	<u>10</u>	<u>0</u>
<u>EAST TOP OF STAIRS</u>	<u>0</u>	<u>83.9</u>	<u>62.3</u>	<u>586</u>	<u>1</u>	<u>11</u>	<u>0</u>
<u>NORTHWEST CORNER</u>	<u>0</u>	<u>84.1</u>	<u>62.3</u>	<u>554</u>	<u>1</u>	<u>16</u>	<u>0</u>
<u>WEST SIDE</u>	<u>0</u>	<u>84.1</u>	<u>62.1</u>	<u>530</u>	<u>1</u>	<u>12</u>	<u>0</u>
<u>MAIN ENTRANCE</u>	<u>1</u>	<u>84.1</u>	<u>62.3</u>	<u>519</u>	<u>1</u>	<u>13</u>	<u>0</u>
<u>NEXT TO TOP OF STAIRS</u>	<u>0</u>	<u>84.2</u>	<u>62.3</u>	<u>529</u>	<u>1</u>	<u>18</u>	<u>0</u>
<u>NORTH SIDE</u>	<u>0</u>	<u>84.1</u>	<u>62.4</u>	<u>536</u>	<u>1</u>	<u>17</u>	<u>0</u>
Guideline levels ASHRAE/AIHA		68 - 75°F/winter 73-79 °F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: [Signature]Date: 6/5/02

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

CONFIDENTIAL,

CITY_21MC100_005759891