

60 CENTRE STREET



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

REPORT OF AIR MONITORING (PHASE CONTRAST MICROSCOPY ANALYSIS OF AIR FILTERS)

CLIENT: DCAS
PROJECT:

DATE: 09/18/01
ADDRESS: 60 Centre Street, Manhattan, NY

CLIENT SAMPLE ID#	LOCATION	R E S P	W O R K	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	SAMPLE VOLUME (liters)	FIBERS PER FIELD	FIBERS PER CC	REMARKS	LAB ID#
01	IWA - Conference Room 7th Floor			19:00	20:00	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-01
02	IWA - Room 700 7th Floor			19:01	20:01	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-02
03	IWA - Lobby South 7th Floor			19:02	20:02	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-03
04	IWA - Room 665 6th Floor			19:09	20:09	15	15	900	0.070	< 0.01	Air Quality (Immed. TAT)	A010919A-04
05	IWA - Room 652			19:11	20:11	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-05
06	IWA - Room 641			19:13	20:13	15	15	900	0.060	< 0.01	Air Quality (Immed. TAT)	A010919A-06
07	IWA - Room 629			19:15	20:15	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-07
08	IWA - Reception Area 6th Floor			19:18	20:18	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-08
09	IWA - Library 500			20:25	21:25	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-09
10	IWA - 561 Room			20:27	21:27	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-10
11	IWA - 543 Room			20:29	21:29	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-11
12	IWA - Room 532			20:31	21:31	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-12
13	IWA - Room 514			20:33	21:33	15	15	900	0.060	< 0.01	Air Quality (Immed. TAT)	A010919A-13
14	IWA - Jury Room 452			20:39	21:39	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-14
15	IWA - Room 412			20:45	21:45	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-15
16	IWA - Room 422			20:47	21:47	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-16
17	IWA - Hall by Elevators 4th Floor			20:49	21:49	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-17
18	IWA - Room 438			20:51	21:51	15	15	900	0.090	< 0.01	Air Quality (Immed. TAT)	A010919A-18
19	IWA - Room 300 Corridor			21:32	22:32	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-19
20	IWA - Hallway by Elevators 3rd Floor			21:35	22:35	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-20
21	IWA - Room 315			21:37	22:37	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-21
22	IWA - Room 325			21:40	22:40	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-22
23	IWA - Corridor 341-345			21:42	22:42	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-23

TYPE OF RESPIRATORS:
TYPE OF WORK:

1 = HALF FACE, 2 = PAPR, 3 = TYPE C, 4 = OTHER (SPECIFY):
1 = BLDG DECON, 2 = PLASTICIZING, 3 = GROSS REMOVAL, 4 = GLOVEBAG, 5 = CLEANING,
6 = ENCAPSULATION, 7 = BAGOUT, 8 = OTHER (SPECIFY):

SAMPLING TECHNICIAN: Z.B. Nowak / P. Sroka
ROTAMETER: KAM- 04

Analyst:

Deepak Bajracharya

DATE RECEIVED: 09/19/01
DATE OF ANALYSIS: 09/19/01
DATE OF REPORT: 09/19/01

Lab Manager:

David Chen

The samples listed above are analyzed by Phase Contrast Microscopy (PCM) as per NIOSH 7400 Method -Issue 3. The detection limit of this method is 7 fibers per square mm per filter area.
KAM CONSULTANTS shall not be liable for information arising from samples that are not in its QA and QC program.

The results relate only to the items calibrated or tested. The certificate of report shall not be reproduced without approval of the laboratory.

The report must not be used by the client to claim endorsement by NVLAP or any agency of the U.S. Government.

NYS-DOH ELAP # 11273

AIHA # 100269



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

REPORT OF AIR MONITORING (PHASE CONTRAST MICROSCOPY ANALYSIS OF AIR FILTERS)

CLIENT: DCAS
PROJECT:

DATE: 09/18/01
ADDRESS: 60 Centre Street, Manhattan, NY

CLIENT SAMPLE ID#	LOCATION	R E S P	W O R K	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	SAMPLE VOLUME (liters)	FIBERS PER FIELD	FIBERS PER CC	REMARKS	LAB ID#
24	IWA - Room 252			21:55	22:55	15	15	900	0.060	< 0.01	Air Quality (Immed. TAT)	A010919A-24
25	IWA - Corridor 248-252			22:00	23:00	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-25
26	IWA - Corridor 228-232			22:02	23:02	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-26
27	IWA - Corridor 208-212			22:04	23:04	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-27
28	IWA - Room 212			22:06	23:06	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-28
29	IWA - Ground Floor by Main Entrance			23:16	0:16	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-29
30	IWA - Main Hall Middle By Main Entrance			23:18	0:18	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-30
31	IWA - Ground Floor Voucher Area			23:19	0:19	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-31
32	IWA - Ground Floor 119			23:21	0:21	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-32
33	IWA - Ground Floor 139			23:23	0:23	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-33
34	IWA - Basement by East Entrance			23:33	0:33	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-34
35	IWA - Basement County Clerk Room 109B			23:35	0:35	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-35
36	IWA - Basement County Clerk Room 109B			23:36	0:36	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-36
37	IWA - Basement Hall By 117 B			23:38	0:38	15	15	900	0.065	< 0.01	Air Quality (Immed. TAT)	A010919A-37
38	IWA - Basement Hall By 103 B			23:40	0:40	15	15	900	<0.055	< 0.01	Air Quality (Immed. TAT)	A010919A-38
39	Field Blank								<0.055			A010919A-39
40	Field Blank								<0.055			A010919A-40
41	Field Blank								<0.055			A010919A-41
42	Field Blank								<0.055			A010919A-42

TYPE OF RESPIRATORS:
TYPE OF WORK:

1 = HALF FACE, 2 = PAPR, 3 = TYPE C, 4 = OTHER (SPECIFY):
1 = BLDG DECON, 2 = PLASTICIZING, 3 = GROSS REMOVAL, 4 = GLOVEBAG, 5 = CLEANING,
6 = ENCAPSULATION, 7 = BAGOUT, 8 = OTHER (SPECIFY):

SAMPLING TECHNICIAN: Z.B. Nowak / P. Sroka
ROTAMETER: KAM- 04

Analyst:

Deepak Bajracharya

DATE RECEIVED: 09/19/01
DATE OF ANALYSIS: 09/19/01
DATE OF REPORT: 09/19/01

Lab Manager:

David Chen

The samples listed above are analyzed by Phase Contrast Microscopy (PCM) as per NIOSH 7400 Method - Issue 3. The detection limit of this method is 7 fibers per square mm per filter area. KAM CONSULTANTS shall not be liable for information arising from samples that are not in its QA and QC program. The results relate only to the items calibrated or tested. The certificate of report shall not be reproduced without approval of the laboratory. The report must not be used by the client to claim endorsement by NVLAP or any agency of the U.S. Government.

NYS-DOH ELAP # 11273

AIHA # 100269



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: DCAS
PROJECT:

SAMPLING DATE: 09-18-01 TUE
ADDRESS: 60 CENTRE STR
M-TAUN, NY

FIELD DATA									LAB ANALYSIS				
SAMPLE ID#	TYPE	LOCATION	R E S P	W O R K	TIME IN PM	TIME OUT PM	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	FIBERS PER FIELD	FIBERS PER CC	LAB ID #	CASSETTE 25MM 37MM
1	LF	CONFERENCE ROOM 7TH FLR			7 ⁰⁰	8 ⁰⁰	15	15	900	1/100	<0.01	1	TEST METHOD:
2	LF	ROOM 700 7TH FLR			7 ⁰¹	8 ⁰¹	15	15	900	4/100	<0.01	2	PCM TEM
3	LF	LIBRARY SOUTH 7TH FLR			7 ⁰²	8 ⁰²	15	15	900	2/100	<0.01	3	TURN-AROUND TIME:
4	LF	ROOM 665 6TH FLR			7 ⁰⁹	8 ⁰⁹	15	15	900	7/100	<0.01	4	IMMEDIATE
5	LF	ROOM 652			7 ¹¹	8 ¹¹	15	15	900	3/100	<0.01	5	12-HOUR
6	LF	ROOM 641			7 ¹³	8 ¹³	15	15	900	6/100	<0.01	6	24-HOUR
7	LF	ROOM 629			7 ¹⁵	8 ¹⁵	15	15	900	5/100	<0.01	7	24-HOUR
8	LF	RECEPTION AREA 6TH FLR			7 ¹⁸	8 ¹⁸	15	15	900	0.5/100	<0.01	8	OTHER:
9	LF	LIBRARY 500			8 ²⁵	9 ²⁵	15	15	900	4/100	<0.01	9	ANALYST:
10	LF	561 ROOM			8 ²⁷	9 ²⁷	15	15	900	2/100	<0.01	10	DB
11	LF	543 ROOM			8 ²⁸	9 ²⁸	15	15	900	2/100	<0.01	11	DATE OF ANALYSIS:
12	LF	ROOM 532			8 ³¹	9 ³¹	15	15	900	3/100	<0.01	12	9-19-01
13	LF	ROOM 514			8 ³³	9 ³³	15	15	900	6/100	<0.01	13	TIME OF ANALYSIS:
14	LF	LIBRARY ROOMS 452			8 ³⁹	9 ³⁸	15	15	900	5/100	<0.01	14	

2001 SEP 19 A

SAMPLE TYPE:

A=BACKGROUND, B=PREABATEMENT, C=DURING ABATEMENT, D=POST-ABATEMENT
E=OUTSIDE WORK AREA, F=INSIDE WORK AREA, G=MICROTRAP EXHAUST DISCHARGE
H=DECONTAMINATION FACILITY, I=CRITICAL BARRIER, J=OUTSIDE BLDG., K=FIELD BLANK
L=AIR QUALITY, M=COMPLIANCE MONITORING

TYPE OF RESPIRATORS:

TYPE OF WORK:

1 = HALF FACE, 2 = PAPR, 3 = TYPE C, 4 = OTHER (SPECIFY):

1 = BLDG DECON, 2 = PLASTICIZING, 3 = GROSS REMOVAL, 4 = GLOVEBAG, 5 = CLEANING,
6 = ENCAPSULATION, 7 = BAGOUT, 8 = OTHER (SPECIFY):

TECHNICIAN: ZB. NOWALL / P. SROKA

ROTAMETER: KALL - 10

PAGE 1 OF 3

CHAIN OF CUSTODY	RELINGUISHED BY:	COMMENTS:	RECEIVED AT LAB BY: <u>DB</u>
	METHOD OF SHIPMENT:		SAMPLE CONDITION UPON RECEIPT: <u>good</u>
	DATE/TIME:		DATE/TIME: <u>9-19-01</u>

CITY_21MC100_011837532

RECEIVED
KAM CONSULTANTS
2001 SEP 19 AM 8:36



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY

FOR ASBESTOS AIR MONITORING

CLIENT: DCAS
PROJECT:

SAMPLING DATE: 09-18-01 TUE
ADDRESS: 60 CENTRE STR
14-TH FL, NY

FIELD DATA										LAB ANALYSIS			
SAMPLE ID#	TYPE	LOCATION	R E S P	W O R K	TIME IN P.M.	TIME OUT P.M.	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	FIBERS PER FIELD	FIBERS PER CC	LAB ID #	CASSETTE 25MM 37MM
15	LF	Room 412			8:45	9:45	15	15	900	5/100	Co.01	15	TEST METHOD: PCM TEM
16	LF	Room 422			8:47	9:47	15	15	900	2/100	Co.01	16	TURN-AROUND TIME: IMMEDIATE
17	LF	HALL ELEVATORS 4TH FL			8:48	9:48	15	15	900	2/100	Co.01	17	12-HOUR
18	LF	Room 438			8:51	9:51	15	15	900	9/100	Co.01	18	24-HOUR
19	LF	Room 300 CORRIDOR			9:32	10:32	15	15	900	3/100	Co.01	19	24-HOUR
20	LF	HALLWAY BY ELEVATORS 3RD FL			9:35	10:35	15	15	900	1/100	Co.01	20	OTHER:
21	LF	Room 315			9:37	10:37	15	15	900	1/100	Co.01	21	ANALYST: DB
22	LF	Room 325			9:40	10:40	15	15	900	0.5/100	Co.01	22	DATE OF ANALYSIS: 9-19-01
23	LF	CORRIDOR 341-345			9:42	10:42	15	15	900	4/100	Co.01	23	TIME OF ANALYSIS:
24	LF	Room 252			9:55	10:55	15	15	900	6/100	Co.01	24	
25	LF	CORRIDOR 248-252			10:40	11:40	15	15	900	2/100	Co.01	25	
26	LF	CORRIDOR 228-232			10:42	11:42	15	15	900	3/100	Co.01	26	
27	LF	CORRIDOR 208-212			10:44	11:44	15	15	900	1.5/100	Co.01	27	
28	LF	Room 212			10:46	11:46	15	15	900	2/100	Co.01	28	

SAMPLE TYPE:

A=BACKGROUND, B=PREABATEMENT, C=DURING ABATEMENT, D=POST-ABATEMENT
E=OUTSIDE WORK AREA, F=INSIDE WORK AREA, G=MICROTRAP EXHAUST DISCHARGE
H=DECONTAMINATION FACILITY, I=CRITICAL BARRIER, J=OUTSIDE BLDG., K=FIELD BLANK
L=AIR QUALITY, M=COMPLIANCE MONITORING

TYPE OF RESPIRATORS:

TYPE OF WORK:

1 = HALF FACE, 2 = PAPR, 3 = TYPE C, 4 = OTHER (SPECIFY):

1 = BLDG DECON, 2 = PLASTICIZING, 3 = GROSS REMOVAL, 4 = GLOVEBAG, 5 = CLEANING,

6 = ENCAPSULATION, 7 = BAGOUT, 8 = OTHER (SPECIFY):

TECHNICIAN: ZB. NOHAK / P. SROKA

ROTAMETER: KALL - 14

PAGE 2 OF 3

CHAIN OF CUSTODY	RELINGUISHED BY: METHOD OF SHIPMENT: DATE/TIME:	COMMENTS:	RECEIVED AT LAB BY: DB SAMPLE CONDITION UPON RECEIPT: good DATE/TIME: 9-19-01
------------------	---	-----------	---

CITY_21MC100_011837533

RECEIVED
KAM CONSULTANTS
2001 SEP 19 AM 8:36



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: DCAS
PROJECT:

SAMPLING DATE: 09-18-01 TUE
ADDRESS: 60 EUTRE STR
MT-TX, NY

FIELD DATA										LAB ANALYSIS			
SAMPLE ID#	TYPE	LOCATION	R E S P	W O R K	TIME IN Am	TIME OUT Am	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	FIBERS PER FIELD	FIBERS PER CC	LAB ID #	CASSETTE 25MM 37MM
29	LF	GROUND FLR BY MAIN ENTRANCE			11:16	12:16	15	15	900	0.5 100	Co.01	A010919A 29	TEST METHOD: PCM TEM
30	LF	1st FLOOR MIDDLE BY MAIN ENTRANCE			11:18	12:18	15	15	900	4 100	Co.01	30	
31	LF	GROUND FLOOR VOUCHER AREA			11:18	12:18	15	15	900	3 100	Co.01	31	TURN-AROUND TIME: IMMEDIATE 12-HOUR 24-HOUR 24-HOUR OTHER:
32	LF	GROUND FLOOR 119			11:21	12:21	15	15	900	4 100	Co.01	32	
33	LF	GROUND FLOOR 139			11:23	12:23	15	15	900	2 100	Co.01	33	
34	LF	BASEMENT BY EAST ENTRANCE			11:33	12:33	15	15	900	2 100	Co.01	34	
35	LF	-1- COUNTY CLERK ROOM 109B			11:35	12:35	15	15	900	2.5 100	Co.01	35	
36	LF	-1- HALL BY 117B			11:36	12:36	15	15	900	4 100	Co.01	36	
37	LF	-1- HALL BY 141B			11:38	12:38	15	15	900	6.5 100	Co.01	37	ANALYST: DB
38	LF	-1- HALL BY 103B			11:40	12:40	15	15	900	2 100	Co.01	38	
39	K	FIELD BLANK								0 100	-	39	DATE OF ANALYSIS 9-19-01
40	K	-1-								0 100	-	40	
41	K	-1-								0 100	-	41	TIME OF ANALYSIS 19 AM
42	K	-1-								0 100	-	42	

SAMPLE TYPE:

A=BACKGROUND, B=PREABATEMENT, C=DURING ABATEMENT, D=POST-ABATEMENT
E=OUTSIDE WORK AREA, F=INSIDE WORK AREA, G=MICROTRAP EXHAUST DISCHARGE
H=DECONTAMINATION FACILITY, I=CRITICAL BARRIER, J=OUTSIDE BLDG, K=FIELD BLANK
L=AIR QUALITY, M=COMPLIANCE MONITORING

TYPE OF RESPIRATORS:

1= HALF FACE, 2= PAPR, 3= TYPE C, 4= OTHER (SPECIFY):

TYPE OF WORK:

1= BLDG DECON, 2= PLASTICIZING, 3= GROSS REMOVAL, 4= GLOVEBAG, 5= CLEANING,
6= ENCAPSULATION, 7= BAGOUT, 8= OTHER (SPECIFY):

TECHNICIAN: DB-NOLAN / P. SROKA

ROTAMETER: KALL 04

PAGE 3 OF 3

CHAIN OF CUSTODY	RELINQUISHED BY: METHOD OF SHIPMENT: DATE/TIME:	COMMENTS:	RECEIVED AT LAB BY: DB SAMPLE CONDITION UPON RECEIPT: good DATE/TIME: 9-19-01
------------------------	---	-----------	---

CITY_21MC100_011837534

RECEIVED
KAM CONSULTANTS